



*Review of
Florida's
Investor-Owned
Electric Utilities*

*2 0 1 8
Service Reliability Reports*



November 2019

State of Florida
Florida Public Service Commission
Division of Engineering

*Review of
Florida's
Investor-Owned
Electric Utilities
2 0 1 8
Service Reliability Reports*

November 2019

**State of Florida
Florida Public Service Commission
Division of Engineering**

Table of Contents

List of Tables and Figures.....	iii
Terms and Acronyms.....	vii
Reliability Metrics	ix
Executive Summary	1
Service Reliability of Duke Energy Florida, LLC	2
Service Reliability of Florida Power & Light Company	2
Service Reliability of Florida Public Utilities Company	3
Service Reliability of Gulf Power Company	4
Service Reliability of Tampa Electric Company	5
Review Outline	7
Section I: Storm Hardening Activities.....	9
Eight-Year Wooden Pole Inspection Program.....	9
Ten Initiatives for Storm Preparedness.....	11
Initiative 1 - Three-Year Vegetation Management Cycle for Distribution Circuits	11
Initiative 2 - Audit of Joint-Use Agreements	14
Initiative 3 - Six-Year Transmission Inspections	15
Initiative 4 - Hardening of Existing Transmission Structures	16
Initiative 5 - Transmission and Distribution Geographic Information System	17
Initiative 6 - Post-Storm Data Collection and Forensic Analysis	17
Initiative 7 - Collection of Detailed Outage Data Differentiating Between the Reliability Performance of Overhead and Underground Systems	17
Initiative 8 - Increased Utility Coordination with Local Governments.....	21
Initiative 9 - Collaborative Research on Effects of Hurricane Winds and Storm Surge	23
Initiative 10 - A Natural Disaster Preparedness and Recovery Program	25
Section II: Actual Distribution Service Reliability.....	27

Duke Energy Florida, LLC: Actual Data	28
Florida Power & Light Company: Actual Data	29
Florida Public Utilities Company: Actual Data	31
Gulf Power Company: Actual Data	32
Tampa Electric Company: Actual Data	33
Section III: Adjusted Distribution Service Reliability	35
Review of Individual Utilities	35
Duke Energy Florida, LLC: Adjusted Data	35
Florida Power & Light Company: Adjusted Data	45
Florida Public Utilities Company: Adjusted Data	55
Gulf Power Company: Adjusted Data	61
Tampa Electric Company: Adjusted Data	70
Section IV: Inter-Utility Reliability Comparisons	79
Inter-Utility Reliability Trend Comparisons: Adjusted Data	79
Inter-Utility Comparisons of Reliability Related Complaints	87
Section V: Appendices	91
Appendix A – Adjusted Service Reliability Data	91
Duke Energy Florida, LLC	91
Florida Power & Light Company	94
Florida Public Utilities Company	98
Tampa Electric Company	103
Appendix B. Summary of Municipal Electric Utility Reports Pursuant to Rule 25-6.0343, F.A.C. – Calendar Year 2018	107
Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to Rule 25- 6.0343, F.A.C. – Calendar Year 2018	139

List of Tables and Figures

Table 1-1 2018 Wooden Pole Inspection Summary	10
Table 1-2 Projected 2019 Wooden Pole Inspection Summary	10
Table 1-3 Vegetation Clearing from Feeder Circuits	12
Table 1-4 Vegetation Clearing from Lateral Circuits	13
Table 2-1 DEF's 2018 Customer Minutes of Interruptions and Customer Interruptions	28
Table 2-2 FPL's 2018 Customer Minutes of Interruptions and Customer Interruptions.....	30
Table 2-3 FPUC's 2018 Customer Minutes of Interruptions and Customer Interruptions.....	31
Table 2-4 Gulf's 2018 Customer Minutes of Interruption and Customer Interruptions.....	32
Table 2-5 TECO's 2018 Customer Minutes of Interruptions and Customer Interruptions	33
Figure 3-1 SAIDI across DEF's Four Regions (Adjusted)	36
Figure 3-2 SAIFI across DEF's Four Regions (Adjusted).....	37
Figure 3-3 CAIDI across DEF's Four Regions (Adjusted)	38
Figure 3-4 DEF's Average Duration of Outages (Adjusted)	39
Figure 3-5 MAIFIE across DEF's Four Regions (Adjusted)	40
Figure 3-6 CEMI5 across DEF's Four Regions (Adjusted).....	41
Figure 3-7 DEF's Three Percent Feeder Report (Adjusted)	42
Figure 3-8 DEF's Top Five Outage Causes (Adjusted).....	43
Figure 3-9 SAIDI across FPL's Sixteen Regions (Adjusted)	46
Figure 3-10 SAIFI across FPL's Sixteen regions (Adjusted)	47
Figure 3-11 CAIDI across FPL's Sixteen Regions (Adjusted).....	48
Figure 3-12 FPL's Average Duration of Outages (Adjusted).....	49
Figure 3-13 MAIFIE across FPL's Sixteen Regions (Adjusted).....	50
Figure 3-14 CEMI5 across FPL's Sixteen Regions (Adjusted).....	51
Figure 3-15 FPL's Three Percent Feeder report (Adjusted)	52
Figure 3-16 FPL's Top Five Outage Causes (Adjusted)	53
Figure 3-17 SAIDI across FPUC's Two Regions (Adjusted).....	55
Figure 3-18 SAIFI across FPUC's Two Regions (Adjusted)	56
Figure 3-19 CAIDI across FPUC's Two Regions (Adjusted)	57
Figure 3-20 FPUC's Average Duration of Outages (Adjusted).....	58
Figure 3-21 FPUC's Top Five Outage Causes (Adjusted)	59
Figure 3-22 SAIDI across Gulf's Three Regions (Adjusted)	61

Figure 3-23 SAIFI across Gulf's Three Regions (Adjusted)	62
Figure 3-24 CAIDI across Gulf's Three Regions (Adjusted)	63
Figure 3-25 Gulf's Average Duration of Outages (Adjusted)	64
Figure 3-26 MAIFIE across Gulf's Three Regions (Adjusted)	65
Figure 3-27 CEMI5 across Gulf's Three Regions (Adjusted)	66
Figure 3-28 Gulf's Three Percent Feeder Report (Adjusted)	67
Figure 3-29 Gulf's Top Five Outage Causes (Adjusted)	68
Figure 3-30 SAIDI across TECO's Seven Regions (Adjusted)	70
Figure 3-31 SAIFI across TECO's Seven Regions (Adjusted)	71
Figure 3-32 CAIDI across TECO's Seven Regions (Adjusted)	72
Figure 3-33 TECO's Average Duration of Outages (Adjusted)	73
Figure 3-34 MAIFIE across TECO's Seven Regions (Adjusted)	74
Figure 3-35 CEMI5 across TECO's Seven Regions (Adjusted)	75
Figure 3-36 TECO's Three Percent Feeder Report (Adjusted)	76
Figure 3-37 TECO's Top Five Outage Causes (Adjusted)	77
Figure 4-1 System Average Interruption Duration (Adjusted SAIDI)	80
Figure 4-2 Number of Service Interruptions (Adjusted SAIFI)	81
Figure 4-3 Average Service Restoration Time (Adjusted CAIDI)	82
Figure 4-4 Average Number of Feeder Momentary Events (Adjusted MAIFIE)	83
Figure 4-5 Percent of Customers with More Than Five Interruptions (Adjusted CEMI5)	84
Figure 4-6 Number of Outages per 10,000 Customers (Adjusted)	85
Figure 4-7 Average Duration of Outage Events (Adjusted L-Bar)	86
Figure 4-8 Total Number of Jurisdictional Complaints	87
Figure 4-9 Total Number of Reliability Related Complaints	88
Figure 4-10 Percent of Complaints that are Reliability Related	89
Figure 4-11 Service Reliability Related Complaints per 10,000 Customers	90
Table A-1 DEF's Number of Customers (Year End)	91
Table A-2 DEF's Adjusted Regional Indices SAIDI, SAIFI, and CAIDI	92
Table A-3 DEF's Adjusted Regional Indices MAIFIE and CEMI5	92
Table A-4 DEF's Primary Causes of Outages Events	93
Table A-5 FPL's Number of Customers (Year End)	94
Table A-6 FPL's Adjusted Regional Indices SAIDI, SAIFI, and CAIDI	95

Table A-7 FPL’s Adjusted Regional Indices MAIFle and CEMI5	96
Table A-8 FPL’s Primary Causes of Outage Events	97
Table A-9 FPUC’s Number of Customers (Year End).....	98
Table A-10 FPUC’s Adjusted Regional Indices SAIDI, SAIFI, and CAIDI	98
Table A-11 FPUC’s Primary Causes of Outage Events	99
Table A-12 Gulf’s Number of Customers (Year End).....	100
Table A-13 Gulf’s Adjusted Regional Indices SAIDI, SAIFI, and CAIDI	100
Table A-14 Gulf’s Adjusted Regional Indices MAIFle and CEMI5.....	101
Table A-15 Gulf’s Primary Causes of Outage Events	102
Table A-16 TECO’s Number of Customers (Year End)	103
Table A-17 TECO’s Adjusted Regional Indices SAIDI, SAIFI, and CAIDI.....	104
Table A-18 TECO’s Adjusted Regional Indices MAIFle and CEMI5.....	105
Table A-19 TECO’s Primary Causes of Outage Events.....	106

Terms and Acronyms

AMI	Advanced Metering Infrastructure
ANSI	American National Standards Institute
CAIDI	Customer Average Interruption Duration Index
CEMI5	Customers Experiencing More Than Five Interruptions
CI	Customer Interruption
CME	Customer Momentary Events
CMI	Customer Minutes of Interruption
DSM	Demand Side Management
DEF	Duke Energy Florida, LLC
EOC	Emergency Operation Center
F.A.C.	Florida Administrative Code
FEMA	Federal Emergency Management Agency
FPL	Florida Power & Light Company
FPUC	Florida Public Utilities Company
GIS	Geographic Information System
Gulf	Gulf Power Company
IEEE	Institute of Electrical and Electronics Engineers, Inc.
IOU	The Five Investor-Owned Electric Utilities: FPL, DEF, TECO, Gulf, and FPUC
L-Bar	Average of Customer Service Outage Events Lasting A Minute or Longer
MAIFle	Momentary Average Interruption Event Frequency Index
N	Number of Outages
NWS	National Weather Service
OMS	Outage Management System
RDUP	Rural Development Utility Program
SCADA	Supervisory Control and Data Acquisition
SAIDI	System Average Interruption Duration Index
SAIFI	System Average Interruption Frequency Index
TECO	Tampa Electric Company
VMP	Vegetation Management Program

Reliability Metrics

Average Duration of Outage Events (L-Bar) is the sum of each outage event duration for all outage events during a given time period, divided by the number of outage events over the same time within a specific area of service.

Customer Average Interruption Duration Index (CAIDI) is an indicator of average interruption duration, or the time to restore service to interrupted customers. CAIDI is calculated by dividing the total system customer minutes of interruption by the number of customer interruptions. ($CAIDI = CMI \div CI$, also $CAIDI = SAIDI \div SAIFI$).

Customers Experiencing More Than Five Interruptions (CEMI5) is the number of retail customers that have experienced more than five service interruptions. (CEMI5 in this review is a customer count shown as a percentage of total customers.)

Customer Interruptions (CI) is the number of customer service interruptions, which lasted one minute or longer.

Customer Minutes of Interruption (CMI) is the number of minutes that a customer's electric service was interrupted for one minute or longer.

Customer Momentary Events (CME) is the number of customer momentary service interruptions, which lasted less than one minute measured at the primary circuit breaker in the substation.

Momentary Average Interruption Event Frequency Index (MAIFIE) is an indicator of average frequency of momentary interruptions or the number of times there is a loss of service of less than one minute. MAIFIE is calculated by dividing the number of momentary interruption events recorded on primary circuits by the number of customers served. ($MAIFIE = CME \div C$)

Number of Outage Events (N) measures the primary causes of outage events and identifies feeders with the most outage events.

System Average Interruption Duration Index (SAIDI) is a composite indicator of outage frequency and duration and is calculated by dividing the customer minutes of interruptions by the number of customers served on a system. ($SAIDI = CMI \div C$, also $SAIDI = SAIFI \times CAIDI$)

System Average Interruption Frequency Index (SAIFI) is an indicator of average service interruption frequency experienced by customers on a system. It is calculated by dividing the number of customer interruptions by the number of customers served. ($SAIFI = CI \div C$, also $SAIFI = SAIDI \div CAIDI$)

Executive Summary

The Florida Public Service Commission (FPSC or Commission) has jurisdiction to monitor the reliability of electric service provided by Florida's investor-owned electric utilities (IOUs) for maintenance, operational, and emergency purposes.¹ This report is a compilation of the 2018 electric distribution reliability data filed by Florida's IOUs. The data is presented using tables and figures so that trends in each IOU's service reliability may be easily observed. In addition, the scope of the IOUs' Annual Distribution Service Reliability Report was expanded to include status reports on the various storm hardening and preparedness initiatives required by the Commission.² This data may be used during rate cases, show cause dockets, and is helpful in resolving customer complaints.

Monitoring service reliability is achieved through a review of service reliability metrics provided by the IOUs pursuant to Rule 25-6.0455, Florida Administrative Code (F.A.C.).³ Service reliability metrics are intended to reflect changes over time in system average performance, regional performance, and sub-regional performance. For a given system, increases in the value of a given reliability metric denote declining reliability in the service provided. Comparison of the year-to-year levels of the reliability metrics may reveal changes in performance, which indicates the need for additional investigation, or work in one or more areas. Rule 25-6.0455, F.A.C., requires the IOUs to file distribution reliability reports to track adjusted performance that excludes events such as planned outages for maintenance, generation disturbances, transmission disturbances, wildfires, and extreme acts of nature such as tornadoes and hurricanes. This "adjusted" data provides an indication of the distribution system performance on a normal day-to-day basis.

The active hurricane seasons of 2004 and 2005 revealed the importance of collecting reliability data that reflects the total reliability experience from the customer perspective. In June 2006, Rule 25-6.0455, F.A.C., was revised to require each IOU to provide both "actual" and "adjusted" performance data for the prior year. This data provides insight concerning the overall reliability performance of each utility.

The March 2019 Distribution Reliability Reports of Duke Energy Florida, LLC (DEF), Florida Power & Light Company (FPL), Florida Public Utilities Company (FPUC), Gulf Power Company (Gulf), and Tampa Electric Company (TECO) and responses to staff's data requests were sufficient to perform the 2018 review.

The following company specific summaries provide highlights of the observed patterns.

¹Sections 366.04(2)c and 366.05, Florida Statutes.

²Wooden Pole Inspection Orders: FPSC Order No. PSC-06-0144-PAA-EI, issued February 27, 2006, in Docket No. 20060078-EI; and FPSC Order Nos. PSC-06-0778-PAA-EU, issued September 18, 2006, PSC-07-0078-PAA-EU, issued January 29, 2007, in Docket No. 20060531-EU.

Storm Preparedness Initiative Orders: FPSC Order Nos. PSC-06-0351-PAA-EI, issued April 25, 2006, PSC-06-0781-PAA-EI, issued September 19, 2006, PSC-06-0947-PAA-EI, issued November 13, 2006, and PSC-07-0468-FOF-EI, issued May 30, 2007, in Docket No. 20060198-EI.

³The Commission does not have rules or statutory authority requiring municipal electric utilities and rural electric cooperative utilities to file service reliability metrics.

Service Reliability of Duke Energy Florida, LLC

The unadjusted data for DEF indicates that its 2018 allowable exclusions accounted for approximately 56 percent of all excluded Customer Minutes of Interruption (CMI). The “Named Storms” category accounted for approximately 45 percent of the CMI excluded. DEF experienced one tornado, Tropical Storm Alberto, Tropical Storm Gordon, and Hurricane Michael.

On an adjusted basis, DEF’s 2018 System Average Interruption Duration Index (SAIDI) was 99 minutes, increasing its adjusted SAIDI by 16 minutes from the 2017 results. The trend for the SAIDI over the five-year period of 2014 to 2018 is trending upward. The System Average Interruption Frequency Index (SAIFI) in 2018 was 1.01 interruptions, indicating a 10 percent increase from 2017. The Customer Average Interruption Duration Index (CAIDI) increased for 2018 compared to 2017. Over the five-year period, the SAIFI is trending downward as the CAIDI is trending upward.

In **Figure 3-8**, DEF’s Top Five Outage Categories, the category “Defective Equipment” is in the top spot representing 28 percent of the top 10 outage categories. The subsequent categories were “Vegetation” (20 percent) and “Other Causes” (19 percent), followed by “Other Weather” (15 percent) and “Animals” (11 percent). The “Vegetation,” “Other Causes,” and “Other Weather” outage categories are trending downward for the five-year period of 2014 to 2018 even though the “Other Weather” category had a 18 percent increase in 2018, the “Vegetation” category had a 5 percent increase, and the “Other Cause” category had a 0.3 percent increase. The “Defective Equipment” category had an increase between 2017 and 2018 and continued to trend upward for the five-year period. The “Animals” category had a decrease in 2018 and is trending downward for the five-year period.

The percentage of reliability complaints compared to the total number of complaints filed with the Commission for DEF increased to 4.3 percent in 2018 from 4.2 percent in 2017. Over the five-year period from 2014-2018, DEF’s reliability related complaints have been trending slightly downward.

In 2018, DEF completed 1,002 storm hardening projects for existing transmission structures. The projects included maintenance pole change-outs, insulator replacements, Department of Transportation/customer relocations, line rebuilds, and system planning additions. The transmission structures are designed to withstand the National Electrical Safety Code (NESC) wind requirements and are built utilizing steel or concrete structures. In addition, DEF replaced 1,168 wooden transmission poles in 2018. At year-end 2018, DEF reported it had 20,117 transmission wooden poles left to harden and plans to harden 1,008 transmission structures and replace 880 wooden transmission poles in 2019.

Service Reliability of Florida Power & Light Company

The unadjusted data for FPL indicates that its 2018 allowable exclusions accounted for approximately 15 percent of the total CMI. The “Named Storms” category accounted for approximately 2.5 percent of the CMI excluded. In addition, FPL’s service area was affected by 6 tornadoes, ice on the lines, Tropical Storm Alberto, Tropical Storm Gordon, and Hurricane Michael.

FPL's 2018 metrics on an adjusted basis include SAIDI which was reported as 53 minutes and represents a 1 minute decrease from last year's reported 54 minutes. The SAIFI improved in 2018 and the CAIDI remained the same. The SAIFI decreased from 0.90 interruptions in 2017 to 0.89 interruptions in 2018 and the CAIDI remained at 60 minutes, as it was in 2017.

"Defective Equipment" (37 percent) and "Vegetation" (17 percent) outages were the leading causes of outage events per customer for 2018. The next three outage causes are "Unknown Causes" (11 percent), "Other Causes" (11 percent), and "Animals" (10 percent). **Figure 3-16** shows an increasing trend in the number of outage events attributed to "Other Cause," which had increased by 6 percent from 2017 to 2018. The analysis shows a decrease in the number of outage events caused by "Defective Equipment," "Vegetation," "Unknown Causes," and "Animals." The number of outages decreased by 8 percent for "Vegetation" and "Unknown Causes" decreased by 0.4 percent from 2017 to 2018. The analysis shows that the "Animals" category is trending downward with a decrease in outages of 1 percent and the "Defective Equipment" category experienced a decrease in outages of 4 percent.

Complaints related to FPL's reliability decreased by 0.1 percent from 2017 to 2018. FPL's reliability related complaints appear to be relatively flat as shown in **Figure 4-10**, even with the decrease in 2018.

In 2018, FPL replaced 1,117 wood transmission structures with spun concrete poles. FPL completed the replacement of ceramic post insulator with polymer insulators in 2014. Also, in 2014, FPL completed the installation of water-level monitoring systems and communication equipment in 223 substations. During 2019 through 2021, FPL plans to replace approximately 1,000 to 1,500 wood transmission structures. FPL has 4,900 wood transmission structures remaining to be replaced.

Service Reliability of Florida Public Utilities Company

The unadjusted data for FPUC indicates that its 2018 allowable exclusions accounted for approximately 99 percent of the total CMI. The "Named Storms" category accounted for approximately 98.4 percent of the CMI excluded. FPUC reported that during 2018, the Northeast division was not impacted by extreme weather events. However, the Northwest division was impacted by Tropical Storm Alberto, Tropical Storm Gordon, and Hurricane Michael.

The 2018 adjusted data for FPUC's SAIDI was 154 minutes, an 11 percent increase from 139 minutes reported in the previous year. The SAIFI decreased from 1.64 interruptions in 2017 to 1.45 interruptions in 2018. The CAIDI value in 2018 was 107 minutes, an increase from the 85 minutes in 2017.

FPUC's top five causes of outages included "Vegetation," "Animals," "Defective Equipment," "Lightning," and "Unknown" events. As shown in **Figure 3-21**, "Vegetation" (38 percent) was the number one cause of outages in 2018 followed by "Animals" (18 percent), "Defective Equipment" (14 percent), "Lightning" (12 percent), and "Unknown" (6 percent). "Animals," and "Defective Equipment" attributed outages decreased in 2018, as "Vegetation," "Lightning," and "Unknown" caused outages increased.

FPUC's reliability related complaints were minimal. In 2018, the Utility had five reliability related complaints filed with the Commission. The volatility in FPUC's results can be attributed to its small customer base that averages 28,000 or fewer customers. For the last five years, the percentage of reliability related complaints against FPUC have been trending upward.

All of the Northeast division's 138kV poles are constructed of concrete and steel. The Northeast division's 69kV transmission system consists of 217 poles, of which 105 are concrete. The Northwest division does not have transmission structures. In 2018, FPUC did not harden any of its transmission structures. However, FPUC plans to harden 10 structures in 2019 and has 112 transmission structures remaining to be hardened.

Service Reliability of Gulf Power Company

The adjusted data for Gulf indicates that its 2018 allowable exclusions accounted for 97 percent of exclusion to its CMI. The "Named Storms" category accounted for approximately 95.9 percent of the total CMI excluded. Gulf explained that Hurricane Michael, Tropical Storm Alberto, and Tropical Storm Gordon affected its service area. In 2018, four tornadoes also affected its service area accounting for 0.05 percent of the total CMI.

The 2018 SAIDI for Gulf was reported to be 97 minutes, which decreased from the 116 minutes reported in 2017. The SAIFI increased to 1.26 interruptions from 1.20 interruptions the previous year. The CAIDI decreased to 77 minutes from 97 minutes in 2017. Gulf stated that it continues to collect outage data, which extends to the customer meter level. The Utility reviews outage data and the resulting reliability indices at the system level and at its three regions. Gulf is analyzing 2018 data to determine the need for any specific improvement opportunities beyond the current programs and storm hardening initiatives.

Gulf's top five causes of outages were "Defective Equipment" (24 percent), "Vegetation" (23 percent), "Animals" (20 percent), "Lightning" (15 percent), and "Unknown Causes" (10 percent). As shown in **Figure 3-29**, the number of outages decreased for "Defective Equipment," "Animals," and "Lightning" in 2018 when compared to 2017.

There were no complaints reported to the Commission against Gulf that were reliability related in 2018. Gulf's percentage of total complaints for the five-year period of 2014 to 2018 has remained relatively flat. Overall, as shown in **Figure 4-10**, Gulf has the lowest percentage of total complaints related to reliability.

Gulf had two priority goals for hardening its transmission structures: installation of guys on H-frame structures and replacement of wooden cross arms with steel cross arms. The installation of guys on H-frame structures was completed in 2012. The replacement of wooden cross arms was completed in 2018. In addition, going forward, Gulf plans to replace all wooden structures on its transmission system with steel or concrete structures. Gulf plans to replace approximately 100 wooden structures in 2019.

Service Reliability of Tampa Electric Company

The adjusted data for TECO indicates that its 2018 allowable exclusions accounted for approximately 21 percent of the CMI. The “Planned Service Interruptions” category accounted for approximately 11 percent of the CMI. There were no extreme weather events that affected TECO’s service area in 2018.

The adjusted SAIDI increased from 73 minutes in 2017 to 95 minutes in 2018 and represents a 30 percent decline in performance. The SAIFI increased to 1.18 interruptions from 1.03 interruptions in the previous year. The CAIDI increased 13 percent, to 80 minutes from 71 minutes reported in 2017. TECO reported the increases in SAIDI, SAIFI, and CAIDI were attributed to several unnamed storms that occurred in November and December 2018.

“Defective Equipment” (24 percent) and “Vegetation” (24 percent) were the largest contributors to TECO’s causes of outage events followed by “Lightning” (18 percent), “Animals” (12 percent), and “Unknown Causes” (11 percent). **Figure 3-37** illustrates the top five outage causes. “Defective Equipment,” the leading cause of outages, has been trending downward since 2014 even though “Defective Equipment” had an 8 percent increase in outages when compared to the previous year. “Animal” and “Lightning” related causes are also trending downward. “Vegetation” and “Unknown Causes” related causes are trending upward with increases of 24 percent and 31 percent, respectively, in 2018.

TECO’s percentage of total service reliability related complaints increased from 8.0 percent in 2017 to 11.2 percent in 2018. TECO’s percentage of service reliability complaints is trending upward over the period of 2014 to 2018. TECO will continue to focus on vegetation management, circuit review activity, line improvements, and other maintenance activities to minimize service-related complaints, in 2019. Working through and responding to complaints at a regional level affords TECO an opportunity to be aware of any trends that may occur for a given feeder or lateral.

TECO’s transmission system is hardened by utilizing its inspections and maintenance program to systematically replace wood structures with non-wood structures. In 2018, TECO hardened 164 structures including 155 pole replacements utilizing steel or concrete poles and replaced 9 sets of insulators with polymer insulators. TECO’s future goal is to harden 120 transmission structures and it has approximately 5,104 wooden poles remaining to be replaced.

Review Outline

This review primarily relies on the March 2019 Reliability Reports filed by the IOUs for the 2018 reliability performance data and storm hardening and preparedness initiatives. A section addressing trends in reliability related complaints is also included. Staff's review consists of five sections:

- ◆ **Section I:** Storm hardening activities, which include each IOU's Eight-Year Wooden Pole Inspection Program and the Ten Storm Preparedness Initiatives.
- ◆ **Section II:** Each utility's actual 2018 distribution service reliability data and support for each of its adjustments to the actual service reliability data.
- ◆ **Section III:** Each utility's 2018 distribution service reliability based on adjusted service reliability data and staff's observations of overall service reliability performance.
- ◆ **Section IV:** Inter-utility comparisons and the volume of reliability related customer complaints for 2014 to 2018.
- ◆ **Section V:** Appendices containing detailed utility specific data of the IOUs and summaries of the municipal and rural cooperative utilities.

Section I: Storm Hardening Activities

Each IOU, pursuant to Rule 25-6.0342(2), F.A.C., must file a storm hardening plan which is required to be updated every three years. The IOU's fourth updated storm hardening plans were filed on March 2 and 3, 2019.⁴ The following subsections provide a summary of each IOU's programs addressing an on-going Eight-Year Wooden Pole Inspection Program and the Ten Storm Preparedness Initiatives as directed by the Commission.

Eight-Year Wooden Pole Inspection Program

FPSC Order Nos. PSC-06-0144-PAA-EI, issued February 27, 2006, in Docket No. 20060078-EI and PSC-07-0078-PAA-EU, issued January 29, 2007, in Docket No. 20060531-EU, require each IOU to inspect 100 percent of their installed wooden poles within an eight-year inspection cycle. The National Electrical Safety Code (NESC) serves as a basis for the design of replacement poles for wooden poles failing inspection. Additionally, Rule 25-6.0342(3)(b), F.A.C., requires that each utility's storm hardening plan address the extent to which the plan adopts extreme wind loading standards as specified in Figure 250-2(d) of the most recent edition of the NESC.

⁴Docket Nos. 20180144-EI (FPL), 20180145-EI (TECO), 20180146-EI (DEF), 20180147-EI (Gulf), and 20180148-EI (FPUC), *In re: Review of 2019-2021 storm hardening plan*.

Table 1-1 shows a summary of the quantities of wooden poles inspected by all IOUs in 2018.

Table 1-1
2018 Wooden Pole Inspection Summary

Utility	Total Poles	Poles Planned 2018	Poles Inspected 2018	Poles Failed Inspection	% Failed Inspection	Years Complete in 8-Year Inspection Cycle
DEF	802,982	100,000	101,607	1,963	1.93%	4
FPL	1,075,419	124,915	135,559	6,547	4.83%	5
FPUC*	26,548	3,413	0	0	0.0%	3
GULF	208,488	26,000	28,070	762	2.71%	5
TECO	285,000	39,500	39,887	2,673	6.70%	5

Source: The IOUs 2018 distribution service reliability reports.

Note: *FPUC reported that poles scheduled to be inspected in October 2018 were not inspected due to Hurricane Michael.

Table 1-2 indicates the projected wooden pole inspection requirements for the IOUs.

Table 1-2
Projected 2019 Wooden Pole Inspection Summary

Utility	Total Poles	Total Number of Wood Poles Inspected in current cycle	Number of Wood Pole Inspections Planned for 2019	Percent of Wood Poles Planned 2019	Percent of Wood Pole Inspections Completed in 8-Year Cycle	Years Remaining in 8-Year Cycle After 2016
DEF	802,982	496,903	100,000	12.45%	62%	4
FPL	1,075,419	646,945	124,915	11.62%	60%	3
FPUC	26,548	6,583	6,765	25.48%	25%	5
GULF	208,488	132,306	26,000	12.47%	63%	3
TECO	285,000	161,672	35,900	12.60%	57%	3

Source: The IOUs 2018 distribution service reliability reports.

The annual variances shown in Tables 1-1 and 1-2 are allowable so long as each utility achieves 100 percent inspection within an eight-year period. Staff continues to monitor each utility's performance.

Ten Initiatives for Storm Preparedness

On April 25, 2006, the Commission issued FPSC Order No. PSC-06-0351-PAA-EI, in Docket No. 20060198-EI. This Order required that the IOUs file plans for Ten Storm Preparedness Initiatives (Ten Initiatives).⁵ Storm hardening activities and associated programs are on-going parts of the annual reliability reports required from each IOU since rule changes in 2006. The status of these initiatives is discussed in each IOU's report for 2018. Separate from the Ten Initiatives, and not included in this review, the Commission established rules addressing storm hardening of transmission and distribution facilities for all of Florida's electric utilities.^{6,7,8}

Initiative 1 - Three-Year Vegetation Management Cycle for Distribution Circuits

Each IOU continues to maintain the commitment to complete three-year trim cycles for overhead feeder circuits, except for TECO, which is on a four-year cycle, since feeder circuits are the main arteries from the substations to the local communities. The approved plans of all the IOUs also require a maximum of a six-year trim cycle for lateral circuits. In addition to the planned trimming cycles, each IOU performs hot-spot tree trimming⁹ and mid-cycle trimming to address rapid growth problems.

⁵Docket No. 20060198-EI, *In re: Requirement for investor-owned electric utilities to file ongoing storm preparedness plans and implementation cost estimates.*

⁶FPSC Order No. PSC-06-0556-NOR-EU, issued June 28, 2006, in Docket No. 20060172-EU, *In re: Proposed rules governing placement of new electric distribution facilities underground, and conversion of existing overhead distribution facilities to underground facilities, to address effects of extreme weather events*, and Docket No. 20060173-EU, *In re: Proposed amendments to rules regarding overhead electric facilities to allow more stringent construction standards than required by National Electric Safety Code.*

⁷FPSC Order Nos. PSC-07-0043-FOF-EU, issued January 16, 2007, and PSC-07-0043A-FOF-EU, issued January 17, 2007, both in Docket Nos. 20060173-EU and 20060172-EU.

⁸FPSC Order No. PSC-06-0969-FOF-EU, issued November 21, 2006, in Docket No. 20060512-EU, *In re: Proposed adoption of new Rule 25-6.0343, F.A.C., Standards of Construction - Municipal Electric Utilities and Rural Electric Cooperatives.*

⁹Hot-spot tree trimming occurs when an unscheduled tree trimming crew is dispatched or other prompt tree trimming action is taken at one specific location along the circuit. For example, a fast growing tree requires hot-spot tree trimming in addition to the cyclical tree trimming activities. TECO defines hot-spot trimming as any internal or external customer driven request for tree trimming. Therefore, all tree trim requests outside of full circuit trimming activities are categorized as hot-spot trims.

Table 1-3 is a summary of feeder vegetation management activities by each company's cycle.

Table 1-3
Vegetation Clearing from Feeder Circuits

IOU	# of Years in Cycle	1 st Year of Cycle	Total Feeder Miles	Miles Trimmed				Total Miles Trimmed	% of Miles Trimmed
				1 st Year	2 nd Year	3 rd Year	4 th Year		
DEF	3	2018	5,268	662				662	12.6%
FPL	3	2016	12,850	4,418	4,381	4,251		13,050	101.6%
FPUC	3	2017	159	29	47			77	48.2%
GULF	3	2016	723	241	280			521	72.1%
TECO	4	2017	1,759	198.9	402.6			602	34.2%

Source: The IOUs 2018 distribution service reliability reports.

Note: In 2012, the Commission approved TECO's request to modify its trim cycle for feeders to four years.¹⁰

Based on the data in Table 1-3, it appears that FPL has completed its feeder vegetation cycles. Gulf appears to be on schedule with its vegetation cycle. DEF has started the first year of its three-year feeder trim cycle and appears to be behind schedule. DEF explained that contract resource availability and multiple hurricanes prevented DEF from completing the full mileage scheduled. FPUC appears to be behind schedule for the three-year feeder trim cycle with 48.2 percent completed. FPUC suggests that its vegetation management would be more efficient if it trimmed all of the laterals associated with the feeders at the same time. This would allow FPUC to keep the trim crews in the same general area instead of moving them to different feeders or laterals. This vegetation management schedule has been started in several locations. TECO indicates that it is behind schedule with its vegetation management cycles due to recent storm activity. TECO explained that due to the storm activity, utilities, municipalities, and private industries have been competing for resources to increase the amount of vegetation management performed. In addition, the changing job market has led to increased resource costs.

¹⁰FPSC Order No. PSC-12-0303-PAA-EI, issued June 12, 2012, in Docket No. 20120038-EI, *In re: Petition to modify vegetation management plan by Tampa Electric Company*.

Table 1-4 is a summary of the lateral vegetation management activities by company.

Table 1-4
Vegetation Clearing from Lateral Circuits

IOU	# of Years in Cycle	1 st Year of Cycle	Total Lateral Miles	Miles Trimmed						Total Lateral Miles Trimmed	% of Lateral Miles Trimmed
				1 st Year	2 nd Year	3 rd Year	4 th Year	5 th Year	6 th Year		
DEF	5	2016	12,744	2,173	1,909	2,626				6,708	52.6%
FPL	6	2013	22,788	4,124	3,685	3,817	3,745	3,560	3,926	22,857	100.3%
FPUC	6	2014	571	145	134	188	86	100		654	114.5%
GULF	4	2018	5,148	1,617						1,617	31.4%
TECO	4	2017	4,488	627	834					1,461	32.6%

Source: The IOUs 2018 distribution service reliability reports.

Note: In 2006, the Commission approved DEF's request to modify its lateral trim cycle to five years.¹¹ In the same docket, the Commission approved FPL's modified trim cycle for laterals to six years.¹² FPUC's lateral trim cycle was modified to six years in 2010.¹³ The Commission approved Gulf's modified lateral trim cycle to four years in 2010.¹⁴ In 2012, the Commission approved TECO's request to modify its trim cycle for laterals to four years.¹⁵

From the data in Table 1-4, it appears that FPL and FPUC have completed their lateral vegetation cycles. DEF is in the third year of its five-year lateral trim cycle with 52.6 percent laterals trimmed indicating that DEF is behind schedule. As previously discussed, DEF was prevented from completing the scheduled trim miles because of contract resource availability and multiple hurricanes. . Gulf reported that its goal is to trim one-fourth of its lateral lines each year. Gulf started its new four-year lateral trim cycle in 2018 and appears to be ahead of schedule. As previously discussed, TECO is behind schedule with its vegetation management cycles due to the storm activity causing limited resource availability and increased resource costs.

Tables 1-3 and 1-4 do not reflect hot-spot trimming and mid-cycle trimming activities. An additional factor to consider is that not all miles of overhead distribution circuits require

¹¹FPSC Order No. PSC-06-0947-PAA-EI, issued November 13, 2006, in Docket No. 20060198-EI, *In re: Requirement for investor-owned electric utilities to file ongoing storm preparedness plans and implementation cost estimates*.

¹²FPSC Order No. PSC-07-0468-FOF-EI, issued May 30, 2007, in Docket No. 20060198-EI, *In re: Requirement for investor-owned electric utilities to file ongoing storm preparedness plans and implementation cost estimates*.

¹³FPSC Order No. PSC-10-0687-PAA-EI, issued November 15, 2010, in Docket No. 20100264-EI, *In re: Review of 2010 Electric Infrastructure Storm Hardening Plan filed pursuant to Rule 25-6.0342, F.A.C., submitted by Florida Public Utilities Company*.

¹⁴FPSC Order No. PSC-10-0688-PAA-EI, issued November 15, 2010, in Docket No. 20100265-EI, *In re: Review of 2010 Electric Infrastructure Storm Hardening Plan filed pursuant to Rule 25-6.0342, F.A.C., submitted by Gulf Power Company*.

¹⁵FPSC Order No. PSC-12-0303-PAA-EI, issued June 12, 2012, in Docket No. 20120038-EI, *In re: Petition to modify vegetation management plan by Tampa Electric Company*.

vegetation clearing. Factors such as hot-spot trimming and open areas contribute to the apparent variances from the approved plans. Annual variances as seen in Tables 1-3 and 1-4 are allowable as long as each utility achieves 100 percent completion within the cycle-period stated in its approved plan for feeder and lateral circuits.

Initiative 2 - Audit of Joint-Use Agreements

For storm hardening purposes, the benefits of fewer attachments are reflected in the extreme wind loading rating of the overall design of pole loading considerations. Each IOU monitors the impact of attachments by other parties to ensure the attachments conform to the utility's strength and loading requirements without compromising storm hardening performance. Each IOU's plan for performing pole strength assessments includes the stress impacts of all pole attachments as an integral part of its eight-year wood pole inspection program. In addition, these assessments are also conducted on concrete and steel poles. The following are some 2018 highlights:

- ◆ DEF performs its joint-use audit on an eight-year cycle with 2018 being the fourth year in the current cycle. In 2018, DEF audited one-eighth of its joint-use attachments. Of the 56,929 distribution poles that were strength tested 47 failed the test. DEF added guy wires to 5 poles and replaced 42 of the failed poles. DEF found no unauthorized attachments on the poles. Of its 5,761 joint-use transmission poles, 779 poles were strength tested with 31 poles failing the test. Thirteen structures have been replaced and eighteen are scheduled for replacement in 2019.
- ◆ FPL audited approximately 20 percent of its service territory through its joint-use survey in order to determine the number and ownership of jointly used poles and associated attachments in 2018. Pole strength and loading tests were also performed on the joint-use poles. The results show that 35 poles (0.04 percent) failed the strength test due to overloading. The results also show that 2,163 poles (2.33 percent) failed the strength test due to other reasons, which could include pole decay or damage caused by lightning, woodpeckers, or vehicle accidents. FPL will replace 730 poles and reinforce 1,433 poles. The 2018 survey and inspection results show that no unauthorized attachments were found.
- ◆ FPUC added language to its Joint-Use Agreements to clarify joint-use safety audit instructions, in 2014. The additional language included a provision for an initial joint-use pole attachment audit to take place 12 months after the effective date of the Agreement, and on a five-year recurring cycle after the first audit. Currently, four Joint-Use Agreements have been executed. The other agreements are being negotiated. FPUC completed the joint-use pole attachment audit in 2016 and discovered discrepancies in the total number of attachments. There were 2,054 attachments identified as unauthorized and no poles failed the strength test. The next audit should take place in 2021.
- ◆ Gulf performs its joint-use inventory audits every five years. The last audit was completed in October 2016 and the next audit will be conducted in 2021. As of 2018, Gulf has 234,262 distribution poles with 313,990 third-party attachers. Gulf is attached to 62,272 foreign poles (poles not owned by Gulf). Gulf's mapping system has been updated to reflect the third-party attachments.

- ◆ TECO conducted comprehensive loading analysis and continued to streamline its processes to better manage attachment requests from attaching entities, in 2018. A comprehensive loading analysis was performed on 3,205 poles. TECO identified 280 distribution poles that were overloaded and 2,673 failed the strength test due to wood damage. All poles were corrected by being re-guyed, re-configured or reinforced with trusses. TECO also found 1,683 poles that had NESC violations due to joint-use attachments and 502 poles with NESC violations due to TECO's attachments.

Initiative 3 - Six-Year Transmission Inspections

The IOUs are required by the Commission to inspect all transmission structures and substations, and all hardware associated with these facilities. Approval of any alternative to a six-year cycle must be shown to be equivalent or better than a six-year cycle, in terms of cost and reliability in preparing for future storms. The approved plans for DEF, FPL, FPUC, Gulf, and TECO require full inspection of all transmission facilities within a six-year cycle. DEF, which already had a program indexed to a five-year cycle, continues with its five-year program. Such variances are allowed so long as each utility achieves 100 percent completion within a six-year period, as outlined in FPSC Order No. PSC-06-0781-PAA-EI, issued September 19, 2006, in Docket No. 20060198-EI.

- ◆ DEF inspected 280 transmission circuits (41 percent), 489 transmission substations (100 percent), 994 transmission tower structures (28.9 percent), and 779 transmission poles (1.5 percent), in 2018. DEF plans to inspect 62 percent of the transmission system in 2019. DEF performs an aerial inspection of transmission structures twice a year. In addition, DEF performs visual inspections on segments containing wood poles on a four-year cycle and visual inspection on segments containing non-wood poles on a five-year cycle. A sound and bore inspection is performed on wooden poles on an eight-year cycle.
- ◆ FPL began a new six-year cycle, performing climbing inspections on all 500kV structures, in 2014. Climbing inspections for all other steel and concrete structures are on a ten-year cycle. In 2018, FPL inspected approximately 85 percent of transmission circuits, 100 percent of transmission substations, 100 percent of non-wood transmission tower structures, and 35 percent of wood transmission poles. In addition, FPL inspects 100 percent of its wooden poles and structures by performing a visual inspection at ground level each year. It appears that FPL is on target for its six-year transmission inspections.
- ◆ FPUC inspected 100 percent of transmission circuits, transmission substations, tower structures, and transmission poles, in 2018. The transmission inspections included climbing patrols of 95 138kV and 217 69kV structures. Transmission inspections will be conducted at a minimum every six years on all transmission facilities. FPUC is on schedule for its transmission facilities inspections, with the next inspection scheduled to be completed by year-end of 2024.

- ◆ Gulf inspected 56 transmission substations in 2018 and conducted 8 inspections of its metal poles and towers as well as 1,342 wood and concrete transmission poles. Gulf also performed four aerial inspections. The Utility replaced 94 of its wooden transmission poles. Most of the transmission metal pole and tower inspections were scheduled for the end of the year. Those inspections were not completed due to Hurricane Michael and will be absorbed into the remaining cycle schedule. Gulf's transmission line inspections include a ground line treatment inspection, a comprehensive walking inspection, and aerial inspections. The transmission inspections are based on two alternating 12-year cycles, which results in the structures being inspected at least once every six years. It appears that Gulf is behind schedule for its transmission inspections; however, as stated above, Gulf will absorb those inspections into the remaining cycle schedule.
- ◆ TECO's transmission system inspection program includes ground patrol, aerial infrared patrol, substation inspections, which are on a one-year cycle, above ground inspection and ground line inspection, which is on an eight-year cycle. The above ground inspection was shifted from a six-year cycle to an eight-year cycle in 2015 by FPSC Order No. PSC-14-0684-PAA-EI, issued December 10, 2014, in Docket No. 20140122-EI. Additionally, pre-climb inspections are performed prior to commencing work on any structure. In 2018, TECO inspected 72 (100 percent) of its transmission substations and completed 207 (100 percent) of its planned transmission equipment inspections. There were 1,028 ground line and 3,031 above ground transmission circuit inspections performed in 2018. It appears that TECO is on target for its transmission inspection schedule.

Initiative 4 - Hardening of Existing Transmission Structures

Hardening transmission infrastructure for severe storms is important in order to continue providing transmission of electricity to high priority customers and key economic centers. IOUs are required by the Commission to show the extent of the utility's efforts in hardening of existing transmission structures. No specific activity was ordered other than developing a plan and reporting on storm hardening of existing transmission structures. In general, all of the IOU's plans continued pre-existing programs that focus on upgrading older wooden transmission poles. Highlights of 2018 and projected 2019 activities for each IOU are explained below.

- ◆ DEF planned 1,002 transmission structures for hardening and completed hardening of 1,168 transmission structures, which includes maintenance pole change-outs, insulator replacements, Department of Transportation/customer relocations, line rebuilds, and system planning additions. The transmission structures are designed to withstand the current NESC wind requirements and are built utilizing steel or concrete structures. In addition, DEF replaced 1,168 wooden transmission poles in 2018. In 2019, DEF plans to harden 1,008 transmission structures and replace 880 wooden poles. DEF reported 58,762 transmission poles, with 20,117 wooden poles (38 percent) that remain to be hardened.
- ◆ FPL completed all replacements of its ceramic post insulators with polymer insulators in 2014. In addition, FPL completed the installation of water-level monitoring systems and communication equipment in its 223 substations. In 2018, FPL replaced 1,117 wooden transmission structures with spun concrete poles. By year-end, FPL had 4,900 (7 percent) wooden transmission structures that remain to be replaced.

- ◆ FPUC did not harden any of its transmission structures, in 2018. However, FPUC does plan to harden 10 structures in 2019. All of the Northeast division's 138kV poles are constructed of concrete and steel and meet NESC standards. The Northeast division's 69kV transmission system consists of 217 poles of which 105 are concrete poles, 7 are wood span guys and 105 are wooden structures. FPUC has 112 transmission structures (51 percent) that remain to be hardened. FPUC explained that wood span guy poles are smaller sized poles that are installed to accept a span guy from the top of the 69kV poles to offset the strain from the line conductor. Span guys transmit horizontal force to another pole until an anchor guy can be used. FPUC indicated that during the hardening replacements, it designed and installed self-supporting structures, which in most cases eliminates the need to use span guys. The Northwest division does not have transmission structures.
- ◆ Gulf has two priority goals for hardening its transmission structures: installation of guys on H-frame structures and replacement of wooden cross arms with steel cross arms. The installation of guys on H-frame structures was completed in 2012. In 2018, the remaining wooden cross arms were replaced. The Utility plans to replace all wooden structures on the transmission system with steel or concrete structures. At this time, Gulf has not set a long-term goal (completion date) for the replacement of all wooden transmission structures on its system, and is currently working on the budget, engineering, and planning phases. Gulf is planning to replace approximately 100 wooden transmission structures in 2019 with steel or concrete structures as part of the ongoing storm hardening plan.
- ◆ TECO is hardening the existing transmission system by utilizing its inspections and maintenance program to systematically replace wood structures with non-wood structures. In 2018, TECO hardened 164 structures including 155 structure replacements utilizing steel or concrete poles and replaced 9 sets of insulators with polymer insulators. TECO's goal for 2019 is to harden 120 transmission structures. TECO has approximately 5,104 (20 percent) wooden poles that remain to be replaced.

Initiative 5 - Transmission and Distribution Geographic Information System

Initiative 6 - Post-Storm Data Collection and Forensic Analysis

Initiative 7 - Collection of Detailed Outage Data Differentiating Between the Reliability Performance of Overhead and Underground Systems

These three initiatives are addressed together because effective implementation of any one initiative is dependent upon effective implementation of the other two initiatives. The five IOUs have Geographic Information System (GIS) and other programs to collect post-storm data on competing technologies, perform forensic analysis, and assessment of the reliability of overhead and underground systems on an ongoing basis. Differentiating between overhead and underground reliability performance and costs is still difficult because underground facilities are typically connected to overhead facilities and the interconnected systems of the IOUs address reliability on an overall basis. The electric utility companies have implemented an Outage Management System (OMS). The collection of information for the OMS is being utilized in the form of a database for emergency preparedness. This will help utilities identify and restore

outages sooner and more efficiently. The OMS also fills a need for systems and methods to facilitate the dispatching of maintenance crews during outages, and for providing an estimated time to restore power to customers. Effective restoration will also yield improved customer service and increased electric utility reliability. The year 2018 highlights and projected 2019 activities for each IOU are listed below:

- ◆ DEF's forensics teams will participate in DEF's 2019 Storm Drill. During field observations, the forensics team collects various information regarding poles damaged during storm events and collects sufficient data at failure sites to determine the nature and cause of the failure. In collaboration with University of Florida's Public Utility Research Center (PURC), DEF and the other IOUs developed a common format to collect and track data related to damage discovered during forensics investigation. Weather stations were installed across Florida as part of the collaboration with PURC and the other IOUs. As a result, DEF is now able to correlate experienced outages with nearby wind speeds. This type of information is augmented with on-site forensics data following a major storm event. DEF collects information to determine the percentage of storm caused outages on overhead and underground systems.

DEF's GIS provides several sets of data and information points regarding DEF's assets. DEF uses OMS, Customer Service System, and GIS to help analyze the performance of its overhead and underground facilities. DEF collects available performance information as part of the storm restoration process. DEF implemented a new GIS, Work Management System, and Asset Management System in 2017. These systems allow DEF to facilitate the compliance tracking, maintenance, planning, and risk management of the major distribution and transmission assets. One hundred percent of the overhead and underground distribution and transmission systems are in the GIS. In addition, in 2018, DEF installed approximately 196 circuit miles of new underground cable. DEF indicated that its distribution system consists of 44 percent underground circuit miles.

In 2018, Hurricane Michael impacted all of the counties within DEF's service territory. The Utility performed data collection and analysis on the impact and found: 0.5 percent peak customers reporting outages in the North Central region, 16.8 percent in the North Coastal region, 1.9 percent in the South Central region, and 1.1 percent in the South Coastal region. DEF restored 775 distribution poles, 244,340 feet of conductor, 351 transformers, 12 substations, 130 transmission towers, 76 transmission circuits, and 23 transmission delivery points. In addition, DEF was required to completely rebuild three distribution feeders, which consisted of 1,465 distribution poles, 528,971 feet of conductor, and 460 transformers.

- ◆ FPL completed its five approved Key Distribution GIS improvement initiatives in 2012. The initiatives include post-hurricane forensic analyses, the addition of poles, streetlights, joint-use survey, and hardening level data to the GIS. Data collection and updates to the GIS will continue through inspection cycles and other normal daily work activities. FPL has post-storm data collection and forensic analysis plans, systems and processes in place and ready for use. The plans, systems and processes capture overhead and underground storm performance based on an alternative metric of analyzing performance of laterals.

FPL utilized its alternative plan to develop metrics to demonstrate the performance of, damage to, and causes of damage to overhead and underground facilities. This includes the population of overhead and underground feeders and laterals experiencing an outage versus the respective total population of feeders and laterals, the performance of overhead hardened versus non-hardened feeders, failure rates for overhead and underground transformers, failure rates for underground facilities by type, major causes of system damage, and overhead pole performance. Even though FPL was impacted by several named storms in 2018, the damage caused by the storms was not significant enough to warrant forensic analysis.

- ◆ FPUC uses GIS mapping for all of its deployed equipment and uses it to identify distribution and transmission facilities. The system interfaces with the Customer Information System to function as a Customer OMS. The implementation of the OMS has resulted in significant improvement in data collection and retrieval capability for analyzing and reporting reliability indices. In 2018, FPUC successfully implement an OMS enhancement in which customers are able to leave a voice message containing further information that is beneficial for managing outages. In addition, FPUC implemented a process to enable customer outage calls to be automatically logged into the system. Field data will be collected, analyzed, and entered into the OMS. The process is triggered 72 hours prior to a storm event. FPUC collects outage data attributed to overhead and underground equipment failure in order to evaluate the associated reliability indices. During 2018, there were no projects to convert overhead facilities to underground on FPUC's system.

FPUC reported that Hurricane Michael caused more than 2,000 poles to be broken, 1,200 transformers to require replacement, and displaced miles of conductor. Due to the nature of the storm, a forensic analysis was performed which focused on overhead feeder facilities. Of the 88 damaged poles that were surveyed, 86 poles (97.7 percent) were not storm hardened, leaving 2 poles (2.3 percent) that were hardened. FPUC determined that the damage to the hardened poles was caused by fallen trees and wind. Thirty-one poles (35.2 percent) were damaged due to fallen trees, and thirteen poles (14.8 percent) were damaged due to wind. Two poles (2.2 percent) were damaged due to flying debris and 42 poles (47.8 percent) were damaged due to a cascade effect. FPUC explained that a cascade effect occurs when a single pole fails and results in additional tension on the conductor which causes an adjacent pole to fail, and so forth. The cascade effect is less likely to occur with storm hardened poles, as those poles should be capable of withstanding additional tension.

- ◆ Gulf completed its distribution facilities mapping transition to its new Distribution GIS in 2009. The transmission system has been completely captured in the transmission GIS database. The Distribution GIS and Transmission GIS are continually updated with any additions and changes as the associated work orders for maintenance, system improvements, and new business are completed. This ongoing process provides Gulf sufficient information to use with collected forensic data to assess performance of its overhead and underground systems in the event of a major storm. The forensic data collection process was tested prior to storm season. This process was activated as part of Gulf's pre-storm preparation for Hurricane Michael. Data collection crews were mobilized and staged for a rapid post-storm response. The crews collected data on storm hardened lines, interstate crossings, predetermined areas, and random locations. The data was transferred to another contractor for data analysis. Using aerial patrol, Gulf was able to capture an initial assessment of the level of damage to the transmission system and record the GPS coordinates and failures with the Transmission Line Inspection System. Gulf's existing Common Transmission Database was utilized to capture all forensic information. Gulf did experience outages and damage from transmission outages, planned outages, and all other outages in 2018. Gulf will continue its record keeping and analysis of data associated with overhead and underground outages.

Gulf's forensic analysis of Hurricane Michael indicated that the peak outages were at 4:00 p.m. on October 10, 2018. Gulf reported that Hurricane Michael and the weather bands that radiated out from the storm affected, to some degree, every county that the Utility serves. Of Gulf's 457,125 total customers, 26.3 percent experienced outages. The Eastern region, which includes Bay, Holmes, Jackson, and Washington Counties, had over 95 percent of customers with outages. The Central region, which includes Okaloosa and Walton Counties, had an average of 8.32 percent of customers with outages. The Western region, which includes Escambia and Santa Rose Counties, had an average of 0.45 percent of customers without power. Gulf replaced approximately 7,000 distribution poles as a result of Hurricane Michael. No poles were repaired as part of the restoration efforts outside of straightening leaning poles, which are not tracked.

- ◆ TECO's GIS continues to serve as the foundational database for all transmission, substation and distribution facilities. Development and improvement of the GIS continues on an ongoing basis. In 2018, over 26 changes and enhancements to the system were made including: data updates, and functionality changes to better conform to business processes and improve the user experience. TECO uses an outside contractor to execute the process that includes the establishment of a field asset database, forensic measurement protocol, integration of forensics activity with overall system restoration, forensics data sampling and reporting format. TECO incurs costs based on the category of storm and level of activation of the outside contractor depending upon the number of storm events in 2019. The data collected following a significant storm will be used to determine the root cause of damage. An established process is in place for collecting post-storm data, forensic analysis and outage performance data for both overhead and underground systems. In 2018, TECO was not impacted by any extreme weather events and did not initiate storm data collection for forensic analysis.

Initiative 8 - Increased Utility Coordination with Local Governments

The Commission's goal with this program is to promote an ongoing dialogue between IOUs and local governments on matters such as vegetation management and underground construction, in addition to the general need to increase pre- and post-storm coordination. The increased coordination and communication is intended to promote IOU collection and analysis of more detailed information on the operational characteristics of underground and overhead systems. This additional data is also necessary to inform customers and communities that are considering converting existing overhead facilities to underground facilities (undergrounding), as well as to assess the most cost-effective storm hardening options.

Each IOU's external affairs representatives or designated liaisons are responsible for engaging in dialog with local governments on issues pertaining to undergrounding, vegetation management, public rights-of-way use, critical infrastructure projects, other storm-related topics, and day-to-day matters. Additionally, each IOU assigns staff to each county's EOC to participate in joint training exercises and actual storm restoration efforts. The IOUs organize ongoing outreach and educational programs addressing underground construction, tree placement, tree selection, and tree trimming practices.

- ◆ DEF's storm planning and response program is operational year-round to respond to catastrophic events at anytime. There are approximately 70 employees assigned full-time, year-round to coordinate with local governments on issues such as emergency planning, vegetation management, undergrounding, and service related issues. In 2018, DEF visited several EOCs in different counties to review storm procedures and participated in several different storm drills, including Florida's state wide annual storm drill, and will continue in 2019. Also in 2018, DEF held seven individual live-line demonstration sessions across its service territory. These events addressed emergency response, general safety awareness, a utility's perspective on hurricane preparedness, and safety issues. Representatives from the sheriff's departments, public schools, and fire/rescue departments attended these sessions.

When Hurricane Michael made landfall in Florida, DEF provided around the clock support for the State EOC and 19 county EOCs within its service territory. DEF executed its "Make It Safe" road-clearing program and modified it to provide support to counties well beyond 24-48 hours. In an effort to keep local governments and the public informed during the restoration process, DEF sent outbound customer messages, used social media sites, conducted print and broadcast interviews, participated in daily round table calls with the State, produced update videos, and distributed news releases.

- ◆ FPL continued efforts to improve local government coordination, in 2018. The Company conducted meetings with county emergency operations managers to discuss critical infrastructure locations in each jurisdiction. FPL also invited federal and state emergency management personnel to participate in FPL's annual storm preparedness drill. In 2018, FPL conducted over 930 community presentations providing information on storm readiness and other topics of community interest. FPL's dedicated government portal website provides reliable information to government leaders, which is useful during storm recovery. The site contains media alerts and releases, customer outage information

and maps, critical infrastructure facility information, estimated time of restoration information, FPL staging site locations, and available personnel resources. In addition, FPL meets with all counties and municipalities that request information on line clearing and underground conversions. In 2018, five municipalities signed an agreement to move forward with their undergrounding projects. The meetings also include discussions on vegetation management and planting the “right tree in the right place.”

- ◆ FPUC has continued its involvement with local governments regarding reliability issues with emphasis on vegetation management. FPUC’s current practice is to have its personnel located at the county EOCs on a 24-hour basis during emergency situations to ensure good communication. FPUC also has a dedicated Manager of Government Relations in each division. The manager’s role is to maintain relationships with local and state government officials and staff, and business and community leaders. The manager is also responsible for responding to customer issues referred by governmental officials.
- ◆ Gulf meets with governmental entities for all major projects, as appropriate, to discuss the scope of the projects and coordinate activities involved with project implementation. Gulf maintains year-round contact with city and county officials to ensure cooperation in planning, good communications, and coordination of activities. In 2018, Gulf participated in hurricane drills, EOC training, and statewide exercises. Gulf assigns employees to county EOCs throughout Northwest Florida to assist during emergencies. Gulf also conducts a storm drill each year. In 2018, Gulf’s service area was severely impacted by Hurricane Michael. Gulf activated its Storm Center on October 9, 2018, and remained activated until December 21, 2018. Gulf reported that major restoration activities were completed in 13 days, with power restored to 99 percent of its customers. Gulf’s EOC representatives facilitated all types of information and communications with local officials and at times were involved in other community support areas.
- ◆ TECO’s communication efforts, in 2018, focused on maintaining existing vital governmental contacts and continued participation on standing disaster recovery planning committees. TECO participated in joint storm workshops, training involving governmental officials and exercises with Hillsborough, Polk, and Pinellas Counties and municipal agencies. TECO continues to work with local, state, and federal governments to streamline the flow of information to help efforts to restore all service as quickly as possible. Hurricane Michael and Tropical Storm Alberto triggered several county and municipal agencies to activate their EOCs. The local EOCs in TECO’s service area were under partial activation to support potential sandbag operations and shelter management. TECO participated in full activation of the State EOC during Tropical Storm Alberto and Hurricane Michael.

Initiative 9 - Collaborative Research on Effects of Hurricane Winds and Storm Surge

PURC assisted Florida's electric utilities by coordinating a three-year research effort, from 2006 to 2009, in the area of hardening the electric infrastructure to better withstand and recover from hurricanes. Hurricane winds, undergrounding, and vegetation management research are key areas explored in these efforts by all of the research sponsors involved with PURC. Since that time, PURC compiles a research report every year and provides the utilities with results from its research. The latest report was issued February 2019.

Current projects in this effort include: (1) research on undergrounding existing electric distribution facilities by surveying the current literature including case analyses of Florida underground projects, and developing a model for projecting the benefits and costs of converting overhead facilities to underground; (2) data gathering and analysis of hurricane winds in Florida and the possible expansion of a hurricane simulator that can be used to test hardening approaches; and (3) an initiative to increase public outreach to address storm preparedness in the wake of Hurricane Sandy. This included reaching out to affected states for further data and a print debate surrounding overhead vs. underground installation of power lines.

The effort is the result of FPSC Order No. PSC-06-0351-PAA-EI, issued April 25, 2006, in Docket No. 20060198-EI, directing each investor-owned electric utility to establish a plan that increases collaborative research to further the development of storm resilient electric utility infrastructure and technologies that reduce storm restoration costs and outages to customers. The order directed the IOUs to solicit participation from municipal electric utilities and rural electric cooperatives in addition to available educational and research organizations.

The IOUs joined with the municipal electric utilities and rural electric cooperatives in the state (collectively referred to as the Project Sponsors) to form a steering committee of representatives from each utility and entered into a Memorandum of Understanding (MOU) with PURC. In serving as the research coordinator for the project outlined by the MOU, PURC manages the workflow and communications, develops work plans, serves as a subject matter expert and conducts research, facilitates the hiring of experts, coordinates with research vendors, advise the project sponsors, and provides reports for project activities.

Undergrounding Of Electric Utility Infrastructure: All five IOUs participate with PURC, along with the other cooperative and municipal electric utilities, to perform beneficial research regarding hurricane winds and storm surge within the State. The group's research shows that while underground systems on average have fewer outages than overhead systems, they can at times take longer to repair. Analyses of hurricane damage in Florida found that underground systems might be particularly susceptible to storm surge. The research on undergrounding has been the focus for understanding the economics and effects of hardening strategies, including undergrounding. As a result, Quanta Technologies was contracted to conduct a three-phase project to understand the economics and effect of hardening policies in order to make informed decisions regarding hardening of underground facilities.

Phase I of the project was a meta-analysis of existing research, reports, methodologies, and case studies. Phase II examined specific undergrounding project case studies in Florida and included an evaluation of relevant case studies from other hurricane prone states and other parts of the

world. Phase III developed a methodology to identify and evaluate the costs and benefits of undergrounding specific facilities in Florida. The primary focus is the impact of undergrounding on hurricane performance. This study also considered benefits and drawbacks of undergrounding during non-hurricane conditions. The collaborative refined the computer model developed by Quanta Technologies. The reports for Phase I, Phase II, and Phase III are available at <http://warrington.ufl.edu/purc/research/energy.asp>.

The collaborative has refined the computer model and there has been a collective effort to learn more about the functionality of the computer code. PURC and the utilities have worked to fill information gaps for model inputs; however, there are still information gaps. These gaps include company specific storm related information, such as, specific equipment damage and associated restoration times and costs. There have also been significant investments and efforts in the area of forensic data collection, which includes the utilities' responses and plans to meet the FPSC's storm preparedness initiative.

PURC has worked with doctoral and master's candidates at the University of Florida to assess the inter-relationships between wind speed and other environmental factors on utility damage. PURC was contacted by the University of Wisconsin and North Carolina State University, who showed interest in the model, but no additional relationships have been established. The Government of Puerto Rico contacted PURC regarding strategies to make Puerto Rico's system more resilient and they expressed interest in the role that the model could play. PURC was also contacted by California stakeholders who are interested in applying the principles of the model toward efforts in the prevention of wildfires. The researchers that contacted PURC cite the model as the only non-proprietary model of its kind.

Hurricane Wind Effects: The collaborative group is trying to determine the appropriate level of hardening required for the electric utility infrastructure against wind damage from hurricanes. The project's focus was divided into two categories: (1) accurate characterization of severe dynamic wind loading; and (2) understanding the likely failure modes for different wind conditions. An agreement with WeatherFlow, Inc., to study the effects of dynamic wind conditions upon hurricane landfall includes 50 permanent wind-monitoring stations around the coast of Florida. This agreement expired in 2012; however, it was renewed in April 2017 and will automatically renew annually on the effective date for an additional one-year period, unless terminated by the parties to the agreement.

Public Outreach: PURC researchers continue to discuss the collaborative effort in Florida with the engineering departments of the state regulators in Connecticut, New York, and New Jersey, Pennsylvania, and regulators in Jamaica, Grenada, Curacao, Samoa, and the Philippines. Puerto Rico and California showed interested in 2018. The regulators and policymakers showed interest in the collaborative effort and its results, but have shown no further interest in participating in the research effort. The media in California showed considerable interest in Florida's storm hardening efforts to apply toward wildfire prevention standards.

Initiative 10 - A Natural Disaster Preparedness and Recovery Program

Each IOU is required to maintain a copy of its current formal disaster preparedness and recovery plan with the Commission. A formal disaster plan provides an effective means to document lessons learned, improve disaster recovery training, pre-storm staging activities and post-storm recovery, collect facility performance data, and improve forensic analysis. In addition, participation in the Commission's annual pre-storm preparedness briefing is required which focuses on the extent to which all Florida electric utilities are prepared for potential hurricane events. The following are some 2018 highlights for each IOU.

- ◆ DEF's Storm Recovery Plan is reviewed and updated annually based on lessons learned from the previous storm season and organizational needs. The Distribution System Storm Operational Plan and the Transmission Storm Plan incorporates organizational redesign at DEF, internal feedback, suggestions, and customer survey responses. DEF uses the Extreme Wind Loading standards in accordance with the NESC, Rule 250C in all planning for transmission upgrades, rebuilds and expansions of existing facilities.
- ◆ FPL's Storm Emergency Plan identifies emergency conditions associated with natural disasters and responsibilities and duties of FPL's Emergency Response Organization. The plan provides a summary of overall emergency process, systems, accounting, safe work practices, etc. The plan also provides information on the Emergency Response Organization conducting damage assessment, restoration response, supporting organizations for external agency support, such as regulatory bodies, EOC's, local governments, etc., and support to major commercial and industrial customers. The plan is reviewed annually and revised as necessary.
- ◆ FPUC utilizes its Disaster Preparedness and Recovery Plan to prepare for storms annually and will ensure all employees are aware of their responsibilities. The objectives included in the plan to ensure orderly and efficient service restoration are: the safety of employees, contractors, and the general public; early damage assessment in order to develop manpower requirements; request additional manpower as soon as conditions and information indicate the need; provide for orderly restoration activities; provide all logistical needs for employees and contractors; provide ongoing preparation of FPUC's employee buildings, equipment and support functions; and provide support and additional resources for employees and their families. The plan was updated in 2018 and included: the organization chart to reflect employee changes.
- ◆ Gulf's 2019 Storm Restoration Procedures Manual is currently being revised and reviewed and all changes will be incorporated by August 2019. Gulf continues to provide annual refresher training in the area of storm preparedness for various storm roles at minimal cost. A mock hurricane drill was completed on April 22, 2019. The drill involved testing the readiness to deal with an unexpected event during a restoration effort. Gulf uses the strategy described in its Storm Restoration Procedures Manual to respond to any natural disaster that may occur. Annually, Gulf develops and refines its planning and preparations for the possibility of a natural disaster. Gulf's restoration procedures establish a plan of action to be utilized for the operation and restoration of generation, transmission, and distribution facilities during major disasters.

- ◆ TECO's Emergency Management Plans address all hazards, including extreme weather events. TECO continues to use the policy labeled Emergency Management and Business Continuity. This policy delineates the responsibility at employee, company, and community levels. TECO continues to participate in internal and external preparedness exercises, collaborating with government emergency management agencies, at local, state and federal levels. Prior to June 1, 2018, all emergency support functions were reviewed, personnel trained, and Incident Command System Logistics and Planning Section Plans were tested. TECO continues to participate in internal and external preparedness exercises, and collaborates with local, state, and federal government emergency management agencies. During the State's mock hurricane exercise, TECO confirmed its response and communications plans.

Section II: Actual Distribution Service Reliability

Electric utility customers are affected by all outage and momentary events, regardless of where problems originate. For example, generation events and transmission events, while remote from the distribution system serving a customer, affect the distribution service experience. Actual reliability data is the accumulation of these events.

The actual reliability data includes two subsets of outage data: (1) data on excludable events; and (2) data pertaining to normal day-to-day activities. Rule 25-6.0455(4), F.A.C., explicitly lists outage events that may be excluded:

- ◆ Planned service interruptions.
- ◆ A storm named by the National Weather Service.
- ◆ A tornado recorded by the National Weather Service.
- ◆ Ice on lines.
- ◆ A planned load management event.
- ◆ Any electric generation or transmission event not governed by subsection Rule 25-6.018(2) and (3) F.A.C.
- ◆ An extreme weather or fire event causing activation of the county emergency operation center.

This section provides an overview of each IOU's actual 2018 performance data and focuses on the exclusions allowed by the rule.

Duke Energy Florida, LLC: Actual Data

Table 2-1 provides an overview of key DEF metrics: Customer Minutes of Interruption (CMI) and Customer Interruptions (CI) for 2018. Excludable outage events accounted for approximately 56 percent of the minutes of interruption experienced by DEF's customers. In 2018, DEF experienced a tornado that impacted its service area on November 2, 2018, Tropical Storm Alberto on May 26-29, 2018, Tropical Storm Gordon on September 3, 2018, and Hurricane Michael on October 9-18, 2018.

The biggest impact on CMI were the "Named Storm" events, which accounted for approximately 45 percent of the excludable minutes of interruptions. DEF stated that the transmission events accounted for 5 percent of the minutes of interruptions. DEF asserted that the initiating causes varied from equipment failures to weather, but were predominantly weather causes. The sustained causes also varied from major storm weather to equipment failure.

Table 2-1
DEF's 2018 Customer Minutes of Interruptions and Customer Interruptions

2018	Customer Minutes of Interruption (CMI)		Customer Interruptions (CI)	
	Value	% of Actual	Value	% of Actual
Reported Actual Data	406,079,802		2,767,634	
Documented Exclusions				
Planned Service Interruptions	18,347,537	4.52%	425,870	15.39%
Named Storms	184,032,388	45.32%	123,609	4.47%
Tornadoes	5,744,317	1.41%	46,403	1.68%
Ice on Lines		0.00%		0.00%
Planned Load Management Events		0.00%		0.00%
Generation/Transmission Events	21,087,208	5.19%	354,051	12.79%
Extreme Weather (EOC Activation/Fire)		0.00%		0.00%
Reported Adjusted Data	176,868,352	43.56%	1,817,701	65.68%

Source: DEF's 2018 distribution service reliability report.

Florida Power & Light Company: Actual Data

Table 2-2 provides an overview of FPL's CMI and CI figures for 2018. Excludable outage events accounted for approximately 15 percent of the minutes of interruption experienced by FPL's customers. FPL reported six tornadoes, ice on the lines, Tropical Storm Alberto, Tropical Storms Gordon, and Hurricane Michael in 2018. FPL stated that even though Tropical Storm Alberto, Tropical Storm Gordon, and Hurricane Michael did not make landfall in its service territory, all of FPL's territories were impacted. Tropical Storm Alberto impacted FPL's service territories on May 25-28, 2018, Tropical Storm Gordon on September 3, 2018, and Hurricane Michael on October 9-11, 2018. The ice on lines impacted the North Florida region on January 3-4, 2018. The tornadoes affected the following regions:

- ◆ Central Broward, South Broward, Boca Raton, and West Palm Beach regions on April 10, 2018
- ◆ North Broward region on April 27, 2018
- ◆ West Palm Beach, Treasure Coast, and Brevard regions on May 14, 2018
- ◆ West Palm Beach region on July 5, 2018
- ◆ Central Florida region on July 25, 2018
- ◆ Toledo Blade region on December 20, 2018

The biggest impact on CMI was the "Planned Service Interruptions" events, which accounted for approximately 7.51 percent of the minutes of interruption. FPL explained that a "Planned Service Interruption" is when customers request interruptions due to upgrades or maintenance to the electrical panel at their residence/business or when FPL is planning system upgrades and maintenance. FPL reported that it will continue to evaluate the need for planned outages and customer-requested outages to determine if there are alternative work methods that could minimize or prevent such outages. If an outage is not preventable, FPL will work with its customers to schedule "Planned Service Interruptions" during times that are more convenient for them. However, while FPL can execute much of its work, such as system upgrades and maintenance, without requiring an interruption, there are instances when an interruption cannot be avoided due to safety and/or the nature of the work being performed.

Table 2-2
FPL's 2018 Customer Minutes of Interruptions and Customer Interruptions

2018	Customer Minutes of Interruption (CMI)		Customer Interruptions (CI)	
	Value	% of Actual	Value	% of Actual
Reported Actual Data (1)	310,040,900		4,991,299	
Documented Exclusions				
Planned Service Interruptions	23,291,759	7.51%	290,152	5.81%
Named Storms	7,775,135	2.51%	49015	0.98%
Tornadoes	6,328,802	2.04%	89052	1.78%
Ice on Lines	7,802,699	2.52%	80,758	1.62%
Planned Load Management Events	0	0.00%	0	0.00%
Generation/Transmission Events (2)	8,152,024	2.63%	627,171	12.57%
Extreme Weather (EOC Activation/Fire)	0	0.00%	0	0.00%
Reported Adjusted Data	264,842,505	85.42%	4,482,322	89.80%

Source: FPL's 2018 distribution service reliability report.

Notes: (1) Excludes Generation/Transmission Events per Rule 25-6.0455(2), .F.A.C.; and (2) Information Only, as reported actual data already excludes Generation/Transmission Events.

Florida Public Utilities Company: Actual Data

Table 2-3 provides an overview of FPUC's CMI and CI figures for 2018. Excludable outage events accounted for approximately 99 percent of the minutes of interruption experienced by FPUC's customers. The biggest impact on CMI was the "Named Storms" events, which accounted for approximately 98.9 percent of the minutes of interruption. FPUC reported that neither the Northeast nor the Northwest divisions were impacted by tornadoes during 2018. FPUC reported that the following weather events impacted its service areas: Tropical Storm Alberto on May 27-29, 2018, Tropical Storm Gordon on September 1-5, 2018, and Hurricane Michael on October 10 through December 31, 2018, affected the Northwest division. There were no extreme weather events that affected the Northeast division.

FPUC reported the Northeast division experienced a major transmission event on May 19, 2018 due to an arrestor failure. The Northwest division experienced one substation event on June 5, 2018 due to failure of a circuit breaker which caused power interruption between FPUC and Gulf. Both divisions had several planned outages that allowed FPUC to perform maintenance to different sections of the distribution system.

Table 2-3
FPUC's 2018 Customer Minutes of Interruptions and Customer Interruptions

2018	Customer Minutes of Interruption (CMI)		Customer Interruptions (CI)	
	Value	% of Actual	Value	% of Actual
Reported Actual Data	443,351,451		107,419	
Documented Exclusions				
Planned Service Interruptions	101,832	0.02%	5,588	5.20%
Named Storms	438,589,687	98.93%	55,950	52.09%
Tornadoes	0	0.00%	0	0.00%
Ice on Lines	0	0.00%	0	0.00%
Planned Load Management Events	0	0.00%	0	0.00%
Generation/Transmission Events	316,807	0.07%	5,150	4.79%
Extreme Weather (EOC Activation/Fire)	0	0.00%	0	0.00%
Reported Adjusted Data	4,343,125	0.98%	40,731	37.92%

Source: FPUC's 2018 distribution service reliability report.

Gulf Power Company: Actual Data

Table 2-4 provides an overview of Gulf’s CMI and CI figures for 2018. Excludable outage events accounted for approximately 97 percent of the minutes of interruption experienced by Gulf’s customers. The biggest impact on CMI was “Named Storms,” which accounted for approximately 96 percent of the minutes of interruption. Tropical Storm Alberto on May 27, 2018, Tropical Storm Gordon on September 4, 2018, and Hurricane Michael on October 10, 2018, affected all three regions of Gulf’s service area. Gulf reported four tornadoes, which accounted for approximately 0.05 percent of the minutes of interruption. The tornadoes affected the following regions:

- ◆ Eastern region on February 11, 2018, April 15, 2018, and August 2, 2018
- ◆ Central region on April 22, 2018
- ◆ Western region on April 22, 2018

Table 2-4
Gulf’s 2018 Customer Minutes of Interruption and Customer Interruptions

2018	Customer Minutes of Interruption (CMI)		Customer Interruptions (CI)	
	Value	% of Actual	Value	% of Actual
Reported Actual Data	1,309,157,347		1,289,638	
Documented Exclusions				
Planned Service Interruptions	5,546,310	0.42%	74,334	5.76%
Named Storms	1,256,062,620	95.94%	548,184	42.51%
Tornadoes	666,047	0.05%	6,439	0.50%
Ice on Lines		0.00%		0.00%
Planned Load Management Events		0.00%		0.00%
Generation/Transmission Events	2,056,881	0.16%	78,851	6.11%
Extreme Weather (EOC Activation/Fire)		0.00%		0.00%
Reported Adjusted Data	44,825,489	3.42%	581,830	45.12%

Source: Gulf’s 2018 distribution service reliability report.

Tampa Electric Company: Actual Data

Table 2-5 provides an overview of TECO’s CMI and CI figures for 2018. Excludable outage events accounted for approximately 21 percent of the minutes of interruption experienced by TECO’s customers. There were no extreme weather events that affected TECO’s service areas during 2018.

The Generation/Transmission events accounted for approximately 10 percent of the minutes of interruption. TECO reported 8 transmission outages in 2018. The causes listed included equipment failure, vehicle collision, animals, and other circumstances. TECO reported that all equipment failures were repaired, structures replaced, overgrown vegetation were trimmed, and poles were repaired. In addition, “Planned Service Interruptions” accounted for approximately 11 percent of the minutes of interruptions. TECO reported that when working “Planned Service Interruptions,” the affected system is temporarily de-energized to safely complete work that has been requested by customers for various reasons.

Table 2-5
TECO’s 2018 Customer Minutes of Interruptions and Customer Interruptions

2018	Customer Minutes of Interruption (CMI)		Customer Interruptions (CI)	
	Value	% of Actual	Value	% of Actual
Reported Actual Data	92,805,642		1,398,802	
Documented Exclusions				
Planned Service Interruptions	9,895,225	10.66%	234,069	16.73%
Named Storms	0	0.00%	0	0.00%
Tornadoes	0	0.00%	0	0.00%
Ice on Lines	0	0.00%	0	0.00%
Planned Load Management Events	0	0.00%	0	0.00%
Generation/Transmission Events	9,505,418	10.24%	250,764	17.93%
Extreme Weather (EOC Activation/Fire)	0	0.00%	0	0.00%
Reported Adjusted Data	73,404,999	79.10%	913,969	65.34%

Source: TECO’s 2018 distribution service reliability report.

Section III: Adjusted Distribution Service Reliability Review of Individual Utilities


The adjusted distribution reliability metrics or indices provide insight into potential trends in a utility's daily practices and maintenance of its distribution facilities. This section of the review is based on each utility's reported adjusted data.

Duke Energy Florida, LLC: Adjusted Data

Figure 3-1 charts the adjusted SAIDI recorded across DEF's system and depicts increases in the lowest, the average, and highest values for 2018. DEF reported that 2018 presented the Utility with a major storm affecting the panhandle and resulting in significant damage to infrastructure. DEF notes that there were 10 days in 2018 that had weather-related outages from afternoon thunderstorms, which caused more than 50 percent of customer outages on those days. In addition, there were two days in 2018 that resulted in equipment failure adding to its SAIDI minutes.

DEF's service territory is comprised of four regions: North Coastal, South Coastal, North Central, and South Central. **Figure 3-1** illustrates that the North Coastal region continues to report the poorest SAIDI over the last five years, fluctuating between 145 minutes and 168 minutes. While the South Coastal and South Central regions have the best or lowest SAIDI for the same period. The North Coastal region is predominantly a rural area and has more square miles when compared to the other regions. This region is also served by predominantly long circuits with approximately 7,700 miles of overhead and underground main circuits. DEF explained that these factors result in higher exposure to outage causes and higher reliability indices.

**Figure 3-1
SAIDI across DEF's Four Regions (Adjusted)**




**DEF's Regions with the Highest and Lowest Adjusted SAIDI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest SAIDI	North Coastal	North Coastal	North Coastal	North Coastal	North Coastal
Lowest SAIDI	South Coastal	South Central	South Coastal	South Central	South Central

Source: DEF's 2014-2018 distribution service reliability reports.

Figure 3-2 shows the adjusted SAIFI across DEF’s system. The minimum, maximum, and average SAIFI indexes are trending downward even though there were increases in 2018. The increases were 11 percent for the minimum value, 10 percent for the average value, and 5 percent for the maximum value. The South Central region had the lowest number of interruptions, while the North Coastal region continues to have the highest number of interruptions.

**Figure 3-2
SAIFI across DEF’s Four Regions (Adjusted)**




**DEF's Regions with the Highest and Lowest Adjusted SAIFI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest SAIFI	North Coastal	North Coastal	North Coastal	North Coastal	North Coastal
Lowest SAIFI	South Coastal	North Central	South Coastal	South Central	South Central

Source: DEF’s 2014-2018 distribution service reliability reports.

Figure 3-3 illustrates the CAIDI, or the average number of minutes a customer is without power when a service interruption occurs, for DEF's four regions. DEF's adjusted CAIDI is increasing for a five-year period from 78 minutes in 2014 to 97 minutes in 2018. The North Coastal region has continued to have the highest CAIDI level for the past five years with the maximum CAIDI trending upward. The South Central region had the lowest CAIDI level during the same period with the minimum CAIDI trending upward.

**Figure 3-3
CAIDI across DEF's Four Regions (Adjusted)**




**DEF's Regions with the Highest and Lowest Adjusted CAIDI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest CAIDI	North Coastal	North Coastal	North Coastal	North Coastal	North Coastal
Lowest CAIDI	South Coastal	South Coastal	South Central	South Central	South Central

Source: DEF's 2014-2018 distribution service reliability reports.

Figure 3-4 is the average length of time DEF spends restoring customers affected by outage events, excluding hurricanes and certain other outage events. This is displayed by the index L-Bar in the graph below. The data demonstrates an overall 11 percent increase of outage durations since 2014, and a 1.4 percent increase from 2017 to 2018. DEF's overall L-Bar index is trending upward, indicating that DEF is spending more time restoring service from outage events.


Figure 3-4
DEF's Average Duration of Outages (Adjusted)



Source: DEF's 2014-2018 distribution service reliability reports.

Figure 3-5 illustrates the frequency of momentary events on primary circuits for DEF's customers recorded across its system. These momentary events often affect a small group of customers. A review of the supporting data suggests that the MAIFle results between 2014 and 2018 appear to be trending downward showing improvement even though there was an increase in the average MAIFle of 35 percent from 2017 to 2018. All four regions appear to fluctuate between having the best (lowest) results to having the worst (highest) results. There was a 47 percent decrease for the lowest MAIFle from 2017 to 2018 and there was a 66 percent increase from 2017 to 2018.

**Figure 3-5
MAIFle across DEF's Four Regions (Adjusted)**




**DEF's Regions with the Highest and Lowest Adjusted MAIFle Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest MAIFle	North Central	South Coastal	North Central	North Coastal	North Coastal
Lowest MAIFle	North Coastal	North Coastal	South Central	South Coastal	North Central

Source: DEF's 2014-2018 distribution service reliability reports.

Figure 3-6 charts the percentage of DEF’s customers experiencing more than five interruptions over the last five years. DEF reported an increase in the average CEMI5 performance from 0.7 percent in 2017 to 1.0 percent in 2018. The average CEMI5 is trending downward over the past five years. The North Central region has the lowest reported percentage for all of DEF’s regions and the North Coastal region continues to have the highest reported percentage.

**Figure 3-6
CEMI5 across DEF’s Four Regions (Adjusted)**



**DEF's Regions with the Highest and Lowest Adjusted CEMI5 Distribution Reliability
Performance by Year**


	2014	2015	2016	2017	2018
Highest CEMI5	North Coastal	North Coastal	North Coastal	North Coastal	North Coastal
Lowest CEMI5	South Central	North Central	North Central	South Coastal	North Central

Source: DEF’s 2014-2018 distribution service reliability reports.

Figure 3-7 shows the fraction of multiple occurrences of feeders using a three-year and five-year basis. During the period of 2014 to 2018, the five-year fraction of multiple occurrences is trending upward as the three-year fraction of multiple occurrences is trending downward. The Three Percent Feeder Report lists the top 3 percent of feeders with the most feeder outage events. The fraction of multiple occurrences is calculated from the number of recurrences divided by the number of feeders reported.

Four of DEF's feeders have been on the Three Percent Feeder Report for the last two years consecutively. The outages varied from equipment failure, a pole that burnt in half, vehicular accident, vegetation, and thunderstorms. DEF replaced the failing equipment, trimmed trees, and performed infrared scans on the feeders. All issues found during the infrared scans were corrected. All four feeders have projects planned to improve reliability. The projects range from replacing wooden poles with fiberglass poles (in heavy woodpecker population areas) to storm hardening projects such as DEF's Deteriorated Conductor Program and Transformer Retrofit Program.

Figure 3-7
DEF's Three Percent Feeder Report (Adjusted)




Source: DEF's 2014-2018 distribution service reliability reports.

Figure 3-8 shows the top five causes of outage events on DEF’s distribution system normalized to a 10,000-customer base. The figure is based on DEF’s adjusted data and represents approximately 93 percent of the top 10 causes of outage events that occurred during 2018. For the five-year period, the top five causes of outage events were “Defective Equipment” (28 percent), “Vegetation” (20 percent), “Other Causes” (19 percent), “Other Weather” (15 percent), and “Animals” (11 percent) on a cumulative basis. The outage events caused by “Vegetation”, “Other Causes,” and “Other Weather” are trending downward even though the “Vegetation” category had a 5 percent increase, “Other Causes” category had a 0.3 percent increase and “Other Weather” category had an 18 percent increase in 2018. DEF reported that it prioritizes the reliability improvements action plan by balancing historical and current year performance. In addition, current year performance is monitored monthly to identify emergent and seasonal issues including load balancing for cold weather and the need for foot patrols of devices experiencing multiple interruptions.

To address outages related to “Defective Equipment,” DEF is continuing to invest in proactive system maintenance activities, such as pole replacements, padmounted transformer replacements, and underground cable replacements. In 2018, DEF continued investing in proactive switchgear replacements, overhead transformer retrofits, and other reliability programs.

Figure 3-8
DEF’s Top Five Outage Causes (Adjusted)



Source: DEF’s 2014-2018 distribution service reliability reports.

Observations: DEF's Adjusted Data

DEF's SAIFI, MAIFIe, CEMI5 and the Three-Year Percent of Multiple Feeder Outage Events are trending downward over the past five years. The SAIDI, CAIDI, L-Bar, and the Five-Year Percent of Multiple Feeder Outage Events are all trending upward over the five-year period. All of the reliability indices, except for the Five-Year Percent of Multiple Feeder Outage Events, had increases from 2017 to 2018. The results for the North Coastal Region have continually demonstrated the highest (poorest) service reliability indices of the four regions within DEF for the past five years. The North Coastal region is predominantly a rural area and has more square miles compared to DEF's other service territories.

DEF reported that 2018 presented the Utility with a major storm affecting the panhandle and resulting in significant damage to infrastructure. DEF also reported that there were 10 days that had weather-related outages from afternoon thunderstorms, which caused more than 50 percent of customer outages on those days. In addition, there were two days in 2018 that resulted in equipment failure adding to its SAIDI minutes.

In 2018, DEF continued work, as part of its Grid Investment Plan, targeting the North Coastal region. The following are the planned projects:

- 8 feeders under the Transformer Retrofit Program
- 2 feeders under the Deteriorated Conductor Program
- 9 feeders under the Self-Optimizing Grid Program

The work under the Grid Investment Plan will continue in 2019 and 2020. In 2019, DEF plans the following programs for the North Coastal region:

- 15 feeders in the Transformer Retrofit Program
- 3 feeders in the Deteriorated Conductor Program
- 5 feeders in Live Front Switchgear Replacement Program
- 29 feeders in the Self Optimizing Grid Program

The following programs are planned to continue in 2020:

- 16 feeders under Transformer Retrofit Program
- 10 feeders under Deteriorated Conductor Program
- 5 feeders under Live Front Switchgear Replacement Program
- 18 feeders in the Self Optimizing Grid Program


DEF is also piloting a Tree Removal and Easement Execution (TREE) Program on a circuit in the North Coastal region, which is prone to vegetation outages from trees outside of the rights-of-way. The TREE Program works on acquiring easements near overhead facilities to allow DEF to remove and trim trees within the easement area to reduce vegetation related outages.

To help improve reliability to its customers, DEF has initiated a targeted undergrounding program. DEF reports the primary purpose of this program is to attempt to eliminate tree and debris related outages. The program is focused in heavily vegetated neighborhoods prone to power outages. The conversion of overhead laterals to underground facilities should decrease outages, reduce momentary interruptions, improve major storm restoration time, improve customer satisfaction, and reduce costs. In 2018, DEF completed 12 laterals projects converting 1.34 miles of overhead laterals to underground. In 2019, DEF is planning to complete 4 lateral projects converting 18 miles of overhead laterals to underground. DEF explained that the selection of an underground lateral project is based on 10 years of data and is focused on Events Per Mile (or Outages per Mile), not standard reliability indices. The 12 laterals that were completed in 2018 had Events per Mile ranging from 268.49 events to 31.82 events.

Florida Power & Light Company: Adjusted Data

Figure 3-9 shows the highest, average, and lowest adjusted SAIDI recorded across FPL's system that encompasses four management regions with 16 service areas. The highest and lowest SAIDI values are the values reported for a particular service area. FPL had an overall decrease of 1 minute (2 percent) to its average SAIDI results for 2018 compared to 2017. The average SAIDI appears to be trending downward over the five-year period of 2014 to 2018. The Pompano region, which is also the North Broward region, has the best SAIDI results for two out of the five years. FPL changed the names of three regions to be consistent with the other FPL regions. Pompano became North Broward, Wingate became Central Broward, and Gulf Stream became South Broward.

**Figure 3-9
SAIDI across FPL's Sixteen Regions (Adjusted)**




**FPL's Regions with the Highest and Lowest Adjusted SAIDI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest SAIDI	North Dade	South Dade	Treasure Coast	Toledo Blade	North Florida
Lowest SAIDI	West Palm	Central Dade	Central Dade	Pompano	North Broward

Source: FPL's 2014-2018 distribution service reliability reports.

Figure 3-10 is a chart of the highest, average, and lowest adjusted SAIFI across FPL's system. FPL had a decrease in the system average results to 0.89 outages in 2018, compared to 0.90 outages in 2017, which is a 1 percent decrease. FPL reported an increase in the highest SAIFI of 1.25 interruptions in 2018 compared to 1.12 interruptions in 2017. The region reporting the lowest adjusted SAIFI for 2018 was North Broward at 0.66 interruptions compared to 0.65 interruptions in the same region in 2017. The highest, average, and lowest SAIFI appear to be trending downward during the period of 2014 to 2018.

Figure 3-10
SAIFI across FPL's Sixteen regions (Adjusted)




FPL's Regions with the Highest and Lowest Adjusted SAIFI Distribution Reliability
Performance by Year

	2014	2015	2016	2017	2018
Highest SAIFI	Wingate	West Dade	Treasure Coast	Toledo Blade	North Florida
Lowest SAIFI	Central Dade	Central Dade	Central Dade	Pompano	North Broward

Source: FPL's 2014-2018 distribution service reliability reports.

Figure 3-11 depicts FPL’s highest, average, and lowest CAIDI expressed in minutes. FPL’s adjusted average CAIDI did not decrease or increase and remained at 60 minutes for both 2017 and 2018. The average duration of CAIDI is trending downward. For 2018, the West Palm service area reported the lowest duration of CAIDI at 48 minutes. The highest duration of CAIDI was 74 minutes for the North Dade service area for 2018, which is a decrease from the recorded 80 minutes in 2017.

Figure 3-11
CAIDI across FPL’s Sixteen Regions (Adjusted)




FPL's Regions with the Highest and Lowest Adjusted CAIDI Distribution Reliability
Performance by Year

	2014	2015	2016	2017	2018
Highest CAIDI	North Dade	North Dade	North Dade	South Dade	North Dade
Lowest CAIDI	Boca Raton	Boca Raton	Boca Raton	West Palm	West Palm

Source: FPL’s 2014-2018 distribution service reliability reports.

Figure 3-12 depicts the average length of time that FPL spends recovering from outage events, excluding hurricanes and other extreme outage events and is the index known as L-Bar (Average Service Restoration Time). FPL had a 3 percent increase in L-Bar from 193 minutes in 2017 to 199 minutes in 2018. There is a 19.8 percent overall increase since 2014 and the L-Bar is trending upward, indicating FPL is spending more time restoring service to the last customer for that given outage.


Figure 3-12
FPL's Average Duration of Outages (Adjusted)



Source: FPL's 2014-2018 distribution service reliability reports.

Figure 3-13 is the highest, average, and lowest adjusted MAIFle recorded across FPL's system. FPL's Wingate and Toledo Blade service areas have experienced the least reliable MAIFle results of the 16 service areas of FPL since 2014. The Pompano, Central Dade, and Manasota service areas had the fewest momentary events since 2014. The results have been trending downward (improving) over the last five years. There is a 7 percent decrease in the average MAIFle results from 2017 to 2018. As a note, FPL calculates MAIFle differently. Specifically, if a feeder begins in one region and crosses another region, all customers on that feeder are impacted by the MAIFle event and are counted in the starting region. Therefore, the number of customers per region will be different.

Figure 3-13
MAIFle across FPL's Sixteen Regions (Adjusted)




**FPL's Regions with the Highest and Lowest Adjusted MAIFle Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest MAIFle	Wingate	Wingate	Wingate	Wingate	Toledo Blade
Lowest MAIFle	Pompano	Manasota	Pompano	Pompano	Central Dade

Source: FPL's 2014-2018 distribution service reliability reports.

Figure 3-14 shows the highest, average, and lowest adjusted CEMI5. FPL's customers with more than five interruptions per year appear to be slightly trending downward. The service areas experiencing the highest CEMI5 over the five-year period appear to fluctuate among West Dade, Treasure Coast, West Palm, and Toledo Blade. Pompano, South Broward (Gulf Stream), and Brevard are reported as having the lowest percentages in the last five years. The average CEMI5 result for 2018 was 0.6 percent compared to 0.8 percent in 2017.

**Figure 3-14
CEMI5 across FPL's Sixteen Regions (Adjusted)**



**FPL's Regions with the Highest and Lowest Adjusted CEMI5 Distribution Reliability
Performance by Year**


	2014	2015	2016	2017	2018
Highest CEMI5	West Palm	West Dade	Treasure Coast	West Palm	Toledo Blade
Lowest CEMI5	Brevard	Brevard	Gulf Stream	Pompano	South Broward

Source: FPL's 2014-2018 distribution service reliability reports.

Figure 3-15 is a graphical representation of the percentage of multiple occurrences of FPL's feeders and is derived from The Three Percent Feeder Report, which is a listing of the top three percent of problem feeders reported by the Utility. The fraction of multiple occurrences is calculated from the number of recurrences divided by the number of feeders reported. The three-year percentage had an increase to 13 percent in 2018 from 11 percent in 2017. The five-year percentage was 16 percent in 2017 and 2018. Both the five-year percentage and the three-year percentage appear to be trending upward.

Staff notes ten feeders were on the Three Percent Feeder Report the last two years. FPL reported that visual assessment follow-up work is scheduled for one feeder, five feeders will be hardened, automated feeder switches will be installed on three feeders, and vegetation trimming will occur on eight of the ten feeders. FPL also reported that in 2017 and 2018, over 325 miles of trimming was performed on these 10 feeders which have nearly 200 miles of overhead facilities.

Figure 3-15
FPL's Three Percent Feeder report (Adjusted)




Source: FPL's 2014-2018 distribution service reliability reports.

Figure 3-16 depicts the top five causes of outage events on FPL’s distribution system normalized to a 10,000-customer base. The graph is based on FPL’s adjusted data of the top 10 causes of outage events. For the five-year period, the five top causes of outage events included “Defective Equipment” (37 percent), “Vegetation” (17 percent), “Unknown Causes” (11 percent), “Other Causes” (11 percent), and “Animals” (10 percent) on a cumulative basis. The outage events due to “Vegetation” and “Unknown Causes” are trending downward as the “Defective Equipment” and “Animals” categories are trending slightly downward. The category “Other Causes” is slightly trending upward. The category “Defective Equipment” dominates the highest percentage of outage causes throughout the FPL regions even though there was a 4 percent decrease in the number of outages from 2017 to 2018.

Annually, FPL evaluates its current reliability remediation programs and verifies the program’s need and/or existence. In addition, FPL proposes new reliability remediation programs to improve its reliability performance concentrating on the highest cause codes and those cause codes that have shown trends needing attention. FPL has 16 reliability programs listed for its 2019 budget. The programs include: priority feeder inspection, reduce the number of direct buried feeder and lateral cables, installing, relocating, and maintaining distribution capacitor banks, and replacing oil circuit reclosers with electronic reclosers. Twelve programs are designed to help improve the “Defective Equipment” cause code. Five programs will help to improve the “Other Causes” cause codes, which had an increase in 2018.

Figure 3-16
FPL’s Top Five Outage Causes (Adjusted)



Source: FPL’s 2014-2018 distribution service reliability reports.

Observations: FPL's Adjusted Data

The least reliable overall results seem to fluctuate between FPL's different service areas, as do the best service reliability results. The 2018 report shows the system indices for SAIDI, SAIFI, CAIDI, MAIFe, and CEMI5 are lower or better than the 2017 results. The system index for L-Bar and the Three-Year Percentages of Multiple Feeder Outage events are higher than the 2017 results. There was no change in the Five-Year Percentages of Multiple Feeder Outage events results. FPL explains that it evaluates its current reliability programs annually to verify the program's need and/or existence. In addition, FPL proposes new reliability programs to improve its reliability performance concentrating on the highest cause codes and those cause codes that have shown trends needing attention. The cause codes that FPL will be concentrating on to improve are "Equipment Failures," "Unknown Causes," and "Other Causes" of outages. FPL is also continuing to increase the utilization of automation to address feeder interruptions.

The North Dade region has had the highest CAIDI for four years consecutively. The CAIDI value for the North Dade region increased by 3 percent in 2018. FPL stated that in 2018, in the North Dade region, more than 30 feeders were improved through various reliability initiatives, including priority feeder programs and overhead line inspections/repairs. In addition to installing 16 new automated feeder switches in North Dade in 2018, FPL completed follow-up work identified through visual assessments and/or thermovision including vegetation management, repair/replacement of feeder and lateral automated switches, insulators, splices, fuse switches, and jumpers.


As a result of lessons learned from Hurricanes Matthew and Irma, FPL initiated a three year Storm Secure Underground Program pilot. This Program targets certain overhead laterals, which were impacted by recent storms, and have a history of vegetation related outages and other reliability issues. While several projects were nearly complete at year-end 2018, the first lateral project was completed in early 2019. In 2019, FPL is planning to complete 152 lateral projects converting 60 miles of overhead laterals to underground. FPL has indicated that this three-year pilot Program will target less than 1 percent of its overall overhead laterals in its system. In addition, FPL reported that the increase in planned projects allows FPL to take advantage of experiences gained, incorporate lessons learned, and convert enough laterals to achieve a statistically valid sample. Since no laterals were completely converted in 2018, FPL is unable to provide any reliability data on its lateral projects. However, next year, FPL should be able to provide the reliability indices and/or the selection criteria utilized for all laterals converted in 2019.

Florida Public Utilities Company: Adjusted Data

FPUC has two electric divisions, the Northwest division, referred to as Marianna (NW) and the Northeast division, referred to as Fernandina Beach (NE). Each division's results is reported separately because the two divisions are 250 miles apart and not directly interconnected. Although the divisions may supply resources to support one another during emergencies, each division has diverse situations to contend with, making it difficult to compare the division's results and form a conclusion as to response and restoration time.

Figure 3-17 shows the highest, average, and lowest adjusted SAIDI values recorded by FPUC's system. The data shows the average SAIDI index is trending downward for the five-year period of 2014 to 2018 even though there was an 11 percent increase from 2017 to 2018.

Figure 3-17
SAIDI across FPUC's Two Regions (Adjusted)




**FPUC's Regions with the Highest and Lowest Adjusted SAIDI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest SAIDI	Marianna (NW)	Marianna (NW)	Marianna (NW)	Marianna (NW)	Marianna (NW)
Lowest SAIDI	Fernandina(NE)	Fernandina(NE)	Fernandina(NE)	Fernandina(NE)	Fernandina(NE)

Source: FPUC's 2014-2018 distribution service reliability reports.

Figure 3-18 shows the adjusted SAIFI across FPUC’s two divisions. The data depicts a 12 percent decrease in the 2018 average SAIFI reliability index from 2017. The data for the average and maximum SAIFI values are trending downward as the minimum SAIFI value is trending upward over the five-year period of 2014 to 2018.

Figure 3-18
SAIFI across FPUC’s Two Regions (Adjusted)




**FPUC's Regions with the Highest and Lowest Adjusted SAIFI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest SAIFI	Marianna (NW)	Marianna (NW)	Marianna (NW)	Marianna (NW)	Marianna (NW)
Lowest SAIFI	Fernandina(NE)	Fernandina(NE)	Fernandina(NE)	Fernandina(NE)	Fernandina(NE)

Source: FPUC’s 2014-2018 distribution service reliability reports.

Figure 3-19 shows the highest, average, and lowest adjusted CAIDI values across FPUC's system. FPUC's data shows the average CAIDI value increased by 26 percent for 2018 (107 minutes) when compared to 2017 (85 minutes). For the past five years, the maximum, the minimum, and the average CAIDI values are trending upward.

**Figure 3-19
CAIDI across FPUC's Two Regions (Adjusted)**




**FPUC's Regions with the Highest and Lowest Adjusted CAIDI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest CAIDI	Marianna (NW)	Fernandina(NE)	Marianna (NW)	Fernandina(NE)	Fernandina(NE)
Lowest CAIDI	Fernandina(NE)	Marianna (NW)	Fernandina(NE)	Marianna (NW)	Marianna (NW)

Source: FPUC's 2014-2018 distribution service reliability reports.

Figure 3-20 is the average length of time FPUC spends recovering from outage events (adjusted L-Bar). There was an 8 percent decrease in the L-Bar value from 2017 to 2018. The data for the five-year period of 2014 to 2018 suggests that the L-Bar index is trending downward indicating FPUC is taking less time to restore service after an outage event.


Figure 3-20
FPUC's Average Duration of Outages (Adjusted)



Source: FPUC's 2014-2018 distribution service reliability reports.

Figure 3-21 shows the top five causes of outage events on FPUC’s distribution system normalized to a 10,000-customer base. The figure is based on FPUC’s adjusted data of the top 10 causes of outages. For 2018, the top five causes of outage events were “Vegetation” (38 percent), “Animals” (18 percent), “Defective Equipment” (14 percent), “Lightning” (12 percent), and “Unknown” (6 percent). These five factors represent 88 percent of the total adjusted outage causes in 2018. The “Lightning” category is relatively flat even though there was a 66 percent increase from 2017 to 2018. The causes by “Defective Equipment,” “Unknown,” and “Vegetation” are also trending upward. “Defective Equipment” decreased 5 percent from 2017 to 2018. The “Unknown” and “Vegetation” category increased 11 percent and 19 percent during the same time period, respectively. The “Animals” category caused outages is trending downward over the five-year period of 2014 to 2018 and there was a 24 percent decrease from 2017 to 2018.

Figure 3-21
FPUC’s Top Five Outage Causes (Adjusted)



Source: FPUC’s 2014-2018 distribution service reliability reports.

FPUC filed a Three Percent Feeder Report listing the top 3 percent of feeders with the outage events for 2018. FPUC has so few feeders that the data in the report has not been statistically significant. There were two feeders on the Three Percent Feeder Report, one in each division. Neither of these feeders was listed on the report for the last five years.

Observations: FPUC's Adjusted Data

The SAIDI and CAIDI average indices have increased compared to 2017. For the five-year period of 2014 to 2018, the average indices for SAIDI, SAIFI, and L-Bar are trending downward as the CAIDI is trending upward. FPUC reported that it continues to invest in its storm hardening initiatives, infrastructure improvements, and system upgrades in both divisions. FPUC believes this will generate reliability improvements in the future. The Utility reviewed its five-year reliability indicator trends, averages and outage causes, and determined the reliability indexes continue to be significantly influenced by weather.

To improve its reliability, in 2018, FPUC planned to implement a new lateral protection strategy by installing cutout-mounted recloser units. This program deploys TripSaver cutout mounted reclosers on the worst performing laterals over the last three years. The TripSaver recloser works the same as an electronic recloser but for a smaller number of customers. The reclosers offer protection to upstream customers by giving a utility the ability to isolate faults and shorten the outage time experienced by customers. However, this project was interrupted by Hurricane Michael. To date, FPUC has installed 50 units in its Northwest division and 12 units in its Northeast division.

In addition, to help mitigate the situation with vegetation caused outages, FPUC suggests that its vegetation management would be more efficient if it trimmed all of the laterals associated with the feeders at the same time. This would allow FPUC to keep the trim crews in the same general area instead of moving them to a different feeder or lateral. This vegetation management schedule has been started in several locations. To help mitigate the situation with animal caused outages, FPUC plans to continue to implement the standard practice of installing animal guards and covering riser wire between the cutout, arrester, and transformer. In addition, if metal brackets are in use, they will be replaced with fiberglass brackets to help control animal related outages. FPUC reported that the deployment of the TripSavers should also help with animal related outages. To further help improve reliability, FPUC is planning to implement a smart metering (AMI) system and an enhanced SCADA system within the next five years in both of its divisions.


FPUC does not have to report MAIFIE or CEMI5 because Rule 25-6.0455, F.A.C., waives the requirement. The cost for the information systems necessary to measure MAIFIE and CEMI5 has a higher impact on small utilities compared to large utilities on a per customer basis.

Gulf Power Company: Adjusted Data

Gulf's service area includes much of the Florida panhandle and covers approximately 7,550 square miles in eight Florida counties – Bay, Escambia, Holmes, Jackson, Okaloosa, Santa Rosa, Walton, and Washington. This geographic area is divided into three regions known as the Western, Central, and Eastern. The region distribution metrics and overall distribution system metrics are presented in the following figures.

Figure 3-22 illustrates Gulf's SAIDI minutes, or the interruption duration minutes on a system basis. The chart depicts a 16 percent decrease in the average SAIDI in Gulf's combined regions when compared to the 2017 results. Gulf's 2018 average performance was 97 minutes compared to 116 minutes in 2017. The highest SAIDI value for 2018 was the Eastern region as the Central region had the best or lowest SAIDI value. The maximum SAIDI index is trending downward, as the minimum and average SAIDI indices are trending upward.

Figure 3-22
SAIDI across Gulf's Three Regions (Adjusted)




**Gulf's Regions with the Highest and Lowest Adjusted SAIDI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest SAIDI	Central	Western	Western	Western	Eastern
Lowest SAIDI	Eastern	Eastern	Central	Eastern	Central

Source: Gulf's 2014-2018 distribution service reliability reports.

Figure 3-23 illustrates that Gulf's SAIFI had a 5 percent increase in 2018 when compared to 2017. The highest SAIFI value for the past five years has fluctuated between the three regions. The lowest values appear to fluctuate between the Central region and the Eastern region. The maximum, average, and minimum SAIFI values appear to be trending upward.

Figure 3-23
SAIFI across Gulf's Three Regions (Adjusted)




**Gulf's Regions with the Highest and Lowest Adjusted SAIFI Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest SAIFI	Central	Western	Eastern	Eastern	Western
Lowest SAIFI	Eastern	Central	Central	Central	Central

Source: Gulf's 2014-2018 distribution service reliability reports.

Figure 3-24 is Gulf's adjusted CAIDI. For 2018, the average CAIDI is 77 minutes and represents a 21 percent decrease from the 2017 value of 97 minutes. In 2018, the Central region continued to have the highest CAIDI value, as the Western region had the lowest CAIDI. Staff notes that the average, the maximum and the minimum CAIDI values are trending downward.

**Figure 3-24
CAIDI across Gulf's Three Regions (Adjusted)**



**Gulf's Regions with the Highest and Lowest Adjusted CAIDI Distribution Reliability
Performance by Year**


	2014	2015	2016	2017	2018
Highest CAIDI	Central	Central	Central	Central	Central
Lowest CAIDI	Western	Eastern	Eastern	Eastern	Western

Source: Gulf's 2014-2018 distribution service reliability reports.

Figure 3-25 illustrates Gulf's L-Bar or the average length of time Gulf spends recovering from outage events, excluding hurricanes and other allowable excluded outage events. Gulf's L-Bar showed a 7 percent decrease from 2017 to 2018. However, the data for the five-year period of 2014 to 2018 shows an upward trend.

Gulf reported that all three of its regions experienced outages due to four non-excludable severe thunderstorms. These severe thunderstorms occurred on June 10, June 28, June 30, and December 1, 2018. During these events, a combined 554 outage events occurred. In addition, a hard freeze, that occurred on January 18, 2018, affected all three regions. A combined total of 59 outage events were a result of this hard freeze.


Figure 3-25
Gulf's Average Duration of Outages (Adjusted)



Source: Gulf's 2014-2018 distribution service reliability reports.

Figure 3-26 is the adjusted MAIFle recorded across Gulf’s system. The adjusted MAIFle results by region show that the Central region had the lowest frequency of momentary events on primary feeders. The Western region has the highest MAIFle index in 2018. The average MAIFle showed a 13 percent decrease when compared to 2017. The data suggest that the highest, average, and lowest MAIFle are all continuing to trend downward, suggesting improvement.

Figure 3-26
MAIFle across Gulf’s Three Regions (Adjusted)




Gulf’s Regions with the Highest and Lowest Adjusted MAIFle Distribution Reliability
Performance by Year

	2014	2015	2016	2017	2018
Highest MAIFle	Central	Western	Western	Western	Western
Lowest MAIFle	Eastern	Eastern	Central	Central	Central

Source: Gulf’s 2014-2018 distribution service reliability reports.

Figure 3-27 shows the highest, average, and lowest adjusted CEMI5 across Gulf's Western, Central, and Eastern regions. Gulf's 2018 results illustrate an 88 percent increase in the average CEMI5 percentage when compared to 2017. The maximum, average, and minimum CEMI5 all appear to be trending upward over the five-year period of 2014 to 2018.

Figure 3-27
CEMI5 across Gulf's Three Regions (Adjusted)



Gulf's Regions with the Highest and Lowest Adjusted CEMI5 Distribution Reliability Performance by Year


	2014	2015	2016	2017	2018
Highest CEMI5	Eastern	Eastern	Eastern	Central	Eastern
Lowest CEMI5	Western	Central	Central	Western	Central

Source: Gulf's 2014-2018 distribution service reliability reports.

Figure 3-28 shows the multiple occurrences of feeders using the Utility's Three Percent Feeder Report and is analyzed on a three- and five-year basis. The Three Percent Feeder Report is a listing of the top 3 percent of feeders that have the most feeder outage events. The supporting data illustrates that the five-year multiple occurrences decreased by 33 percent from 2017 to 2018 as the three-year multiple occurrences increased. The five-year period of 2014 to 2018 indicates overall that the five-year index is trending downward, as the three-year multiple occurrences index is trending upward.

There were 10 feeders on the Three Percent Feeder Report. Gulf reported that the three top causes of the outages associated with the 10 feeders listed were defective equipment, lightning, and vegetation. Gulf has a program for addressing these feeder issues called the Outage Mitigation Program. This Program addresses the root cause of the outages and develops a work plan to replace and/or repair system devices and material to prevent future outages. Part of this Program includes visual and infrared feeder patrols of the system, analysis of outage and fault data, coordination studies, and vegetation trimming.


Figure 3-28
Gulf's Three Percent Feeder Report (Adjusted)



Source: Gulf's 2014-2018 distribution service reliability reports.

Figure 3-29 shows the top five causes of outage events on Gulf’s distribution system normalized to a 10,000-customer base. The figure is based on Gulf’s adjusted data of the top 10 causes of outage events and represents 90 percent of the total adjusted outage events that occurred during 2018. The top five causes of outage events were “Defective Equipment” (24 percent), “Vegetation” (23 percent), “Animals” (20 percent), “Lightning” (15 percent), and “Unknown Causes” (10 percent). The percentage of outages due to “Defective Equipment” was the highest cause of outages. The number of outage events due to “Defective Equipment” is trending upward even though there was a 7 percent decrease in 2018. The numbers of outage events due to “Animals”, “Vegetation,” and “Unknown Causes” are trending upward. The number of outages due to “Lightning” is trending downward. Gulf continues to focus its process improvement efforts on the system wide top outage causes through its existing programs and storm hardening efforts.

Figure 3-29
Gulf’s Top Five Outage Causes (Adjusted)



Source: Gulf’s 2014-2018 distribution service reliability reports.

Observations: Gulf's Adjusted Data


There were improvements seen in Gulf's SAIDI, SAIFI, CAIDI, MAIFe, L-Bar, and the Five-Year Percentages of Multiple Feeder Outage events indices in 2018 as the CEMI5 and the Three-Year Percentages of Multiple Feeder Outage events declined. Overall it appears that the trend lines of the reliability indices for the five-year period of 2014 to 2018 are primarily trending upward.

Gulf continues to collect outage data at the customer meter level. The Utility reviews outage data and the resulting reliability indices at the system level and by its three regions. Gulf is analyzing 2018 data to determine the need for any specific improvement opportunities beyond the current programs and storm hardening initiatives. Gulf reported that it seeks opportunities to improve system reliability. Gulf continues to invest in additional smart switches and self-healing networks to reduce the customer impact of large outages, and it is incorporating additional switching points that should continue to improve the SAIFI and CEMI metrics.

Tampa Electric Company: Adjusted Data

Figure 3-30 shows the adjusted SAIDI values recorded by TECO's system. None of the seven TECO regions had improvements in SAIDI performance during 2018, with the Eastern region having the lowest SAIDI performance results. The Dade City region continues to have the poorest SAIDI performance results for the five-year period of 2014 to 2018. The lowest SAIDI index for the seven regions appears to be trending upward. The average SAIDI index increased 30 percent from 2017 to 2018. This index appears to also be trending upward. The Central, Eastern, and Winter Haven regions recorded the lowest SAIDI indices for the five-year period. Dade City, Plant City, and South Hillsborough regions have the fewest customers and represent the most rural, lowest customer density per line mile in comparison to the other four TECO divisions.

Figure 3-30
SAIDI across TECO's Seven Regions (Adjusted)




TECO's Regions with the Highest and Lowest Adjusted SAIDI Distribution Reliability Performance by Year

	2014	2015	2016	2017	2018
Highest SAIDI	Dade City	Dade City	Dade City	Dade City	Dade City
Lowest SAIDI	Central	Winter Haven	Central	Eastern	Eastern

Source: TECO's 2014-2018 distribution service reliability reports.

Figures 3-31 illustrates TECO's adjusted frequency of interruptions per customer reported by the system. TECO's data represent a 15 percent increase in the SAIFI average from 1.03 interruptions in 2017 to 1.18 interruptions in 2018. TECO's Dade City region continues to have the highest frequency of service interruptions when compared to TECO's other regions. The minimum and average SAIFI are trending upward while the maximum SAIFI is trending downward.

Figure 3-31
SAIFI across TECO's Seven Regions (Adjusted)




TECO's Regions with the Highest and Lowest Adjusted SAIFI Distribution Reliability
Performance by Year

	2014	2015	2016	2017	2018
Highest SAIFI	Dade City	Dade City	Dade City	Dade City	Dade City
Lowest SAIFI	Central	Western	Central	Central	Eastern

Source: TECO's 2014-2018 distribution service reliability reports.

Figure 3-32 charts the length of time that a typical TECO customer experiences an outage, which is known as CAIDI. The highest CAIDI minutes appear to be confined to the Dade City, Plant City, and Western regions. Winter Haven and Central regions have had the lowest (best) results for the last five years. The average CAIDI is trending downward at this time suggesting TECO's customers are experiencing shorter outages, notwithstanding the 13 percent increase in the average CAIDI when comparing 2017 to 2018.

Figure 3-32
CAIDI across TECO's Seven Regions (Adjusted)




TECO's Regions with the Highest and Lowest Adjusted CAIDI Distribution Reliability
Performance by Year

	2014	2015	2016	2017	2018
Highest CAIDI	Western	Dade City	Plant City	Central	Western
Lowest CAIDI	Central	Central	Central	Winter Haven	South Hillsborough

Source: TECO's 2014-2018 distribution service reliability reports.

Figure 3-33 denotes a 1.7 percent increase in outage durations for the period from 2017 to 2018 for TECO. The average length of time TECO spends restoring service to its customers affected by outage events, excluding hurricanes and other allowable excluded outage events is shown in the L-Bar index. The L-Bar index continues to be trending upward for the five-year period of 2014 to 2018, suggesting longer restoral times.


Figure 3-33
TECO's Average Duration of Outages (Adjusted)



Source: TECO's 2014-2018 distribution service reliability reports.

Figure 3-34 illustrates TECO’s number of momentary events on primary circuits per customer recorded across its system. In 2018, the MAIFle performance declined over the 2017 results in all regions except Western. The average MAIFle increased by 4 percent from 2017 to 2018. Figure 3-34 also indicates that the average MAIFle is trending downward, which suggest an improvement in performance over the five-year period of 2014 to 2018.

**Figure 3-34
MAIFle across TECO’s Seven Regions (Adjusted)**




**TECO's Regions with the Highest and Lowest Adjusted MAIFle Distribution Reliability
Performance by Year**

	2014	2015	2016	2017	2018
Highest MAIFle	Dade City	Dade City	Dade City	Dade City	Dade City
Lowest MAIFle	Central	Central	Central	Central	Central

Source: TECO’s 2014-2018 distribution service reliability reports.

Figure 3-35 indicates that the percent of TECO’s customers experiencing more than five interruptions. Three regions in TECO’s territory experienced a decrease in the CEMI5 results for 2018. The Central, South Hillsborough, Western, and Winter Haven regions experienced an increase in the CEMI5 index. Even with improvement, Dade City reported the highest CEMI5 percentage for 2018. With TECO’s results for this index varying for the past five years, the average CEMI5 index appears to be trending upward indicating a decline in performance. There was a 36 percent increase in the average CEMI5 index from 2017 to 2018.

Figure 3-35
CEMI5 across TECO’s Seven Regions (Adjusted)



TECO's Regions with the Highest and Lowest Adjusted CEMI5 Distribution Reliability Performance by Year


	2014	2015	2016	2017	2018
Highest CEMI5	Dade City	Dade City	Dade City	Dade City	Dade City
Lowest CEMI5	Western	Winter Haven	South Hillsborough	Central	Eastern

Source: TECO’s 2014-2018 distribution service reliability reports.

Figure 3-36 represents an analysis of TECO's top 3 percent of problem feeders that have reoccurred (appeared on the Three Percent Feeder Report) on a five-year and three-year basis. The graph is developed using the number of recurrences divided by the number of feeders reported. The five-year average of outages per feeder increased by 45 percent from 2017 to 2018. The three-year average of outages also increased by 43 percent from 7 percent in 2017 to 10 percent in 2018. Both the five-year average of outages per feeder and the three-year average of outages appear to continue to trend upward for the five-year period of 2014 to 2018.

Staff notes that there was one feeder on the Three Percent Feeder Report for the last two years consecutively. Five circuit outages were reported for this feeder in 2018. The causes for the outages varied from tree limb debris to vehicle accidents that resulted in electrical wire/pole damage. This feeder will have tree trimming completed in 2019 and reliability improvements (e.g., three-phase main-feeder reclosers, TripSavers, and lightning arresters) completed in 2020. TECO stated that it will continue to monitor circuit outage performance as part of its daily and ongoing review of system reliability and will respond accordingly at a regional level.


Figure 3-36
TECO's Three Percent Feeder Report (Adjusted)



Source: TECO's 2014-2018 distribution service reliability reports.

Figure 3-37 indicates that the top five causes of outage events on TECO’s distribution system normalized to a 10,000-customer base. The figure is based on TECO’s adjusted data of the top 10 causes of outage events and represents 89 percent of the total outage events that occurred during 2018. For the five-year period, the five top causes of outage events included “Defective Equipment” (24 percent), “Vegetation” (24 percent), “Lightning” (18 percent), “Animals” (12 percent), and “Unknown Causes” (11 percent) on a cumulative basis. “Defective Equipment” is the highest cause of outages for 2018. “Vegetation” and “Lightning” causes are the next two top problem areas for TECO. The outages due to “Vegetation” increased 24 percent from 2017 to 2018. The outages from “Lightning” increased 58 percent for the same time period. The numbers of outages due to “Defective Equipment,” “Lightning,” and “Animals” causes are trending downward while the number of outages due to “Vegetation” and “Unknown Causes” are trending upward.

Figure 3-37
TECO’s Top Five Outage Causes (Adjusted)



Source: TECO’s 2014-2018 distribution service reliability reports.

Observations: TECO's Adjusted Data

All of TECO's 2018 reliability indices declined in performance compared to 2017. For the five-year period of 2014 to 2018, the indices for SAIDI, SAIFI, CEMI5, L-Bar, the Three-Year Percent of Multiple Feeder outage events, and the Five-Year Percent of Multiple Feeder outage events are all trending upward. The indices for CAIDI and MAIFIE are trending downward. TECO reported the increase in the reliability indices were due to several unnamed storm days that occurred in November and December 2018. TECO notes that the Dade City, Plant City, and Winter Haven regions have the fewest customers and represent the most rural, lowest customer density per line mile. TECO indicated that the rural areas typically have higher reliability indices due to the greater distance of travel for service restoration.

In 2018, the Dade City region had the highest reliability indices in four of the five indices although Dade City did improve in two of the five indices. The Dade City region has a total of 14 feeders/circuits. In 2017, TECO installed new reclosers along with other activities to improve the reliability of the Dade City region. In 2018, TECO installed additional reclosers and trimmed trees in the Dade City area. For 2019 and 2020, TECO is planning on performing additional work to improve the Dade City region's reliability. At year-end 2019, TECO should have performed reliability improvement work on at least 35 percent of the Dade City region's feeders/circuits.

Section IV: Inter-Utility Reliability Comparisons

Section IV contains comparisons of the utilities' adjusted data for the various reliability indices that were reported. It also contains a comparison of the service reliability related complaints received by the Commission.


Inter-Utility Reliability Trend Comparisons: Adjusted Data

The inter-utility trend comparison focuses on a graphical presentation that combines all of the IOUs' distribution reliability indices for the years 2014 to 2018. **Figures 4-1** through **4-3** apply to all five utilities while **Figures 4-4** and **4-5** do not apply to FPUC because it is not required to report MAIFle and CEMI5 due to the size of its customer base. The adjusted data is used in generating the indices in this report and is based on the exclusion of certain events allowed by Rule 25-6.0455(4), F.A.C. Generalizations can be drawn from the side-by-side comparisons; however, any generalizations should be used with caution due to the differing sizes of the distribution systems, the degree of automation, and the number of customers. The indices are unique to each IOU.

Figure 4-1 indicates that DEF's, Gulf's, and TECO's SAIDI trend has risen since 2014, while FPL and FPUC are trending downward. Comparing 2017 SAIDI values to 2018 SAIDI indices, FPL and Gulf have improved as the other utilities declined in performance. Gulf's SAIDI value decreased 16 percent and FPL decreased 2 percent from 2017 to 2018. DEF's SAIDI value has increased 19 percent, FPUC increased 11 percent, and TECO increased 30 percent from 2017 to 2018.

SAIDI is the average amount of time a customer is out of service per retail customers served within a specified area of service over a given period. It is determined by dividing the total Customer Minutes of Interruption by total Number of Customers Served for the respective area of service.

**Figure 4-1
System Average Interruption Duration (Adjusted SAIDI)**




Source: The IOUs' 2014-2018 distribution service reliability reports.

Figure 4-2 shows a five-year graph of the adjusted SAIFI for each IOU. The 2018 data shows FPL and FPUC's SAIFI values decreased (improved) from the 2017 results as DEF, Gulf and TECO's SAIFI values increased. Over the five-year period of 2014 to 2018, Gulf and TECO's SAIFI values are all trending upward. DEF, FPL and FPUC's SAIFI value is trending downward for the period of 2014 to 2018.

SAIFI is the average number of service interruptions per retail customer within a specified area of service over a given period. It is determined by dividing the Sum of Service (a/k/a Customer) Interruptions (CI) by the total Number of Customers Served for the respective area of service.

Figure 4-2
Number of Service Interruptions (Adjusted SAIFI)




Source: The IOUs' 2014-2018 distribution service reliability reports.

Figure 4-3 shows a five-year graph of the adjusted CAIDI for each IOU. DEF, FPUC, and TECO had an increase in the CAIDI from 2017 to 2018 while Gulf had a decrease in the CAIDI. FPL's CAIDI value was the same for 2018 as it was for 2017. All utilities, except DEF and FPUC, CAIDI values are trending downward for the five-year period of 2014 to 2018. DEF's and FPUC's CAIDI value is trending upward for the same period.

CAIDI is the average interruption duration or the time to restore service to interrupted customers. CAIDI is calculated by dividing the total system CMI by the number of customer interruptions, which is also SAIDI, divided by SAIFI.

Figure 4-3
Average Service Restoration Time (Adjusted CAIDI)




Source: The IOUs' 2014-2018 distribution service reliability reports.

Figure 4-4 shows a five-year graph of the adjusted MAIFle for DEF, FPL, Gulf, and TECO. DEF, FPL, and TECO's MAIFle indices are all trending downward for the five-year period of 2014 to 2018. Gulf's MAIFI appears relatively flat for the five-year period. Comparing the MAIFle for 2017 to 2018, DEF increased by 35 percent, FPL decreased by 7 percent, Gulf decreased by 13 percent and TECO increased by 4 percent. FPUC is exempt from reporting MAIFle and CEMI5 because it has fewer than 50,000 customers.

MAIFle is the average frequency of momentary interruptions events or the number of times there is a loss of service of less than one minute. MAIFle is calculated by dividing the number of momentary interruptions events recorded on primary circuits (CME) by the number of customers served.


Figure 4-4
Average Number of Feeder Momentary Events (Adjusted MAIFle)



Source: The IOUs' 2014-2018 distribution service reliability reports.

Figure 4-5 shows a five-year graph of the adjusted CEMI5 for FPL, Gulf, DEF, and TECO. CEMI5 is a percentage. It represents the number of customers that experienced more than five service interruptions in the year divided by the total number of customers. In 2018, DEF, Gulf and TECO's CEMI5 percent increased to 1.0 percent from 0.7 percent in 2017 for DEF, 1.5 percent from 0.8 percent in 2017 for Gulf, and 1.5 percent from 1.1 percent in 2017 for TECO. FPL decreased from 0.8 percent in 2017 to 0.6 percent in 2018. DEF and FPL are trending downward as Gulf and TECO are trending upward for the period of 2014 to 2018.


Figure 4-5
Percent of Customers with More Than Five Interruptions (Adjusted CEMI5)



Source: The IOUs' 2014-2018 distribution service reliability reports.

Figure 4-6 shows the number of outages per 10,000 customers on an adjusted basis for the five IOUs over the last five years. The graph displays each utility's adjusted data concerning the number of outage events and the total number of customers on an annual basis. The number of FPL outages decreased from 95,077 in 2017 to 93,306 in 2018, and the number of outages per 10,000 customers is trending downward for the five-year period. TECO's results are trending downward for the five-year period. DEF's number of outages increased for 2018 and the results are relatively flat for the five-year period. Gulf's number of outages decreased for 2018, and is trending upward for the five-year period. FPUC's results decreased for 2014 to 2015, increased for 2015 to 2016, decreased for 2016 to 2017, and decreased for 2017 to 2018. Due to its small customer base, FPUC's number of outages per 10,000 customers may be more volatile.


Figure 4-6
Number of Outages per 10,000 Customers (Adjusted)



Source: The IOUs' 2014-2018 distribution service reliability reports.

Figure 4-7 represents the average duration of outage events (Adjusted L-Bar) for each IOU. From the data shown, it appears that the utilities have been consistent with their restoral times for the five-year period of 2014 to 2018, even with increases from 2017 to 2018.

Figure 4-7
Average Duration of Outage Events (Adjusted L-Bar)




Source: The IOUs' 2014-2018 distribution service reliability reports.

Inter-Utility Comparisons of Reliability Related Complaints

Figures 4-8, 4-9, 4-10, and 4-11 represent consumer complaint data that was extracted from the Commission’s Consumer Activity Tracking System (CATS). Each consumer complaint received by the Commission is assigned a code after the complaint is resolved. Reliability related complaints have 10 specific category types and typically pertain to “Trees,” “Safety,” “Repairs,” “Frequent Outages,” and “Momentary Service Interruptions.”

Figure 4-8 shows the total number of jurisdictional complaints¹⁶ for each IOU. In comparing the number of complaints by the different companies, the total number of customers should be considered. FPL has the higher number of complaints, but FPL also has more customers than the other companies.

Figure 4-8
Total Number of Jurisdictional Complaints




Source: FPSC CATS.

¹⁶Non-jurisdictional complaint codes include load management, hurricanes, and damage claims.

Figure 4-9 charts the total number of reliability related complaints for the IOUs. DEF is showing the largest amount of reliability complaints for the five-year period of 2014 to 2018 with FPUC and Gulf showing the least amount. Gulf is trending downward in the number of reliability complaints, while DEF, FPL, FPUC, and TECO are trending upward.


Figure 4-9
Total Number of Reliability Related Complaints



Source: FPSC CATS.

Figure 4-10 shows the percentage of reliability related customer complaints in relation to the total number of complaints for each IOU. DEF and Gulf appear to be trending downward as FPL, FPUC and TECO are trending upward. The percentages of FPUC complaints compared to the other companies appears high, however FPUC has fewer customers and fewer complaints in total.

Figure 4-10
Percent of Complaints that are Reliability Related




Source: FPSC CATS.

Figure 4-11 charts the volume of reliability related complaints per 10,000 customers for the IOUs. The volume of service reliability complaints is normalized to a 10,000-customer base for comparative purposes. This is calculated for each IOU by dividing the total number of reliability complaints reported to the Commission by the total number of the utility's customers. This fraction is then multiplied by 10,000 for graphing purposes.

All the IOUs have less than one reliability complaint per 10,000 customers since 2014 except FPUC. For the five-year period, Gulf is trending downward as FPL is staying relatively flat. DEF, FPUC, and TECO are trending upward for the five-year period. The volatility of FPUC's results can be attributed to its small customer base, which typically averages 28,500 customers.

Figure 4-11
Service Reliability Related Complaints per 10,000 Customers



Source: The IOUs' 2014-2018 distribution service reliability reports and FPSC CATS.

Section V: Appendices

Appendix A – Adjusted Service Reliability Data

Duke Energy Florida, LLC

Table A-1
DEF's Number of Customers (Year End)

	2014	2015	2016	2017	2018
North Central	388,187	396,395	400,510	406,483	409,949
North Coastal	196,321	198,525	200,565	203,300	204,915
South Central	449,363	458,457	470,534	484,848	493,782
South Coastal	663,973	670,743	677,255	682,618	686,076
DEF System	1,697,844	1,724,120	1,748,864	1,777,249	1,794,722

Source: DEF's 2014-2018 distribution service reliability reports.

Table A-2
DEF's Adjusted Regional Indices SAIDI, SAIFI, and CAIDI

	Average Interruption Duration Index (SAIDI)					Average Interruption Frequency Index (SAIFI)					Average Customer Restoration Time Index (CAIDI)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
North Central	84	72	78	75	86	1.11	0.85	0.90	0.84	0.96	76	84	87	90	90
North Coastal	159	145	155	154	168	1.57	1.47	1.39	1.45	1.52	101	99	111	107	111
South Central	83	71	79	70	84	1.04	0.91	1.01	0.84	0.93	80	77	78	83	90
South Coastal	66	71	73	75	95	0.96	0.97	0.90	0.88	0.95	68	74	81	85	100
DEF System	85	80	85	83	99	1.09	0.98	0.98	0.92	1.01	78	81	86	90	97

Source: DEF's 2014-2018 distribution service reliability reports.

Table A-3
DEF's Adjusted Regional Indices MAIFle and CEMI5

	Average Frequency of Momentary Events on Feeders (MAIFle)					Percentage of Customers Experiencing More than 5 Service Interruptions (CEMI5)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
North Central	10.8	8.3	8.6	7.6	3.6	1.07%	0.32%	0.36%	0.37%	0.42%
North Coastal	10.0	7.1	7.8	8.2	13.6	3.47%	3.96%	4.00%	2.83%	4.80%
South Central	10.3	8.1	7.0	6.9	11.4	1.04%	0.64%	1.06%	0.87%	0.44%
South Coastal	10.8	11.2	7.3	6.8	10.8	1.36%	0.43%	0.68%	0.21%	0.49%
DEF System	10.6	9.2	7.6	7.2	9.7	1.45%	0.87%	1.09%	0.73%	0.95%

Source: DEF's 2014-2018 distribution service reliability reports.

Table A-4
DEF's Primary Causes of Outages Events

	Adjusted Number of Outages Events						Adjusted L-Bar Length of Outages				
	2014	2015	2016	2017	2018	Percentages	2014	2015	2016	2017	2018
Animals	5,020	5,321	5,369	5,597	4,566	10.7%	75	75	80	80	82
Unknown	2,867	1,224	1,097	998	766	1.8%	82	77	90	94	83
All Other	8,073	7,900	7,390	8,287	8,310	19.4%	170	167	174	180	173
Defective Equipment	7,221	8,572	9,195	10,475	12,038	28.1%	150	142	147	150	152
Lightning	1,647	1,201	1,216	1,261	1,517	3.5%	166	145	150	151	157
Vegetation	9,816	8,240	7,879	8,143	8,522	19.9%	137	136	145	150	148
Other Weather	5,875	7,141	4,965	5,478	6,463	15.1%	108	134	134	145	144
Vehicle	420	412	429	505	599	1.4%	241	227	235	223	233
DEF System	40,939	40,011	37,540	40,744	42,781	100%	132	134	140	145	147

Source: DEF's 2014-2018 distribution service reliability reports.

Note: (1) "Other Causes" category is the sum of diverse causes of outage events which individually are not among the top 10 causes of outage events.

Florida Power & Light Company

Table A-5
FPL's Number of Customers (Year End)

	2014	2015	2016	2017	2018
Boca Raton	366,503	370,266	374,080	378,125	380,552
Brevard	297,877	301,843	305,151	307,825	312,017
Central Broward*	268,737	271,478	273,692	276,218	278,910
Central Dade	282,155	287,147	292,421	297,237	314,448
Central Florida	279,726	283,868	286,492	289,426	293,507
Manasota	378,304	384,138	390,400	395,636	401,766
Naples	379,012	386,710	394,355	399,295	406,500
North Broward*	310,483	314,209	317,731	319,630	321,508
North Dade	235,112	237,328	240,194	241,259	248,900
North Florida	150,052	153,683	157,967	161,216	166,703
South Broward*	331,643	335,006	337,828	339,518	342,226
South Dade	299,919	304,336	309,022	311,692	299,375
Toledo Blade	254,982	260,053	265,547	269,787	275,688
Treasure Coast	283,693	287,508	291,334	294,545	299,495
West Dade	254,130	257,539	261,484	264,888	266,629
West Palm	357,064	361,717	364,292	366,570	370,077
FPL System	4,729,392	4,796,829	4,861,990	4,912,867	4,978,301

Source: FPL's 2014-2018 distribution service reliability reports.

Note: Three management regions were renamed: Pompano became North Broward, Wingate became Central Broward and Gulf Stream became South Broward.

Table A-6
FPL's Adjusted Regional Indices SAIDI, SAIFI, and CAIDI

	Average Interruption Duration Index (SAIDI)					Average Interruption Frequency Index (SAIFI)					Average Customer Restoration Time Index (CAIDI)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
Boca Raton	63	54	51	45	50	1.21	1.08	1.08	0.89	1.00	52	50	47	50	49
Brevard	69	53	53	56	44	1.14	0.96	0.87	1.04	0.87	61	55	60	54	50
Central Broward*	74	64	58	61	60	1.25	1.14	0.86	1.11	0.90	59	57	67	55	66
Central Dade	54	47	41	42	42	0.80	0.78	0.66	0.79	0.77	68	60	63	53	54
Central Florida	61	50	49	46	47	0.95	0.90	0.80	0.85	0.84	64	55	61	54	56
Manasota	57	55	52	50	52	0.83	1.00	0.91	0.77	0.73	68	55	57	65	72
Naples	58	57	56	64	55	0.88	0.91	0.97	0.92	0.89	66	62	57	69	62
North Broward*	52	57	48	38	39	0.86	1.03	0.80	0.65	0.66	61	55	60	58	59
North Dade	77	71	59	69	69	0.83	0.87	0.72	0.96	0.94	92	82	82	72	74
North Florida	77	68	64	64	73	1.06	1.08	1.00	1.04	1.25	73	63	64	62	58
South Broward*	58	52	43	42	51	0.96	0.88	0.83	0.79	0.90	60	59	51	54	56
South Dade	73	76	68	63	59	0.90	1.08	0.99	0.79	0.83	81	71	69	80	71
Toledo Blade	73	65	75	77	70	1.16	0.98	1.14	1.12	1.01	63	66	66	69	69
Treasure Coast	74	72	81	66	47	1.07	1.05	1.19	1.11	0.81	69	69	68	59	59
West Dade	72	68	56	54	67	1.20	1.24	0.99	0.85	1.03	60	55	57	63	65
West Palm	49	55	51	46	46	0.85	1.01	0.88	0.96	0.97	58	55	58	47	48
FPL System	64	59	56	54	53	0.99	1.00	0.92	0.90	0.89	65	60	61	60	60

Source: FPL's 2014-2018 distribution service reliability reports.

Note: Three management regions were renamed: Pompano became North Broward, Wingate became Central Broward and Gulf Stream became South Broward.

Table A-7
FPL's Adjusted Regional Indices MAIFle and CEMI5

	Average Frequency of Momentary Events on Feeders (MAIFle)					Percentage of Customers Experiencing More than 5 Service Interruptions (CEMI5)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
Boca Raton	8.6	7.4	5.6	4.6	4.3	0.89%	0.76%	1.36%	0.37%	0.90%
Brevard	9.6	7.8	5.2	4.0	3.5	0.33%	0.27%	0.17%	0.86%	0.27%
Central Broward*	12.9	10.4	7.9	6.5	4.5	0.81%	0.59%	0.53%	0.66%	0.17%
Central Dade	7.8	7.5	5.0	3.6	3.0	0.66%	0.29%	0.55%	0.78%	0.73%
Central Florida	8.9	6.5	5.2	3.4	3.8	0.51%	0.30%	0.15%	0.24%	0.84%
Manasota	7.0	6.1	5.3	4.0	3.8	0.33%	0.91%	0.21%	0.34%	0.26%
Naples	7.0	7.1	6.8	6.0	4.7	0.74%	0.56%	0.44%	0.34%	0.35%
North Broward*	6.9	6.1	4.5	3.1	3.4	0.46%	1.01%	1.23%	0.07%	0.54%
North Dade	8.4	7.7	5.3	3.3	3.2	0.89%	1.01%	0.28%	1.23%	0.70%
North Florida	10.3	8.7	5.8	4.2	3.2	0.60%	0.71%	0.44%	0.72%	1.44%
South Broward*	8.8	6.6	5.1	4.0	4.4	0.68%	0.79%	0.13%	0.60%	0.17%
South Dade	7.9	7.1	5.8	4.3	3.8	0.61%	0.89%	0.24%	0.67%	0.29%
Toledo Blade	9.7	8.2	7.8	4.5	5.2	1.33%	0.65%	1.57%	1.48%	1.94%
Treasure Coast	11.0	8.1	6.4	4.0	3.5	0.96%	1.03%	2.87%	1.73%	0.51%
West Dade	8.2	7.8	6.4	4.4	4.5	0.60%	1.46%	0.57%	0.72%	0.49%
West Palm	8.5	7.5	5.5	4.4	4.7	1.39%	1.01%	0.50%	2.04%	0.63%
FPL System	8.7	7.5	5.8	4.3	4.0	0.74%	0.76%	0.70%	0.78%	0.60%

Source: FPL's 2014-2018 distribution service reliability reports.

Note: Three management regions were renamed: Pompano became North Broward, Wingate became Central Broward and Gulf Stream became South Broward.

**Table A-8
FPL's Primary Causes of Outage Events**

	Adjusted Number of Outage Events						Adjusted L-Bar Length of Outages				
	2014	2015	2016	2017	2018	Percentages	2014	2015	2016	2017	2018
Unknown	11,703	11,022	10,139	10,436	10,482	11.2%	124	124	133	163	145
Vegetation	21,633	23,155	20,331	17,264	15,949	17.1%	187	182	197	205	199
Animals	9,359	9,878	9,506	9,219	9,131	9.8%	94	93	100	109	104
Remaining Causes	3,410	3,147	2,821	3,308	3,394	3.6%	142	140	158	167	172
Other Weather	10,141	9,426	7,978	7,458	7,335	7.9%	160	167	173	215	194
Other	9,187	8,358	7,340	9,402	9,959	10.7%	148	149	161	217	198
Lightning	1,938	1,770	1,647	1,192	1,902	2.0%	245	241	255	245	282
Vehicle	877	969	911	1,026	954	1.0%	251	230	248	253	275
Defective Equipment	33,733	32,838	32,013	35,772	34,200	36.7%	190	179	195	206	238
FPL System	101,981	100,563	92,686	95,077	93,306	100%	166	162	175	193	199

Source: FPL's 2014-2018 distribution service reliability reports.

Notes: (1) "Other Causes" category is a sum of outages events that require a detailed explanation.

(2) "Remaining Causes" category is the sum of many diverse causes of outage events, which individually are not among the top 10 causes of outage events, and excludes those identified as "Other Causes."

Florida Public Utilities Company

Table A-9
FPUC's Number of Customers (Year End)

	2014	2015	2016	2017	2018
Fernandina(NE)	15,628	15,787	16,037	16,286	16,410
Marianna (NW)	12,621	12,649	12,663	12,764	11,729
FPUC System	28,249	28,436	28,700	29,050	28,139

Source: FPUC's 2014-2018 distribution service reliability reports.

Table A-10
FPUC's Adjusted Regional Indices SAIDI, SAIFI, and CAIDI

	Average Interruption Duration Index (SAIDI)					Average Interruption Frequency Index (SAIFI)					Average Customer Restoration Time Index (CAIDI)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
NE	88	105	128	93	137	1.14	1.19	1.41	1.04	1.23	77	88	90	89	112
NW	284	155	258	197	178	2.81	2.15	2.63	2.41	1.75	101	72	98	82	102
FPUC System	175	127	185	139	154	1.89	1.62	1.95	1.64	1.45	93	79	95	85	107

Source: FPUC's 2014-2018 distribution service reliability reports.

**Table A-11
FPUC's Primary Causes of Outage Events**

	Adjusted Number of Outage Events						Adjusted L-Bar Length of Outages				
	2014	2015	2016	2017	2018	Percentages	2014	2015	2016	2017	2018
Vegetation	262	295	436	354	421	37.9%	87	76	78	83	86
Animals	245	201	354	267	204	18.4%	60	53	51	56	62
Lightning	96	148	128	77	128	11.5%	110	90	82	81	98
Unknown	66	75	89	62	69	6.2%	67	64	75	89	88
Corrosion	-	-	12	-	-	-	-	-	102	-	-
All Other	45	27	58	44	61	5.5%	62	94	65	86	76
Other Weather	381	178	148	152	55	5.0%	155	94	147	168	101
Vehicle	25	25	26	30	21	1.9%	108	130	121	94	148
Defective Equipment	138	136	163	160	152	13.7%	232	97	94	117	101
FPUC System	1,258	1,085	1,414	1,146	1,111	100%	105	80	81	93	86

Source: FPUC's 2014-2018 distribution service reliability reports.

Notes: (1) "Other Causes" category is the sum of many diverse causes of outage events which individually are not one of the top 10 causes of outage events.

(2) Blanks are shown for years where the quantity of outages was less than one of the top 10 causes of outage event.

Gulf Power Company

Table A-12
Gulf's Number of Customers (Year End)

	2014	2015	2016	2017	2018
Central	114,363	115,524	116,745	118,010	119,219
Eastern	113,897	115,099	116,702	117,847	114,413
Western	215,787	218,848	221,968	225,949	229,351
Gulf System	444,047	449,471	455,415	461,806	462,983

Source: Gulf's 2014-2018 distribution service reliability reports.

Table A-13
Gulf's Adjusted Regional Indices SAIDI, SAIFI, and CAIDI

	Average Interruption Duration Index (SAIDI)					Average Interruption Frequency Index (SAIFI)					Average Customer Restoration Time Index (CAIDI)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
Central	115	75	91	110	86	1.07	0.82	1.04	1.05	0.90	107	92	88	105	95
Eastern	73	59	93	108	103	0.78	0.86	1.21	1.27	1.30	93	69	77	85	79
Western	81	110	97	123	99	0.94	1.21	1.15	1.24	1.42	87	91	85	100	70
Gulf System	88	88	95	116	97	0.93	1.02	1.14	1.20	1.26	94	86	83	97	77

Source: Gulf's 2014-2018 distribution service reliability reports.

Table A-14
Gulf's Adjusted Regional Indices MAIFle and CEMI5

	Average Frequency of Momentary Events on Feeders (MAIFle)					Percentage of Customers Experiencing More than 5 Service Interruptions (CEMI5)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
Central	2.8	1.8	1.5	2.1	1.6	0.36%	0.17%	0.22%	0.91%	0.51%
Eastern	1.9	1.7	1.6	2.3	1.9	0.43%	1.66%	1.84%	0.86%	2.15%
Western	2.3	2.7	2.7	2.7	2.4	0.28%	0.59%	0.77%	0.80%	1.68%
Gulf System	2.3	2.2	2.1	2.4	2.1	0.34%	0.76%	0.91%	0.84%	1.49%

Source: Gulf's 2014-2018 distribution service reliability reports.

Table A-15
Gulf's Primary Causes of Outage Events

	Adjusted Number of Outage Events						Adjusted L-Bar Length of Outages				
	2014	2015	2016	2017	2018	Percentages	2014	2015	2016	2017	2018
Animals	2,132	2,743	3,557	3,514	2,189	19.6%	64	60	65	70	69
Lightning	1,827	1,788	1,913	1,633	1,623	14.5%	136	134	138	164	131
Unknown	557	598	748	818	1,121	10.0%	86	79	82	101	102
Vehicle	289	293	381	377	389	3.5%	185	170	164	171	181
All Other	445	379	457	428	442	4.0%	113	101	100	113	110
Vegetation	1,294	1,888	1,954	2,460	2,521	22.6%	123	138	116	144	119
Other Weather	196	251	220	366	257	2.3%	181	137	126	243	145
Defective Equipment	2,257	2,340	2,714	2,804	2,618	23.5%	138	137	132	140	140
Gulf System	8,997	10,280	11,944	12,400	11,160	100%	116	112	107	125	116

Source: Gulf's 2014-2018 distribution service reliability reports.

Notes: (1) "Other Causes" category is the sum of many diverse causes of outage events, which individually are not among the top 10 causes of outages events.

Tampa Electric Company

Table A-16
TECO's Number of Customers (Year End)

	2014	2015	2016	2017	2018
Central	190,459	193,436	196,431	202,572	205,611
Dade City	14,165	14,372	14,492	14,801	14,954
Eastern	115,122	117,268	119,286	122,667	125,030
Plant City	57,220	58,472	59,381	61,187	62,131
South Hillsborough	69,431	72,340	75,450	80,194	84,636
Western	196,085	198,224	199,891	203,805	206,962
Winter Haven	69,687	70,799	71,888	74,403	75,778
TECO System	712,169	724,911	736,819	759,629	775,102

Source: TECO's 2014-2018 distribution service reliability reports.

Table A-17
TECO's Adjusted Regional Indices SAIDI, SAIFI, and CAIDI

	Average Interruption Duration Index (SAIDI)					Average Interruption Frequency Index (SAIFI)					Average Customer Restoration Time Index (CAIDI)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
Central	63	70	63	64	87	0.80	1.06	0.85	0.82	1.04	79	66	74	78	83
Dade City	206	199	153	153	168	2.36	1.92	1.79	2.10	1.98	87	104	86	73	85
Eastern	76	67	85	63	85	0.96	0.90	0.99	0.89	1.00	80	75	86	72	86
Plant City	117	117	113	92	112	1.47	1.46	1.20	1.44	1.55	79	80	94	64	72
South Hillsborough	74	86	104	84	99	0.85	1.10	1.35	1.20	1.43	88	78	77	70	69
Western	81	78	81	71	97	0.86	0.89	0.94	0.99	1.12	94	87	86	72	86
Winter Haven	77	66	82	76	93	0.93	0.93	0.94	1.21	1.27	83	71	87	62	73
TECO System	80	79	83	73	95	0.94	1.03	1.00	1.03	1.18	85	77	83	71	80

Source: TECO's 2014-2018 distribution service reliability reports.

Table A-18
TECO's Adjusted Regional Indices MAIFle and CEMI5

	Average Frequency of Momentary Events on Feeders (MAIFle)					Percentage of Customers Experiencing More than 5 Service Interruptions (CEMI5)				
	2014	2015	2016	2017	2018	2014	2015	2016	2017	2018
Central	8.3	8.5	7.8	7.9	8.1	0.83%	0.51%	0.96%	0.18%	1.41%
Dade City	19.8	18.0	14.7	14.2	14.8	5.94%	10.41%	2.72%	6.64%	4.73%
Eastern	9.9	9.1	9.2	8.8	10.2	0.33%	0.27%	0.47%	1.79%	0.77%
Plant City	15.1	11.8	13.4	12.8	14.7	1.37%	2.61%	2.15%	3.02%	1.10%
South Hillsborough	8.7	11.0	12.8	10.8	11.1	0.23%	0.82%	0.17%	2.43%	2.93%
Western	9.6	8.7	8.8	8.4	8.3	0.15%	0.42%	0.63%	0.30%	1.19%
Winter Haven	11.4	11.1	9.7	9.7	9.9	0.54%	0.15%	1.81%	0.20%	2.23%
TECO System	10.0	9.6	9.6	9.2	9.6	0.62%	0.81%	0.92%	1.07%	1.54%

Source: TECO's 2014-2018 distribution service reliability reports.

Table A-19
TECO's Primary Causes of Outage Events

	Adjusted Number of Outage Events						Adjusted L-Bar Length of Outages				
	2014	2015	2016	2017	2018	Percentages	2014	2015	2016	2017	2018
Lightning	1,917	1,779	1,751	1,258	1,258	13.6%	199	218	255	206	207
Animals	1,483	1,321	1,178	1,632	1,632	17.6%	98	100	97	105	96
Vegetation	1,974	2,064	1,959	2,108	2,108	22.7%	192	190	214	195	200
Unknown	850	792	931	972	972	10.5%	134	125	144	141	134
Other Weather	209	166	-	-	-	-	82	192	-	-	-
Vehicle	343	397	363	401	401	4.3%	76	199	211	214	78
Defective Equipment	2,788	2,803	2,581	2,494	2,494	26.9%	419	198	243	203	190
All Other	182	559	428	649	408	4.4%	165	166	173	147	188
TECO System	9,746	9,881	9,191	9,514	9,273	100%	173	179	203	177	180

Source: TECO's 2014-2018 distribution service reliability reports.

Notes: (1) "Other Causes" category is the sum of many diverse causes of outage events which individually are not among the top 10 causes of outages events.

(2) Blanks are shown for years where the number of outages was too small to be among the top 10 causes of outage events.

Appendix B. Summary of Municipal Electric Utility Reports Pursuant to Rule 25-6.0343, F.A.C. – Calendar Year 2018

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Alachua, City of	Yes	Yes. The City design is based on 110 mph wind load with a 1.25 (minimum) safety factor for wind gusts.	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	The City's inspection cycle is on an eight-year cycle (12.5% per year) The City of Alachua owns only distribution poles, no transmission poles. In October 2015, the City completed its first eight-year cycle.	For 2018, the City inspected 463 (18.6%) of its 2,492 distribution poles.	From the 2018 inspection report: 41 (8.8%) poles were rejected. Four poles were deemed priority rejects requiring immediate change-out due to shell rot at ground level. 37 poles were deemed non-priority rejects due to shell rot, decay top, split top and woodpecker holes.	From the 2018 inspection report: the failed poles were 30, 35, 40, 45, 50 or 55 feet, Class 3, 4, 5 or 6 and replaced accordingly. The non-priority reject poles were treated and wrapped.	The City continues to use the information from the PURC conference held in 2007 and 2009, to improve vegetation management.	The City trims approximately 62 miles of overhead distribution on a three-year cycle. Approximately 20% of the facilities are trimmed each year. GIS mapping system is used to track trimming annually and to budget annual trimming projects.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Bartow, City of	Yes. The City is currently guided by the EWL standards as specified in the 2017 edition of the NESC. The City lies within the 100-110 mph region.	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	The facilities are inspected on an eight-year cycle. Inspections are visual, and tests are made to identify shell rot, insect infestation, and excavated to determine strength.	The City began round two of its eight-year pole inspection cycle in 2016 and elected to perform pole inspections every other year. In 2018, the City inspected 1,704 poles.	147 (9%) distribution poles failed inspection due to pole top rot or rotten ground decay in 2018.	54 poles were replaced ranging in size from 30 to 65 feet Classes 1 to 5 in 2018. Also in 2018, 12 poles had the equipment lowered and the top of the pole cut. These poles ranged in size from 30 to 40 feet, Class 5.	The City is on a four-year trim cycle with trim out at 6-10-foot clearance depending on the situation and type of vegetation, along with foliage and herbicidal treatments.	The City feels that its four-year cycle and other vegetation management practices are effective in offering great reliability to its customers. The City is currently contracting additional line clearance personnel to maintain the four-year cycle.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
City of Jacksonville Beach d/b/a Beaches Energy Services	Yes. BES has a program in place where all OH distribution lines, roughly three city blocks inland of the Atlantic Ocean, will be replaced with UG conductors, pad mounted transformers, switches, and junction cabinets.	Yes. BES uses stronger concrete poles rather than wood poles and eliminates of static lines with shorter distribution structures to reduce moment loads on the structures. BES has a distribution wooden pole replacement program where BES will replace the wooden poles with concrete. To date, 697 concrete poles have been placed in service.	BES eliminated all exposed “live-front” connected transformers. The high voltage cables are connected to the transformers with sealed “dead front” elbows. Fiberglass foundations for pad mounted equipment have been replaced with thick heavy concrete foundations.	Yes. “Back lot line” construction has been eliminated, all electric kWh meters are located outside & near the front corner of buildings, all replacement or new URD underground cables are being installed in conduits & have a plastic, jacketed sheath, & all pad mounted equipment located near buildings have minimum access clearance.	Yes	The transmission structure is inspected annual, which includes insulators, downguys, grounding, and pole integrity. The distribution poles are inspected on an eight-year cycle using sound and bore method for every wood pole. Poles 10 years old and older were treated at ground level for rot and decay.	424 (100%) transmission structure inspections were planned and completed. In 2018, 150 (2.8%) distribution poles were inspected.	No transmission structures failed the inspection. In 2018, no distribution structures failed inspection.	No transmission structures failed the inspection. In 2018, no poles were replaced.	The transmission line rights-of-way are mowed and maintained annually. Tree trimming crews work year round to maintain a two to three year VMP cycle for transmission and distribution lines.	All vegetation management activities for 2018 have been fully completed and the vegetation management activities for 2019 are on schedule.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Blountstown, City of	Yes	Yes. The City of Blountstown adopted a larger minimum pole standard of a Class 3 pole in 2007 in an effort to harden facilities.	The City does not have any underground facilities. The City raised its substation facilities above historical flooding so that the components at the facilities will not suffer directly from flooding.	Yes	No. Guidelines do not include written safety, pole reliability, pole loading, capacity and engineering standards and procedures for attachments by others to the transmission and distribution poles.	The City owns 1,947 utility poles and does visual inspections of all poles once a year. The City took a direct hit from Hurricane Michael, which resulted in a rebuild of its system. The City is retagging all poles due to this event.	100% of all poles are visually inspected annually.	34 (1.7%) poles required replacement because of ground rot, extreme cracking and warping and upgrading the lines. The City also reconducted about 2,800 linear feet of distribution line.	34 Class 5 poles were replaced with Class 3 poles.	The City has a four-year tree trimming cycle with a 10-foot clearance of lines and facilities. The City has policies to remove dead, dying, or problematic trees before damage occurs.	The City will trim 25% of the system with a 10-foot clearance in 2019.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Bushnell, City of	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	The agreements include language that specifies that the third-party attacher, not the City, has the burden of assessing pole strength and safety before they attach to the pole. The City performs follow-up audits on the attachments.	The City has no transmission facilities. All distribution poles are on a seven-year cycle. The inspection includes visual, sound/bore, pole condition, and wind loading.	In 2018, the City inspected 297 poles.	Of the poles inspected in 2018, 27 poles failed. The reasons for the failures were age, shell flake, and ground rot.	Of the 27 poles that failed inspections, to date, 6 poles were replaced in 2018. The City replaced Class 4 and 5 with Class 1 and 2 poles.	Tree removal, power line trim, and rights-of-way clearing are on a three-year cycle. Distribution lines not located on rights-of-way are trimmed on an “as needed” basis.	The City is working on major additions to the system which has and will continue to increase the City’s VM area.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Chattahoochee, City of	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	The distribution facilities are on a three-year cycle inspection using visual, excavation around base, sounding, and probing with steel rod. The City does not have any transmission facilities.	1,957 distribution poles were inspected in January 2018.	In 2018, 53 (2.7%) poles failed the inspection due to ground line and pole top decay.	No poles were replaced. A schedule has yet to be determined.	The City trims the distribution system on an annual basis. This cuts down on animal outages by limiting their pathways to poles and conductors.	The 2007 and 2009 PURC workshops reports are used to improve vegetation management.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Clewiston, City of	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	The City does not have standard guidelines for pole attachments as all attachments are reviewed by engineers, and place all new construction underground.	The facilities are on a five-year inspection cycle, which began in 2014, using sound, prod and visual inspections. The City performs infrared inspections on the facilities on a three- to four-year cycle.	In 2018, 320 (20%) poles were scheduled for inspection and 200 (63% of planned) poles were inspected.	30 (18%) poles failed inspection due to pole rot.	All of the City's transmission poles are concrete. In 2018, the City replaced 5-40 feet distribution poles previously identified. The 30 poles failing the 2018 inspection were Class 4 and 5 poles and are scheduled for replacement in the near future.	The City has a City ordinance that prohibits planting in easements. 100% of the distribution system is inspected annually for excessive tree growth. The City trims the entire system continuously as needed. The City will also accept requests from customers for tree trimming.	All transmission and feeders checked and trimmed in 2018 as every year, and the City completed 37 customer requests for tree trimming.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Fort Meade, City of	Yes	Yes	The current procedures address flooding & storm surges. Participant in PURC study on conversion of OH to UG.	Yes	Yes	The City's facilities are on an eight-year cycle using visual and sound and probe technique.	The City has distribution lines only. The City replaced 8 poles in 2018.	The City has approximately 2,760 dist. poles. Of those poles 8 (>1%) poles failed inspection. The poles failed inspection due to age deterioration, animal infestation, and vehicle accidents.	The City replaced 8 (> 1%) poles with poles ranging from 45 feet to 30 feet, Class 5 to Class 4.	The facilities are on a three-year inspection cycle, and have a low outage rate due to problem vegetation.	The City has completed approximately 30% of trimming. The city reported 97 outages in 2018, with 11% (11) due to vegetation.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Fort Pierce Utilities Authority	Yes	Yes	Yes. FPUA references FEMA 100 Year Flood Zone for pad mounted equipment installation and alternatively, may elect to install fully submersible equipment as deemed necessary.	Yes	Yes	FPUA utilizes a contractor to perform inspection of all wood distribution and transmission poles on an eight-year cycle. The inspection includes visual inspection from ground line to the top and some excavation is performed on older poles.	3,000 distribution and 100 transmission poles were planned for inspection in 2018. 2,852 distribution and 5 transmission poles were inspected in 2018 indicating 14.0% were inspected. FPUA notes that the inspections are performed by section, which has a combination of structures, so the yearly target is based on area, not on structure.	No transmission pole failed inspection in 2018. 205 (7.2%) distribution pole failed inspection in 2018. 196 failures are non-priority because the calculated strength fell below 67% due to decay at ground line but had sufficient integrity for reinforcement.	FPUA replaced 102 wood distribution poles in 2018. The 196 non-priority poles will be reinforced or replaced during the 2019 and 2020 fiscal years.	FPUA maintains a three-year VM cycle for transmission and distribution system. FPUA also aggressively seeks to remove problem trees when trimming is not an effective option.	FPUA spent \$330,000 for the trimming, removal and disposal of vegetation waste in fiscal year 2018, which was sufficient to meet the yearly target of addressing one-third of the system.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Gainesville Regional Utilities	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes; GRU has instituted a Continuous Improvement Program, which identifies the worst performing devices, circuits and most compromised primary voltage underground cable.	Yes	The facilities are on an eight-year cycle for all lines and includes visual, sound, and bore, and below ground line inspection to 18 inches around the base of each pole.	122 transmission poles were inspected 2018. GRU inspected 4,644 distribution poles in 2018.	No transmission poles were rejected; however, one transmission pole was identified for replacement for hardening. 37 (0.8%) distribution poles failed due to shell rot, internal decay, and decayed tops.	43 distribution poles were replaced in 2018, ranging in size from 30 feet to 50 feet Class 3 to Class 6.	The VMP includes 560 miles of overhead distribution lines on a three-year cycle. The VMP includes an herbicide program and standards from NESC, ANSI A300, and Shigo-Tree Pruning.	The VMP is an on going and year round program. 100% of the transmission facilities were inspected in 2018, with 145 trees identified for trimming and /or removal. 200 distribution circuit miles were trimmed in 2018.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Green Cove Springs, City of	Yes	Yes	Yes, all facilities are installed a minimum 8 inches above the roadway.	Yes	Yes	The City does not have transmission lines as defined by 69kV and above. The City will continue to inspect and replace poles over the next three years. After that, the City will begin a more regular pole inspection program.	In 2018, the City planned to inspect 25% of its poles and actually inspected approximately 1,400 or 30% of its poles.	In 2018, 77 (6%) wood distribution poles were replaced. The poles failed visual inspection due to rot and split tops.	The poles that were replaced ranged from 35 feet to 65 feet, all Class 2.	The City contracts annually to trim 100% of the system three-phase primary circuits including all sub-transmission and distribution feeder facilities. Problem trees are trimmed and removed as identified.	100% of system was trimmed in 2018. PURC held two vegetation management workshops in 2007 and 2009 and the City has a copy of the report and will use the information.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Havana, Town of	Yes	No. Participating in PURC granular wind research study through the Florida Municipal Electric Assoc.	Non-coastal utility; therefore storm surge is not an issue	Yes	Yes	Total system is 1,173 poles; inspected several times annually using sound and probe method.	100% planned and completed in 2018.	12 (1.02%) poles failed inspection.	All 12 poles were replaced. The poles ranged from 30 feet to 50 feet, Class 3 to Class 4. Hurricane Michael caused the Town to replace 26 additional poles ranging from 30 feet to 50 feet, Class 3 to Class 4.	Written policy requires one-third of entire system trimmed annually.	33% of the system was trimmed in 2018.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Homestead Energy Services	Yes	Yes	Yes. Participating in PURC's study on the conversion of overhead to underground facilities through Florida Municipal Electric Association.	Yes	Yes	All transmission poles concrete. With the use of drone technology, the transmission system will be on a three-year cycle performing thermographic inspection. The distribution facilities are on an eight-year cycle using sound and bore and loading evaluations and the annual thermographic inspection was completed April 2018.	50% of the transmission system is scheduled for inspection during the 2018/2019 fiscal year. Approximately 50% of the distribution poles were inspected during 2016/2017 fiscal year. HES did not inspect any distribution poles during the 2017/2018 fiscal year.	2 (1.5%) transmission poles of the 135 poles inspected failed inspection due to cracks in the concrete top. 101 (2.1%) distribution poles of the 4,713 poles inspected failed inspections due to ground rot, upper roof rot and split tops. In addition, following Hurricane Irma, 162 wooden poles were replaced due to vegetation, high winds, or poles failing previous inspections.	Two transmission poles are scheduled for remediation in 2019. Based on the results of the 2016 and 2017 inspections, HES reworked 8 poles, installed 4 poles ranging from 55 feet to 50 feet, Class 3 to Class 2, and replaced 83 poles ranging from 45 feet to 35 feet, Class 3 to Class 4. As a result of Hurricane Irma, HES replaced 162 poles with Class 2, Class 1, or concrete poles.	Trimming services are contracted out and entire system is trimmed on a two-year cycle. HES added an additional tree trimming crew at the end of 2016. There are no issues for transmission facilities.	HES enacted code changes, which require property owners to keep vegetation trimmed to maintain 6-feet of clearance from city utilities.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
JEA	Yes	Yes	Yes. Currently has written Storm Policy and associated procedures addressed for Category 3 storms or greater.	Yes	Yes	Transmission circuits are on a five-year cycle, except for the critical N-1 240kV, which is on a two-year cycle. Distribution poles are on an eight-year inspection cycle, using sound and bore with excavation.	22 transmission circuits (which includes many poles on each circuit) and 16 distribution circuits were inspected in 2018.	Based on 2018 inspection: 56 transmission wooden poles failed inspection and 13% distribution poles failed inspection due to ground decay, pole top decay, and middle decay.	In 2018, 50 transmission wood poles and 1,556 distribution poles were replaced. The poles listed as emergency poles (under 1%) are replaced immediately. Two poles failing the 2018 inspections were listed as emergency poles.	The transmission facilities are in accordance with NERC FAC-003-1. The distribution facilities are on a 2.5-year trim cycle as requested by their customers to improve reliability.	JEA fully completed all 2018 VM activities and is fully compliant with NERC standard for vegetation management. VMP activities are on schedule for 2019.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Keys Energy Services, City of Key West	Yes	Yes	Yes	Yes. The KEYS will ensure all future construction occurs adjacent to public roads, will relocate all primary high voltage facilities that are currently inaccessible over a three-year period, and will develop a multi-year program to relocate all secondary facilities that are currently inaccessible. Phase I was completed in 2018 and Phase II is expected to be completed in 2019. Phase III is a multi-year program.	Yes	The Keys does not have any wooden transmission poles. The concrete and metal transmission poles are inspected every two years by helicopter and infrared survey. 100% of the distribution poles were inspected in 2015 by Osmose, Inc.	An inspection of all transmission facilities was done in 2014. From the 2015 inspection, 5,823 concrete poles, 6,616 wooden, and 6 other type of distribution poles were inspected.	No transmission poles failed inspection. 70 (1.2%) concrete poles and 484 (7.3%) wooden poles failed inspection in 2015. The reasons for the failures are decayed top, excessive cracking, excessive spur cuts, hollow, mechanical damage, rotten ground rot, ground shell rot, wind shake, wood borers, woodpecker holes.	No transmission facilities failed inspection. The KEYS approved a multi-year contract to manufacture 485 new ductile iron poles, which was completed in 2018. Due to Hurricane Irma, 519 poles were replaced in 2017 and 98 poles were replaced in 2018.	The Keys' 241 miles 3 Phase distribution lines are on a two-year trim cycle and 68 miles of transmission lines are a quarterly cycle. The Keys tree crews remove all invasive trees in the rights-of-way and easements. The trees are cut to ground level and sprayed with an herbicide to prevent re-growth.	In 2018, the Keys had 1 feeder outages and 9 lateral outages due to trees. The Keys will strive to continue to improve its VMP to further reduce outages.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Kissimmee Utility Authority	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue. Low areas susceptible to flooding have been identified and are monitored.	Yes	Yes	All transmission and distribution inspections are outsourced to experienced pole inspector who utilizes sound and bore and ground-line excavation method for all wood poles. Transmission poles are inspected on a three-year cycle and distribution poles are inspected on an eight-year cycle.	No transmission poles were inspected in 2018 as it was a non-inspection year. 2,107 distribution poles were inspected in 2018, which is 14.6% of the system.	12 (0.5%) distribution poles failed inspection due to decayed top, exposed pocket, woodpecker holes, split top and shell rot. No new failures were identified during the transmission inspection.	No transmission poles were replaced and ten distribution poles were replaced in 2018. The distribution poles were 35 to 45 feet and range from Class 3 to Class 7.	KUA has a written Transmission Vegetation Management Plan (TVMT) where it conducts visual inspection of all transmission lines semi-annually. The guidelines for KUA's distribution facilities are on a three-year trim cycle.	100% required remediation during the transmission facilities inspection was completed in 2018. Approximately 104.1 miles (33%) of distribution facilities were inspected and remediated in 2018.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Lake Worth Utilities, City of	Yes	The facilities are not designed to be guided by the extreme loading standards on a system wide basis. However, CLW is guided by the extreme wind-loading standard for new construction, major planned work, etc. after December 10, 2006.	Underground distribution construction practices require installation of dead front pad mounted equipment in areas susceptible to flooding.	Yes	Yes	Visual inspections are performed on all CLW transmission facilities on an annual basis. The transmission poles are concrete and steel. CLW performs an inspection of the distribution facilities on an eight-year cycle. Pole tests include hammer sounding and pole prod penetration 6 inches below ground.	In 2018, CLW inspected 430 poles.	60 poles were deemed unsatisfactory in 2018. Poles are replaced when pole prod penetration exceeds 2 inches or there is evidence of pole top shell rot.	CLW replaced 43 poles in 2018, with 17 poles pending replacement.	CLW has an on-going VMP on a system wide, two-year cycle. Minimum clearance of 10 feet in any direction from CLW conductors is obtained.	Contractor attempts to get property owners permission to remove trees which are dead or defective and are a hazard; fast growing soft-wooded or weed trees, small trees which do not have value but will require trimming in the future, trees that are unsightly as a result of trimming and have no chance for future development, and trees that are non native and invasive.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Lakeland Electric	Yes	Yes. For all pole heights 60 feet and above; and meet or exceed Grade B construction below this height.	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	The facilities are on an eight-year inspection cycle using visual, sound and bore, with ground line excavation and in addition; visual inspection during normal course of daily activities. Lakeland Electric initiated its second eight-year cycle in 2017.	There were 81 (12.5%) transmission poles planned for inspection and 99 (15%) were completed. There were 7,080 (12.5%) distribution poles planned for inspection and 7,391 (13%) completed.	6 (6.1%) transmission poles failed inspection due to decay. 487 (6.6%) distribution poles failed inspection due to decay.	All poles recommended in 2018 were assessed for appropriate action. 15 distribution poles were reinforced and 413 distribution poles were replaced, repaired, or removed in 2018. 1,923 distribution poles were deferred to 2019. 1 transmission pole was repaired or replaced in 2018 and 49 replacements were deferred to 2019.	The facilities are on a three-year inspection cycle for transmission and distribution circuits. VMP also provides in between cycle trim to enhance reliability.	27 miles of 230kV transmission lines were inspected in 2018. 16.65 miles of 69kV transmission lines were inspected in 2018. LE completed 498 miles of distribution lines for 2018.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Leesburg, City of	Yes	Yes.	Leesburg is approximately 60 miles inland from the Atlantic and Gulf coasts and is not subject to major flooding or storm surge.	Yes	Yes. Foreign utility attachments are inspected on an eight-year cycle.	No transmission facilities. The Distribution facilities are on an eight-year cycle using visual, sound/bore, excavation method, and ground level strength test.	8,765 (76%) poles were inspected in 2018. The current inspection cycle was started in 2016.	331 (3.8%) poles failed inspection due to, but not limited to ground line rot, woodpecker damage, and other causes.	During 2018, 93 (28%) poles were replaced that failed inspection. In some areas, underground distribution infrastructure was installed in place of the rejected poles.	Four-year trim cycle for feeder and lateral circuits. Problem trees are trimmed or removed as identified.	In 2018, 48.5 miles of distribution lines were trimmed as planned.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Moore Haven, City of	Yes	At this time, the facilities are not designed to be guided by the extreme loading standards on a system wide basis. The City is participating in PURC granular wind research study through Florida Municipal Electric Assoc.	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	The City inspects all the distribution facilities annually by visual and sound inspections.	The City continuously inspected the distribution facilities in 2018 by visual and sound method. The City is one square mile and easily inspected during routine activities. The City does not own any transmission facilities. The City is upgrading its 3 Phase poles.	The City is working on the rear-of secondary, making them more accessible. The City has approximately 410 poles in the distribution system and streetlights.	The City replaced six 30-foot poles, six 35-foot poles, and, twenty-four 40-foot poles.	The City is continuous tree trimming in easements and rights-of-way. 100% of distribution system is trimmed each year.	The City expended approximately 20% of Electric Dept. Resources to vegetation management. All vegetation management is performed in house.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Mount Dora, City of	The City retained an engineering firm and developed construction standards for 12kV distribution poles.	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	A new construction standard was developed to use guy wires for all levels on poles. The standards for poles that the City developed in 2012 reflect the impact of pole attachments on pole loading capacity.	The City does not own any transmission lines. Distribution lines and structures are visually inspected for cracks and a sounding technique used to determine rot annually. The City engaged a contractor to inspect and treat all wood poles on December 5, 2017. The project was completed in March 2018.	The City completed 100% of planned distribution inspections in 2018.	The City had 83 distribution poles in 2018 that failed inspection. The reasons for the failures were tree trimming needed, remove vegetation, loose or missing guy, damaged or missing guy guard, rotten or damaged pole, missing or damaged squirrel guard, insulators or grounds, blown lightning arrestor, and damaged pole attachment.	The city had 1,775 wooden poles as of January 1, 2018. The City's table shows 32 wooden poles were replaced. The wooden replaced range from 25 feet to 45 feet. The wooden poles were replaced with 30 to 45 feet concrete, fiberglass, or steel poles.	An outside contractor working two crews 40 hours per week completes tree trimming on a 12-month cycle.	The City trimmed trees on a 12-month cycle, and removed limbs from trees in rights-of-way and easements that could create clearance problems.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
New Smyrna Beach Utilities Commission, City of	Yes	Yes	Yes. The City only installs stainless steel dead front pad mounted transformers in its system and existing pad mounted transformers are being upgraded to dead front stainless steel transformers.	Yes	Yes	The transmission and distribution facilities are on an eight-year inspection cycle. Additionally, distribution facilities are inspected as part of the City's normal maintenance when patrolling distribution facilities.	0 (0%) transmission poles were inspected during 2018 as 100% transmission poles were inspected in 2012 and 18% were inspected in 2017. 1,501 (12.5%) distribution poles were inspected in 2018.	0 (0%) transmission poles were rejected in 2018. 56 (3.7%) distribution poles failed inspection due to decay, split top, and woodpecker damage.	No transmission poles were replaced in 2018. The City replaced/ repaired 12 distribution poles. The poles are sizes 30-45 feet and Class 4-5.	The City maintains three crews on continuous basis to do main feeder and hot spot trimming. The City mows its transmission lines on a yearly basis.	The City trimmed approximately 30% of distribution system in 2017, and performed clear cutting on 0% of the transmission lines.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Newberry, City of	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	Distribution poles are inspected on an eight-year inspection cycle at ground line for deterioration, entire upper part of the pole for cracks, and soundness of upper part of pole.	The City inspected 200 (12.82%) of 1,560 the poles in 2018.	10 (5%) of the poles were rejected due to ground rot from the inspection in 2018.	Ten distribution poles were replaced in 2018: six wooden poles were 45 feet, Class 3 and four were 40 feet, Class 3. They were replaced with 45 and 40 feet, Class 3 CCA poles.	The City trims all distribution lines on a three-year trim cycle, with attention given to problem trees during the same cycle. Problem trees not in the rights-of-way are addressed with the property owner.	One third of distribution facilities are trimmed each year to obtain a three-year cycle.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Ocala Electric Utility, City of	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	The City inspects its system on an eight-year inspection cycle, which include above ground inspection, sounding, boring, excavation, chipping, internal treatment, and evaluation of each pole to determine strength. 2015 is the first year in the second eight-year cycle.	No transmission poles were inspected in 2018, since 100% were inspected in 2015. The transmission poles will again be inspected in 2023, which is the beginning of the next cycle. 4,974 (15.6%) of the 31,884 wood distribution poles were inspected in 2018.	44 (0.9%) distribution poles failed inspection due to shell rot, decayed top, split top, woodpecker holes, and other reasons.	11 (0.2%) of the distribution poles were braced and 44 (0.9%) poles were replaced. Ocala noted that poles remediated by bracing are not counted in the rejection numbers, since they still meet the standards with the immediate bracing applied. Bracing occurs at the time of inspection.	The City is on a four-year trim cycle for distribution and three-year trim cycle for transmission, with additional pruning over areas allowed minimal trimming. In 2013, an IVM style-pruning program was implemented which uses manual, mechanical, and chemical control methods for managing brush.	In 2018, the City trimmed one-fourth of the distribution system and one-third of the transmission system. Ocala cleared several rights-of-way with traditional aerial lift crews and the implementation of a mechanical trimmer and mulcher. In addition, Ocala used an herbicide contract applicator for vegetation control along the power lines.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Orlando Utilities Commission, City Orlando	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	OUC facilities are on an eight-year inspection cycle, which includes visual inspection, sounding & boring, excavation, removal of exterior decay, ground line and internal treatments.	OUC planned 6,200 (12%) inspection for distribution and transmission facilities and completed 6,376 (13%) inspections in 2018.	167 poles (2.7%) failed inspection. Failure causes include: decay and others.	4 poles were deemed priority replacement, 4 were completed. There are no poles pending restoration using reinforcing truss. The remaining 163 will be replaced in 2019.	222 miles of transmission facilities are on a three-year trim cycle. 1,323 miles of distribution facilities are on a three-year trim cycle. OUC follows safety methods in ANSI A300 & Z133.1.	For 2018, 421 distribution miles were planned and 100% were completed. For 2018, 112 transmission miles were planned and 36% were completed. OUC noted that its transmission VMP allows until May 30, 2019, for completion.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Quincy, City of	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue	Yes	Yes	The City's pole inspection procedures include visual and sound and bore methods for an inspection cycle of eight years.	Visual inspections were carried out on all 2,869 distribution poles in 2018. Detailed inspections were carried out on all 31 transmission poles and 162 distribution poles for 2018. All transmission poles are made of concrete and found to be in good condition.	8 distribution poles (0.3%) failed inspection. The poles showed signs of rotting around the base of the pole or the top of the pole. The poles were replaced with wood poles. No transmission poles failed inspection. The City replaced 133 poles due to Hurricane Michael.	148 (5%) distribution poles were replaced. The poles ranged from 25 feet to 55 feet, Class 3 to Class 7. The extra poles were replaced due to relocations and vehicle accidents.	The City trims its electric system rights-of-way on a regular basis using in-house crews. The City strives to trim 25% of the system per year.	Approximately 47 miles (54%) of vegetation trimming was planned and completed on the distribution system in 2018. 100% of the City's transmission lines were inspected in 2018.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Reedy Creek Improvement District	Yes. The District has less than 2 miles of overhead distribution lines and roughly 297 miles of underground distribution.	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	The District does not have any foreign attachments on the facilities.	The District performs a visual inspection monthly of its overhead transmission system and inspects the distribution facilities every eight years.	All distribution poles were inspected and treated by an outside contractor in 2013. The District has 19 wooden distribution poles. No inspections were completed in 2018.	All distribution poles passed inspection.	The District's transmission system has no wooden poles in service. The transmission system includes approximately 14 miles of overhead transmission ROW. The distribution system is essentially an underground system with 19 wooden poles.	14 miles of transmission rights-of-way is ridden monthly for visual inspection. The District contracts tree trimming each spring to clear any issues on rights-of-way.	Periodic inspections in 2018 yielded minimal instances of vegetation encroachment. In each scenario, tree-trimming services were engaged to remove any concerns. The District continues its long-term vegetation management plan to ensure all clearances remain within acceptable tolerances.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Starke, City of	Yes	Yes. The City participates in the PURC granular wind research study through the Florida Municipal Electric Association.	Non-coastal utility; therefore storm surge is not an issue.	Yes	The City is in the process of studying this issue.	The City is in process of having all their poles GIS mapped. To date, they have approximately two-thirds of their poles mapped and inspected. The poles are replaced as needed on a visual basis.	One third of the City's poles (1,248) poles were inspected.	In 2018, 78 poles (6.25%) were found to be rotten or damage caused by a vehicle accident.	The City has no transmission poles. The following distribution poles were replaced in 2018: 16 (1.28%), Class 2, 30 feet, 6 (0.48%) Class 2, 35 feet, 38 (3.04%) Class 2, 40 feet, 7 (0.56%) Class 2, 45 feet and 11 (0.88%) Class 7, 25 feet.	The City trims their trees upon visual inspection. The City trims 33% of their electrical distribution system annually.	The City trims distribution lines throughout the year as needed and when applicable removes dead or decayed trees. The City trimmed 33% of distribution system in 2018. The City will use the information from PURC's VM workshops to improve their VM.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Tallahassee, City of	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue. However, the City's Electric Purdom Generation Station in St. Marks is subject to storm surge and flooding. There is a plan in place to address flooding and storm surge that is reviewed annually.	Yes	Yes	Every 8 years a new pole inspection cycle is initiated to inspect all poles over a three-year period. The inspection includes visual inspection, sound & bore, internal & fumigant treatment, assessment & evaluation for strength standards. The City performs a climbing and physical inspection of its transmission structures on a five-year cycle.	No transmission poles were inspected in 2018. All distribution poles were inspected from FY 2013-FY 2014. No distribution pole inspections were performed in 2018. The next cycle will begin in 2021 for both transmission and distribution poles and structures.	The annual climbing inspection identified 0 (0.0%) transmission poles/structures to be rejected.	0 (0.0%) transmission poles were replaced. The City replaced 887 distribution poles and structures in 2018. The poles ranged from 35 feet to 65 feet, Classes 2 to 4. During Hurricane Michael, 307 poles were changed, varying from 35 feet to 60 feet, Class 2 to Class 4.	The transmission facilities are on a 3-year trim cycle with target of 25 to 32 feet clearance on lines. The distribution facilities are on an 18-month trim cycle on overhead lines to 6 feet clearances.	The transmission rights-of-way & easements were mowed in 2018. Approximately 1,037 miles of overhead distribution lines were managed in 2017 and 2018.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Wauchula, City of	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	The City of Wauchula has a third-party contractor inspect its substation yearly and 60% of distribution poles in 2017-18.	The City of Wauchula has a third-party contractor inspect its substation yearly and 60% of distribution poles in 2017-2018. This will complete the City's inspection cycle.	Approximately 4% (out of 3,200 poles) have failed due to poles rotting.	70 distribution poles were replaced in 2018 ranging from 35 feet to 55 feet, all Class 4.	The policy on vegetation management is on a three-year cycle that includes trimming trees and herbicides for vines.	The City completes one-third of the system every year. The City also uses PURC's 2007 and 2009 vegetation management reports to help improve its practices.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructure s and major thoroughfares									
Williston, City of	Yes	Yes	Not applicable, the City of Williston is a non-costal utility; therefore storm surge/flooding is not an issue.	Yes	As a result of employee turnover within the management ranks the City has not established any data on pole reliability, pole loading capacity, or engineering standards and procedures for attachments by others to our distribution poles. The City anticipates outsourcing this function in the 2018–2019 budget years.	All distribution poles are visual and sound inspection on a three-year cycle. The city uses both the bore method and the visual and sound method to inspect poles.	33% of 1,102 poles were inspected in 2018. This is the first year of the three-year cycle.	In 2018, no poles were found defective during the inspection.	No poles were replaced in 2018 since no poles were found defective.	The distribution lines are on a three-year trim cycle with attention to problem trees during the same cycle. Any problem tree not in rights-of-way is addressed to the property owner to correct.	One-third of distribution facilities are trimmed every year to obtain a three-year cycle.

**Appendix B. Summary of Municipal Electric Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Winter Park, City of	The City has an initiative to put its entire distribution system underground. The City requires new residential service to be installed underground and to date, 73.6% of the system is underground.	The facilities are not designed to meet extreme loading standards on a system wide basis. The City participates in PURC's granular wind research study through Florida Municipal Electric Association.	Non-coastal utility; therefore storm surge is not an issue	Yes	Yes	The City does not own transmission poles or lines. The distribution facilities are on an eight-year cycle, which the City is evaluating the cycle for length. The inspection includes visual, assessment prior to climbing and sounding with a hammer.	The City does not own transmission poles. The City did not conduct pole inspections in 2018; however, WPE routinely inspect poles that are involved with daily jobs and work orders.	The City replaced one pole in 2018. The cause was damaged during a seasonal storm.	Based on the 2007 full system inspections, all repairs and replacements have been made. The City routinely inspects the poles involved with daily jobs and work orders. The pole replaced was a 30 feet Class 1 wood pole. This pole was replaced with a 30 feet concrete light pole.	Vegetation management is performed on a three-year trim cycle, which is augmented as needed between cycles.	The trimming crews trimmed approximately 51.0 miles of distribution lines in 2018. The City is using the PURC 2007 and 2009 reports to improve VMP practices.

Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to Rule 25-6.0343, F.A.C. – Calendar Year 2018

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Central Florida Electric Cooperative, Inc.	Yes	Central Florida's facilities are not designed to be guided by the extreme loading standards on a system wide basis. However, the wind standard for Central Florida's facilities is between 100 mph inland and 130 mph at the coast.	Central Florida continues to participation in evaluation of PURC study to determine effectiveness of relocating to underground.	Yes	Yes	100% of the transmission facilities are inspected annually using above and ground level inspections. The distribution facilities are on a nine-year cycle for inspections using above and ground level inspections.	Central Florida planned and inspected 43 miles of the transmission facilities in 2018. 18,328 (21%) distribution poles were inspected in 2018.	Of the 18,328 distribution poles inspected in 2018, 338 (1.84%) were rejected. These poles are scheduled to be replaced.	290 distribution poles were replaced in 2018. The poles varied from 30 feet to 40 feet, Class 3 to Class 7.	Trees are trimmed or removed within 15 feet of main lines, taps, and guys on a five-year plan.	In 2018, 665 miles of 3,131 miles of primary overhead line on the system were trimmed.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Choctawhatchee Electric Cooperative, Inc.	Yes	Yes	Yes	Yes	Yes. Inspect and physically count every attachment on a three-year cycle.	The Coop inspects new construction of power lines on a monthly basis and has an eight-year cycle to cover all poles.	During 2018, 6,596 poles or 11% of 60,077 total poles were inspected.	667 poles or 10.1% of the poles failed inspection ranging from spit top to wood rot.	56.5% of 667 failed poles were replaced.	Current rights-of-way program is to cut, mow, or otherwise manage 20% of its rights-of-way on an annual basis. Standard cutting is 10 feet on either side of primary from ground to sky. In 2015, the Coop increased the standard overhead primary line easement area from 20 feet to 30 feet.	In 2018, 434 miles were cut on primary lines and the Coop worked to remove problem tress under the primary lines, which reduces hot-spotting requirements between cycles. The Company also established herbicidal spraying program.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Clay Electric Cooperative, Inc.	Yes	Clay's distribution facilities are not designed to be guided by the extreme wind loading standards specified by Figure 250-2(d) except as required by rule 250-C, but Clay's transmission facilities are guided by the extreme wind loading. Clay is participating in the PURC's granular wind research study through the Florida Municipal Electric Association.	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	Clay's transmission facilities are on a ten-year cycle, which includes sound/bore techniques, excavation, climbing inspection (four-year cycle), and ground (two-year) patrol. Clay's distribution system is now on a ten-year cycle using excavation, sound and bore at the ground line and visual inspection (five-year cycle) and system feeder inspection excluding ground line (five-year cycle).	Clay completed the transmission ground patrol inspection in 2016 & the next inspection will be done in 2026. In 2018, Clay performed the system feeder and ground line pole inspection. The total number of distribution poles inspected was 44,275.	The inspection found 11 (0.4%) transmission poles inspected required some form of maintenance and 3 (0.1%) poles resulted in rejects. 20,597 (47%) distribution poles were rejected due to various reasons including ground rot, top decay, holes high, and split.	8 (0.3%) transmission poles required maintenance. 3 (0.1%) transmission poles were replaced with 55 to 75 feet, Class 1 poles. 3,601 distribution poles were replaced with poles ranging from 20 feet to 55 feet, Class 2 to 7.	Clay's VMP for the transmission facilities is on a three-year cycle and includes mowing, herbicide spraying and systematic re-cutting. Clay's VMP for the distribution facilities is on a three-year cycle for city, a four-year cycle for urban and five-year cycle for rural and includes mowing spraying and re-cutting.	In 2018, Clay mowed 53.78 miles, sprayed 54.88 miles, and recut 49.77 miles of its transmission rights-of-way. In 2018, Clay mowed 2,611.60 miles, sprayed 2,380.78 miles, and recut 2,048.9 miles of its distribution circuits.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Escambia River Electric Cooperative	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	Escambia River inspects its distribution facilities on an eight-year cycle using visual, sound, and bore techniques in accordance with RUS standards.	4,800 (14%) distribution poles were planned and 2,027 (6%) inspections were completed in 2018. Because of the higher than normal trend of pole rejection, Escambia River focused its time and resources in the repair and replacement of the rejected poles. Escambia River does not own any transmission poles.	Approximately 171 poles failed inspection in 2018. The common cause was pole rot at the top and bottom of the poles.	In 2018, Escambia River replaced 67 poles from the 2017 inspection and 161 (94%) poles from the 2018 inspection. These numbers reflect various pole sizes and Classes.	Escambia River's distribution facilities are on a five-year trim cycle. Distribution lines and rights-of-way is cleared 20 feet; 10 feet on each side.	In 2018, approximately 340 miles (21.6%) of the power lines were trimmed with 315 miles (20%) planned.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Florida Keys Electric Cooperative Association, Inc.	Yes	The facilities were not designed to the extreme loading standards on a system wide basis. However, the Company has adopted the extreme wind loading standard in April 2007.	Yes	Yes	Yes	The company inspects 100% of the transmission structures annually by helicopter. The distribution poles are on an eight-year cycle and was completed in 2010. All 10,698 distribution poles have been inspected and all 1,003 rejects have been replaced. Inspections and treatment resumed in 2015 and was completed in 2018.	100% of the transmission poles were inspected in 2018 by helicopter. 3,422 (25%) distribution poles were inspected in 2018.	No transmission structures failed inspections in 2018. 114 transmission water structures were inspected in 2017 and are scheduled for foundation repairs in 2020. 158 (4.6%) distribution poles failed inspection in 2018.	No transmission poles were replaced in 2018. 158 distribution poles that failed inspection in 2018 are scheduled to be replaced in 2019.	100% of the transmission system is inspected and trimmed annually. The distribution system is on a three-year trimming cycle. The trade-a-tree program was implemented in 2007 for problem trees within the rights-of-way.	100% of the transmission facilities are inspected annually and VM tasks are performed as needed. In addition, all substation properties are inspected annually and VM tasks are performed as needed. Approximately 230 circuit miles of distribution lines were trimmed in 2018. Additional distribution spot trimming was conducted as necessary.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Glades Electric Cooperative, Inc.	Yes	Yes	Non-coastal utility; therefore storm surge is not an issue; GEC participated in a workshop hosted by Florida Catastrophic Planning that addressed flooding and storm surges.	Yes	Yes	The facilities are on a 10-year sound and bore inspection cycle with excavation inspection cycle for all wood poles in addition to System Improvement Plan inspections.	100% of total 83 miles of transmission lines were planned and completed by visual inspections. 2,502 miles of distribution lines and 125 miles of underground distribution lines were planned and inspected in 2017. No inspections were performed in 2018.	705 (6%) distribution poles failed during the 2017 inspection due to decay, rot and top splits.	532 distribution poles rejected in the 2017 inspection were replaced. The distribution poles ranged from 35 to 40 feet, Class 5 to 6 and were replaced with 35 to 40 feet, Class 3 or Class 5 poles.	All trimming is on a three-year cycle. The rights-of-way are trimmed for 10-foot clearance on both sides, and herbicide treatment is used where needed.	GEC trimmed 623 miles of distribution circuits in 2018. The transmission rights-of-way are inspected annually and trimmed if necessary. Vegetation growth is not an issue for the transmission lines.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Gulf Coast Electric Cooperative, Inc.	Not bound by the extreme loading standards due to system is 99.9% under the 60 feet extreme wind load requirements.	The method of construction used by GCEC does, however, meet the “design to withstand, without conductors, extreme wind loading in Rule 250C applied in any direction on the structure.”	Yes. GCEC continues to evaluate the PURC study to determine effectiveness of relocating to underground	Yes	Yes	No transmission lines. Performs general distribution pole inspections on an eight-year cycle. Also, GECE inspects underground transformers and other padmount equipment on a four-year cycle.	GCEC inspected 5,805 (11.4%) distribution poles, in 2018. Also, in 2018, GCEC inspected 481 padmount transformers, which accounts for approximately 14.7% of padmounted equipment.	Of the 5,805 poles inspected in 2018, 162 (2.79%) poles were rejected. The poles were rejected due to decay/split tops, ground rot, heart rot, and mechanical damage.	In 2018, GCEC replaced 76 wooden poles prior to Hurricane Michael.	GCEC owns approximately 2,165 miles of overhead and 442 miles of underground distribution lines. GCEC strives to clear the entire ROW on a five-year cycle. GCEC clears between 20 and 30 feet width, from ground to sky.	GCEC trimmed approximately 350 miles of ROW in 2018. GCEC also works closely with property owners for danger tree removal.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Lee County Electric Cooperative, Inc.	Yes	Yes	Yes. The majority of LCEC's underground facilities, excluding conduits and cables, are at or above existing/ surrounding grade.	Yes	Yes	Transmission facilities are inspected ever two years for 138kV systems. The inspections are done by climbing or the use of a bucket truck. The distribution facilities are on a two-year visual inspection cycle and on a ten-year climbing inspection cycle for splitting, cracking, decay, twisting, and bird damage.	In 2018, 1,342 (57.8) transmission poles were inspected, which was 100% of the poles that were scheduled. 36,102 (22.3%) distribution poles were inspected, which was over 100.0% of the inspections scheduled.	24 (1.8%) transmission poles failed inspection due to rot. 369 (0.8%) distribution poles failed inspection due to rot/split top, out of plumb, and woodpecker damage.	20 transmission poles were replaced with concrete and steel poles. 83 (2.4%) distribution poles were repaired through trussing and patching. 286 poles were replaced in 2018. The sizes varied by Class 1 to Class 6.	VMP strategies include cultural, mechanical, & chemical treatments and the plan is on a six-year cycle for 1 Phase distribution facilities and three years for 2 & 3 Phase distribution facilities. The 138kV transmission systems are on an annual cycle.	LCEC completed 7.6 miles (100% planned) of Transmission trimming, 537 miles (100% planned) three-phase trimming, and 428 (100% planned) miles of single-phase trimming,

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Okefenoke Rural Electric Membership Cooperative	Yes	The facilities are not designed to be guided by the extreme loading standards on a system wide basis. OREMC is participating in PURC's granular wind research study.	OREMC is continuing the evaluation of the PURC study to determine effectiveness of relocating to underground.	Yes	Yes	OREMC owns no transmission facilities. The inspections for the distribution systems include visual, sound/bore with excavations, and chemical treatment. The pole inspections are on an eight-year cycle.	In 2018, OREMC performed inspections on 7,465 (12.8%) poles. OREMC has 58,499 wood poles as of December 31, 2018.	In 2018, 54 (0.72%) poles were rejected. The cause of the rejection was ground rot and above ground damage.	The 54 poles failing inspection in 2018 are scheduled to be replaced in 2019. During the course of other projects, 904 new poles were added and 629 poles were retired in 2018.	Vegetation control practices consist of complete clearing to the ground line, trimming, and herbicides. The VMP is on a five-year trim cycle. OREMC utilizes contractors for its VM programs.	OREMC planned 500 miles of rights-of-way for trimming and completed 516 miles in 2018. Also in 2018, contractors sprayed 403 miles of rights-of-way.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Peace River Electric Cooperative, Inc.	Yes	The facilities are not designed to be guided by the extreme loading standards on a system wide basis. Peace River is currently participating in PURC granular wind research study.	Peace River is continuing the evaluation of PURC study to determine effectiveness of relocating to underground to prevent storm damage and outages.	Yes	Yes	Peace River currently uses RDUP bulletin 1730B-121 for planned inspection and maintenance. The facilities are located in Decay Zone 5 and are inspected on an eight-year cycle. The transmission poles are visually inspected every two years.	391 transmission (170 concrete, 3 steel, 218 wooden) poles are inspected every two years. 8,722 (15.3%) of 56,996 distribution poles were inspected.	Peace River did not replace any transmission poles in 2018. 244 (2.79%) distribution poles were rejected in 2018.	Peace River replaced 168 poles in 2018. The distribution poles receiving remediation in 2018 varied from 25 feet to 50 feet, Class 1 to 7.	Peace River utilized guidelines in either RUS bulletins or other materials available through RUS. In addition, Peace River uses a Georgia Rights-of-way program, which uses a ground to sky method by removing trees. The VMP is on a four- to five-year cycle.	In 2018, the Company completed rights-of-way maintenance on 1,101 (39.26%) of its 2,804 miles of overhead distribution.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Sumter Electric Cooperative, Inc.	Yes	Transmission and distribution facilities are designed to withstand winds of 110 MPH in accordance with 2017 NESC extreme wind load	Non-coastal utility; therefore storm surge is not an issue.	Yes	Yes	The transmission facilities are on a five-year cycle using ground line visual inspections, which includes sounding and boring and excavation. The distribution facilities are on an eight-year cycle using sound, bore, & excavation tests.	106 (9.77%) transmission poles were planned and inspected in 2018. 17,555 (12.8%) distribution poles were planned and inspected in 2018. 7,783 (12.8%) distribution underground structures were planned and inspected in 2018.	Zero transmission poles failed inspection. 2,385 (14%) distribution poles failed inspection. The causes are due to ground rot and top deterioration.	34 (100%) wooden transmission poles were replaced with spun-concrete poles. 1,386 (58.1%) distribution poles were replaced. The transmission and distribution poles ranged from 25 to 80 feet and Class 1 to Class 7.	Distribution and transmission systems are on a three-year trim cycle for feeder and laterals. SECO's VM includes tree trim cycles, tree removals, and herbicide treatment with a minimum 10-foot clearance and a desired clearance of 15-feet from its distribution system. The transmission system specification is a 30-foot clearance.	In 2018, SECO trimmed 492 miles for its cycle and an extra 36 miles of its distribution system. In addition, an extra five miles were trimmed on its transmission system. SECO removed 25,168 trees in 2018.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Suwannee Valley Electric Cooperative, Inc.	Yes	SVEC facilities are not designed to be guided by the extreme loading standards on a system wide basis. SVEC participates in PURC wind study.	Non-coastal utility; therefore storm surge is not an issue	Yes	Yes	SVEC inspects all structures on an eight-year cycle using sound/bore and visual inspection procedures.	SVEC inspected five (100%) transmission structures in 2018. 14,500 (16%) distribution structures were inspected in 2018.	768 (7%) inspections of distribution poles failed due to ground line decay, excessive splitting, & woodpecker damage. Zero inspections of transmission poles failed.	1,010 (7%) distribution poles of total inspected were remediated by ground line treatment and 724 (5%) distribution poles were replaced. Zero transmission structures were remediated.	SVEC's facilities are on a four- to three-year inspection cycle includes cutting, spraying and visual on as-needed basis.	In 2018, 821 (21%) miles were cut and 931 miles rights-of-way sprayed. 1,295 (33%) miles are planned for cutting and 821 miles are planned for spraying in 2019.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Talquin Electric Cooperative, Inc.	Yes	Yes	Talquin has a very small percentage subject to storm surge. The anchoring system that Talquin applied to padmount transformers did not perform well during Hurricane Michael. Talquin is now applying a different method used by other utilities. The method involves attaching the surface equipment to a below grade vault that acts as the anchoring system.	Yes	Yes, inspecting on a five-year cycle.	Annual inspections in house of transmission lines are performed by checking the pole, hardware, and conductors. An outside pole-treating contractor inspects distribution and transmission poles each year. The poles are inspected on eight year rotation since 2007.	8,304 distribution poles were inspected in 2018. There were no transmission poles scheduled for inspection in 2018.	276 (3.32%) of the distribution poles inspected were rejected.	The priority poles were replaced and the rejected poles are being inspected and repaired or replaced if necessary. Talquin replaces 30-foot Class 7 poles with stronger 35-foot Class 6 poles with guys and 35-foot Class 6 poles with 40 foot Class 4 poles as a minimum standard.	Talquin maintains its rights-of-way by mechanical cutting, mowing, and herbicidal applications.	559 (19%) miles of distribution and 9.15 (16%) miles of transmission rights-of-way were treated in 2018. In addition, Talquin received 1,468 non-routine requests for tree maintenance.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Tri-County Electric Cooperative, Inc.	Yes	Yes	The current standard practice is to restrict electrification of flood prone areas. Due to natural landscape within area, storm surge issues are low.	Yes	Yes	The transmission facilities are inspected on a five-year cycle by both ground line and visual inspections. The distribution facilities are on an eight-year cycle using both ground line and visual inspections.	During 2018, the transmission poles were visually inspected. Tri-County inspected 4,834 (8.6%) distribution poles in 2018.	211 (4.3%) distribution poles were rejected. The Coop repaired 112 broken ground wires.	The 211-rejected distribution poles found during the 2018 inspection, which required replacement, are in the process of being changed out.	The Coop attempts to acquire 30-foot rights-of-way easement for new construction. The entire width of the obtained ROW easement is cleared from ground level to a maximum height of 60 feet in order to minimize vegetation and ROW interference with the facilities.	In 2018, approximately 360 distribution miles were trimmed and sprayed. The Coop has approximately 2,783 miles of overhead distribution lines in four counties.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
West Florida Electric Cooperative Association, Inc.	Yes	Yes.	Non-coastal utility; therefore, storm surge is not an issue. Some areas in territory are subject to flooding. In these areas, line design is modified to compensate for known flooding conditions.	Yes	Yes. General inspections are completed on an eight-year cycle.	West Florida continues to use RUS Bulletin 1730B-121 as its guideline for pole maintenance and inspection. In addition, WFEC contracted with Osmose Utilities Services to enhance the pole inspection program.	Prior to Hurricane Michael, WFEC inspected 7% of its poles. During 2018, Osmose inspected 5,937 poles.	Out of the 7% inspected, 5% required maintenance or replacement. The rejected percentage of the Osmose inspection was 2.4%.	During 2018, 2 miles of single phase line was converted to 3 phase to correct loading issues. WFEC re-insulated and upgraded approximately 20 miles of distribution lines from 12.5kV to 25kV. During the re-insulation procedure, every pole is upgraded to 25kV and the pole replaced, if necessary.	West Florida's VM includes ground to sky side trimming along with mechanical mowing and tree removal.	During 2018, WFEC mowed and side trimmed 784 miles of its distribution system. Also, WFEC chemically sprayed approximately 685 miles of rights-of-way. Approximately 632 miles will be trimmed and mowed during 2019.

**Appendix C. Summary of Rural Electric Cooperative Utility Reports Pursuant to
Rule 25-6.0343, F.A.C. – Calendar Year 2018**

Utility	The extent to which Standards of construction address:					Transmission & Distribution Facility Inspections				Vegetation Management Plan (VMP)	
	Guided by Extreme Wind Loading per Figure 250-2(d)		Effects of flooding & storm surges on UG and OH distribution facilities	Placement of distribution facilities to facilitate safe and efficient access	Written safety, pole reliability, pole loading capacity and engineering standards for attachments	Description of policies, guidelines, practices, procedures, cycles, and pole selection	Number and percent of poles and structures planned and completed	Number and percent of poles and structures failing inspections with reasons	Number and percent of poles and structures by class replaced or remediated with description	Description of policies, guidelines, practices, procedures, tree removals, with sufficient explanation	Quantity, level, and scope of planned and completed for transmission and distribution
	Major Planned Work Expansion, Rebuild or Relocation	Targeted Critical Infrastructures and major thoroughfares									
Withlacoochee River Electric Cooperative, Inc.	Yes	The facilities are not designed to be guided by the extreme wind loading standards on a system wide basis. However, most new construction, major planned work and targeted critical infrastructure meets the design criteria that comply with the standards.	Yes. In addition to using stainless steel construction for pad mounted equipment, WREC uses Ethylene-Propylene-Rubber insulated cable for all underground primary distribution installation.	Yes. In 2018, WREC relocated 120 miles of overhead primary lines from rear lots to street, changing out hundreds of older poles and facilities; this will continue until older areas are all upgraded.	Yes	WREC inspects the transmission and distribution facilities annually (approximately 3,007 miles for 2018) by line patrol, physical and visual inspections.	68 miles or 100% of transmission facilities were inspected by walking, riding or aerial patrol. 2,939 miles of distribution facilities were inspected annually by line patrol, voltage conversion, rights-of-way, and Strategic Targeted Action and Repair (S.T.A.R.).	OSMOSE (a contractor for pole inspection and treatment) found 6.2% poles with pole rot and 1.0% poles were rejected in 2003 to 2004. WREC discontinued this type of inspection/treatment plan and now data is unavailable on the exact failure rates.	5,771 wooden, composite, cement, concrete, steel, aluminum, and fiberglass poles ranging in size from 12 to 100 feet were added; 3,764 poles were retired.	In 2017, WREC contracted with an arborist company to assist with the aggressive VMP that includes problem tree removal, horizontal/vertical clearances and under-brush to ground. WREC maintains over 180 overhead feeder circuits (over 7,100 miles of line) on a trim cycle between four to five years.	All transmission lines are inspected annually. 4.5 miles of transmission rights-of-way issues were addressed in 2018. In addition, during 2018, WREC addressed 4,472 rights-of-way service orders ranging from trimming a single account to trimming an entire subdivision or area.