Shawna Senko

From:	Amy Williams <awilliams@uswatercorp.net></awilliams@uswatercorp.net>
Sent:	Tuesday, January 21, 2014 3:16 PM
То:	Filings@psc.state.fl.us
Cc:	Ron Derossett
Subject:	Docket No.: 130194-WS-Lakeside Waterworks, Inc.
Attachments:	Responce to PSC First Staff Data Req. 1-9-14 with invoices.pdf

FPSC,

Please allow this submission on behalf of Lakeside Waterworks, Inc. in regards to Docket No. 130194-WS.

Any questions or concerns please feel free to contact my office directly at (727) 848-8292 ext. 239

Thank You,

Amy N. Williams

Enterprise Systems - Accounting Admin

U.S. Water Services Corporation 4939 Cross Bayou Blvd. New Port Richey, FL 34652-3434 P: (727) 848-8292 ext. 239 F: (727) 849-7809

LAKESIDE WATERWORKS, INC.

January 20, 2014

Ms. Carlotta Stauffer, Commission Clerk, Office of Commission Clerk 2540 Shumard Oak Boulevard Tallahassee, Florida, 32399-0850. Via: Email to Commission Clerk Via: Fedex – Hard Copies

RE: Docket No. 130194-WS – Lakeside Waterworks, Inc. Response to PSC First Staff Data Request 1/9/2014

2. USW management fee covers – Pg. 22 of contract

3. Yr 1 - 2013; Yr 2 -2014; Yr 3 - 2015

4. How PSC Expense fee \$10,000 was calculated? PSC Fee was estimated and included within the "Organization Cost" category regarding transfer and also rate case. Current expense totals \$2,300 in PSC Water and Wastewater PSC fees paid for Transfer and Rate Case Fees. This estimate has been adjusted to \$2,300.

5. Lift Station rehabilitation includes – \$79,000 how this figure was calculated; Lift Station # 3 needs to have control panel replaced -\$8,000; New discharge piping and fittings- \$10,000; pump discharge piping, rails and base-\$8,000 Pumps - \$12,000. Lift Station #4 needs to have control panel replaced -\$8,000; New discharge piping and fittings- \$10,000; pump discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps - \$12,000; Pumps discharge piping, rails and base-\$8,000 Pumps discharge piping, rails and piping, rails and

6. Electrical Control Panel – New or replacement. How amount was calculated (\$15,000). The control panel needs to house 4 starters, 6 breakers, timers, switches, surge protection, emergency power hook ups, web based SCADA components (\$ 5,000) and labor to build and install the panel (\$10,000).

7. Document expense of \$4,265.30- Date repairs made –Jan 19, 2013 completed; Needed because the existing air header was leaking air which prevented efficient treatment and added to the plant cost and exerted addition wear and tear on the blower system; The old chlorine pump worked erratically, causing ineffective disinfection needed to satisfy FDEP requirements -; Invoices #787750 & 773330 attached.

8. Document expense of \$659.83 - Posted to expense account and removed from CIP list

9. Expense of \$5,296.43 - Date repairs made –December 17, 2012 completed ; Mercoid switches were installed on the hydro tank to regulate the system pressure more efficiently; The addition of 4 chlorine pumps was needed to maintain efficient chlorine residuals in the distribution system per FDEP requirement; Installed saddle tap to feed chlorine to the wells prior to the ground storage tank to maintain a chlorine residual for disinfection and algae removal from the GST; Installed new conduit from the HSP to electrical panel; Chlorine injection at the wells enhance the chlorine residuals throughout

LAKESIDE WATERWORKS, INC.

the treatment system which maintains disinfection levels and discourages algae growth in the system components; Pressure switch repaired to maintain proper pressure in the distribution system - ; Invoice # 787751 attached.

10. Expense of \$244.94 - Date repairs made – February 28, 2013 completed ; Needed because – Decant pumps is needed to remove the clear supernatant from the digester to allow for efficient residuals handling ; Invoice # 776178 attached.

11. Expense of \$3,047.21 –3/12/2013 completed - Starter replacement at WWTP (\$751.38) invoice # 780147; *Revised Total Expenses-* \$751.38 Invoice attached.

12. Expense of \$1,024.64 was an estimated expense, actual invoice expense was \$1,232.68- Date repairs made 12/9/2013 Emergency call out for 6" water main break ; Invoice #788662 attached.

13. Expense of \$1,960 – The estimated cost of each meter is \$98.00, we will replace 10% of the meters on hand (20) and at a cost of \$1,960, this expense is for the estimated replacement of water meters that have exceeded 10 years or 1,000,000 gallons through the meter, recommended by the AWWA; Meter replacement is for 10% per year as recommended by the AWWA and is ongoing. There were no invoices for meter replacements for 2013.

14. Expense of \$121,000 – Estimate based on experience and historical data – Replace aeration Basin – \$30,000; Install new air header – \$25,000; Install new blowers - \$5,000; Install new flow splitter and barscreen \$8,000; Install new 5,000 gal digester - \$6,000; Demo old Plant- \$8,000; Rehab spray field - \$15,000; Upgrade electrical control panel- \$5,000; Rerate plant from .0 to .02 MGD, Eng & Permitting - \$14,000; Miscellaneous site work \$5,000. No invoices associated with this expense. It is anticipated to follow the CIP schedule as outlined.

15. Is there any overlap between the projects identified in Lakeside CIP Budget and any other capital projects? There are no other capital projects scheduled during the Lakeside CIP projects as outlined.

If you have any further request please contact this office.

Sincerely v Derer

Lakeside WW / Shangri-La CIP		Year 1		Year 2		Year 3
		2013		2014		2015
Includes PSC Fee	Organizational Cost (Orginally Estimated - Actual to date \$2,300)	\$ 2,300.00				
	Replace the aeration basins, install new air headers and blowers, Install					
WWTP	new flow splitter and bar screen on headworks, install new 5,000 gallon digester, demo the old plant, rehabilitate the spray field, upgrade the			121,000.00		
	electrical power system, rerate the plant from a 0.050 MGD to 0.020				8	
	MGD wich includes design and permitting and miscellaneous site work.					
Lift Station	Rehabilitate two (2) lift stations (Does not include wetwell lining)	 undika	\$	79,000.00		in the second
WTP	Replace generator housing		\$	2,000.00		
	Install Electrical Control Panel for two wells and four high service pumps		\$	15,000.00		
WWTP	Repair Air Header, diffusers, installed new chlorine pump,	\$ 4,265.30			-	
WTP	Installed Mercoid switch on Hydro Tank 2; Installed 4 new chlorine pumps; Installed saddle tap for new chlorine injection site; Install new electrical conduit; Chlorine injection installed at both wells;repaired	\$ 5,296.43				
	existing pressure switch.					
WWTP	Install Decant Pump	\$ 244.94				
w/ww/ls	Misc. Repairs (Corrected)	\$ 751.38				
Distribution	Replace 10' of 6" water pipe (Corrected to actual cost)	\$ 1,232.68		_		
Meters	Replace 20 meters per year	\$ -	\$	1,960.00	\$	1,960.
		\$ 14,090.73	Ś	218,960.00	\$	1,960.

U.S. Water Sorvicos Corporation

4939 Cross Bayou Blvd. New Port Richey, FL 34652

Bill To

Lakeside Waterworks, Inc. Attn: Amy Williams 4939 Cross Bayou Boulevard New Port Richey, FL 34652

Invoice

Invoice #	787751
Date	12/2/2013
Due Date	1/17/2014
Account #	2535
P.O. No.	

All service pricing anticipates payment by Check or ACH. Due to additional costs incurred, services paid by credit card will require an additional "pass through" 3% processing fee in order to be accepted.

				Pro	oject		
				2535-09 W	TP Upgrades	1	
Date		Descriptio	on		Quantity	Rate	Amount
וזארואבן	WTP UPGRADES Installed new site glass. Installed (2) ne Ran new wire and conduit. Cleaned up Changed out liquid level switch on AVI Installed (4) new stemmer pumps and n Installed 4-way alternator. Replaced ba Repaired fence. Replaced brackets in gr Did walk through with Gary. Materials to Complete Scope of Service Labor to Complete Scope of Service	panel. L. mounted on ad breaker, ground store	i wall.		1 1	3,098.03 2,198.40	3,098.03 2,198.40
rlease remit p	payment to the above address. We app	preciate yo	ur business!	Total			\$5,296.43
Phone i				Payme	ents/Cre	dits	\$-5,296.43
727-848-82	292 727-848-7701			Bala	nce Du	le	\$0.00

01:10:2014



Bill To

Lakeside Waterworks, Inc. Attn: Amy Williams 4939 Cross Bayou Boulevard New Port Richey, FL 34652

Invoice

Invoice #	784970
Date	10/15/2013
Due Date	11/14/2013
Account #	2535
P.O. No.	

All service pricing anticipates payment by Check or ACH. Due to additional costs incurred, services paid by credit card will require an additional "pass through" 3% ¹ processing fee in order to be accepted.

				Project		
			2535-07 bad 3	pole breaker on I	HSP#1	
Date		Descriptio	חנ	Quantity	Rate	Amount
	Emergency Call. HSP #1 short cyc Arrived at site and removed jumper separate breaker. Cleaned contacto mercoids. Found locked up pump, Tradesman Maintenance Technician Installed new 60amp, 3-pole breake Tradesman Circuit Breaker	r wire someone ors on starter tha , due to bad beau	at welded together. Reset pressure on rings. Found bad breaker.	all 3 3 1 1	57.91 52.01 57.91 272.16	173.73 156.03 57.91 272.16
Please rem	it payment to the above address. W	e appreciate ye	our business! To	tal		\$659.83
Phor	ne# Fax#		Pa	yments/Cre	edits	\$0.00
727-848	8-8292 727-848-7701		B	alance D	ue	\$659.83



Bill To

Lakeside Waterworks, Inc. Attn: Amy Williams 4939 Cross Bayou Boulevard New Port Richey, FL 34652

Invoice

Invoice #	788662
Date	12/31/2013
Due Date	1/30/2014
Account #	2535
P.O. No.	

1

All service pricing anticipates payment by Check or ACH. Due to additional costs incurred, services paid by credit card will require an additional "pass through" 3% processing fee in order to be accepted.

		[/ Pr	oject	_	
			2535 -28 E/C 6" v	vater break at b	oridge	
Date		Descriptio	n	Quantity	Rate	Amount
12/9/2013	and mega lugs. Tradesman Maintenance Technician Maintenance Technician	45 broke, cut o	nut and replaced with new MJ 45, sleeves (N/C), (6) Sigma PVC restr slee6, (2)	4 4 4 1 1	57.91 52.01 52.01 584.96	231.64 208.04 208.04 584.96
Please remi	t payment to the above address. We	appreciate yo	Tota	I		\$1,232.68
Phon	e# Fax#		Payn	nents/Cre	dits	\$0.00
727-848	-8292 727-848-7701		Bal	ance Di	ue	\$1,232.68



Services Corporation

4939 Cross Bayou Blvd. New Port Richey, FL 34652

Bill To

Lakeside Waterworks, Inc. Attn: Amy Williams 4939 Cross Bayou Boulevard New Port Richey, FL 34652

Invoice

Invoice #	776178
Date	2/28/2013
Due Date	4/6/2013
Account #	2535
P.O. No.	

All service pricing anticipates payment by Check or ACH. Due to additional costs incurred, services paid by credit card will require an additional "pass through" 3% processing fee in order to be accepted.

1

			Project				
			2535-	12 Install Dec	ant pump		
Date		Descri	otion	Qty or Hrs	Unit	Rate	Amount
	Installed	decant pump.					
	Decant p	ump		1	LS	244.94	244.94
				t			
Disease		to the above address. We app	raalata vaur busingst				
r lease rem	n payment	to the above address, we app	rectate your business:	Total			\$244.94
Phor	ne #	Fax#		Payme	ents/Cre	dits	\$-2 44.94
727-848	3-8292	727-848-7701		Bala	nce Di	Je	\$ 0.00

05142013



Bill To

Lakeside Waterworks, Inc. Attn: Amy Williams 4939 Cross Bayou Boulevard New Port Richey, FL 34652

Invoice

Invoice #	780147
Date	6/24/2013
Due Date	7/24/2013
Account #	2535
P.O. No.	

All service pricing anticipates payment by Check or ACH. Due to additional costs incurred, services paid by credit card will require an additional "pass through" 3% processing fee in order to be accepted.

		Project				
		2535-1	9 #1 starter re	placement		
Date	Descrip	otion	Qty or Hrs	Unit	Rate	Amount
	Installed new Siemens starter for an emer	gency call lift station alarm.				
3/12/2013	Tradesman Siemens Starter		2 1	Hours LS	57.91 635.56	115.82 635.56
Please remit	payment to the above address. We appr	eciate your business!	Total			\$751.38
Phone	e # Fax #		Payme	ents/Cree	dits	\$-751.38
727-848-	8292 727-848-7701		Bala	nce Du	le	\$0.00

09132013



4939 Cross Bayou Blvd.

New Port Richey, FL 34652

Bill To

Lakeside Waterworks, Inc. Attn: Amy Williams 4939 Cross Bayou Boulevard New Port Richey, FL 34652

Invoice

/ Invoice #	773330				
Date	12/20/2012				
Due Date	1/19/2013				
Account #	2535				
P.O. No.					

All service pricing anticipates payment by Check or ACH. Due to additional costs incurred, services paid by credit card will require an additional "pass through" 3% processing fee in order to be accepted.

		Project					
		2535-05 repair air header					
Date	Descrip	otion	Qty or Hrs	Unit	Rate	Amount	
12/3/2012 12/13/2012	Repair air header. Removed old part on diffuser and replace Tradesman Materials to Complete Scope of Service Replaced worn out hose for last diffuser Tradesman Materials to Complete Scope of Service		4	Hours LS Hours LS	57.91 59.00 57.91 53.10	231.64 59.00 231.64 53.10	
Please remi	t payment to the above address. We app	reciate your business!	Total			\$575.38	
Phon	e# Fax#		Payme	ents/Cre	dits	\$-575.38	
727-848-8292 727-848-7701			Balance Due			\$0.00	

03:04/2013



Bill To

Lakeside Waterworks, Inc. Attn: Amy Williams 4939 Cross Bayou Boulevard New Port Richey, FL 34652

Invoice

Invoice #	787750			
Date	12/2/2013			
Due Date	1/17/2014			
Account #	2535			
P.O. No.				

All service pricing anticipates payment by Check or ACH. Due to additional costs incurred, services paid by credit card will require an additional "pass through" 3% processing fee in order to be accepted.

			Project				
			2535	-08 WW	TP Upgrades	3	
Date	Description		Quantity	Rate	Amount		
1/10/13	WWTP UPGRADES Repaired (4) diffusers and manifol Welded broken handrails. Welded Re-painted rusted areas on handrai Repaired air header. Installed (2) installed steel. Did walk through with Gary. Materials to Complete Scope of Se Labor to Complete Scope of Servi	I walkways and ils and weld repa new stenner pun ervice ce	reinforced. airs. nps and removed wood kick plates	s and (1	1,711.39 1,978.56	1,711.39 1,978.56
Please remit payment to the above address. We appreciate your business!		Toțtal			\$3,689.95		
Phone	e# Fax#			Payments/Credits s		\$0.00	
727-848-8292 727-848-7701			Balance Due 53,			\$3,689.95	