WASTEWATER MALFUNCTION / ABNORMAL EVENT REPORT

This form is provided for your convenience only. You may complete this form and email to SD-AbnormalEvents@dep.state.fl.us. If the spill is greater than 1000 gallons you MUST call the State Watch Office at 1-800-320-0519. All items with an asterisk (*) are required by rule and must be completed.

*FACILITY NAME: KW Resort Utilities		*FACILITY TYPE: Choose One		
*Permit Number: FLA014951		*County: Choose One		
*REPORTER NAME: CALVIN BATLLE		*RESPONSIBLE PARTY: KW RESORT UTILITIES		
*Reporter Address:		*Responsible Party Address: 6630 FRONT ST		
*Reporter Phone: 3057804354		*Responsible Part	*Responsible Party Phone: 3052953301	
*DEP: *DATE:12/21/15 *TIME:		3: 0930 *PERSON CONTACTED: Matt SEMCHESKI		
*State Watch Office: *Date: N/A *Time:		: N/A INCIDENT NUMBER:		
Spill Information				
*SPILL CHARACTERISTIC	*Sourc		*Area Affected	
■ UNTREATED/RAW	_{TION #} <u>L2A</u>	Surge Tank	STORM WATER	
PARTIALLY TREATED MANHOL	E	AERATION TANK	Surface Water/	
☐ TREATED ☐ FORCE M	IAIN/GRAVITY LINE	☐ CLARIFIER	GROUND	
☐ REUSE/RECLAIMED ☐ DISPOSAI	. System	☐ DIGESTER	☐ CONTAINMENT AREA	
OTHER OTHER		CHLORINE CONTACT T	ANK OTHER/	
*AMOUNT OF DISCHARGE: 700 GALLONS *AMOUNT RECOVERED: GALLONS *ONGOING: *CEASED: ** *PHYSICAL LOCATION/ ADDRESS/ LATITUDE & LONGITUDE: INTERSECTION OF 5TH ST AND 7TH AVE				
* Malfunction/Cause				
PUMP FAILURE	I LINE BREAK		<u>Weather</u>	
BLOWER FAILURE	FATS/OILS/GREASE B	LOCKAGE	☐ LIGHTNING	
SWITCH/TIMER FAILURE	ILURE OTHER CLOG OR BLOC		HEAVY RAINFALL	
☐ CLARIFIER FAILURE ☐ POWER OUTAGE/FAIL		URE	HIGH WINDS	
☐ FILTER BYPASS/FAILURE ☐ ACCIDENT			TROPICAL STORM:	
DISINFECTION SYSTEM FAILURE	UNKNOWN	•	HURRICANE:	
OTHER OUTSIDE CONTRACTO		R	OTHER:	
PVC PIPE CRACKED AT CHECK VALVE ON DISCHARGE LINE				
* Effluent Limit Violations				
CL ₂ MG/L	TURBIDITY	NTU	PHSU	
TSSMG/L	NO ₃ MG/L		CBOD ₅ MG/L	
OTHER	FECAL COLIFORMS_	CFU/100ML [ABNORMAL FLOW MGD	
* Corrective / Remedial Action Being Taken				
LINE REPAIRED	CONTAINED ON-SITE		RESTORED POWER	
DISINFECTED WITH LIME		SURFACE WATERS IMPACTED)	AUXILIARY POWER SYSTEM ON-LINE	
■ WASHED DOWN	SIGNS POSTED NEAR	•	BACK-UP ON-LINE	
☐ VAC TRUCK/DESTINATION	REPAIRED/REPLACE			
* REMEDIAL ACTIONS BEING TAKEN / ESTIMATED TIME FOR COMPLETION OF REPAIRS:				
PVC REPLACED				

PREVENTATIVE PLANS/MEASURES

PLEASE DESCRIBE HOW YOU INTEND TO PREVENT SIMILAR OCCURRENCES IN THE FUTURE:

CHECK ALL CONNECTIONS/PIPING ON LIFST STATIONS