

080268

RECEIVED-FPSC
09 MAR -2 PM 4: 54

February 25, 2009

COMMISSION
CLERK

Florida Public Service Commission
Office of Commission Clerk
2540 Shumard Oak Boulevard
Tallahassee, Florida 32399-0850

Subject: The Application for Transfer of Facilities of Springside Water and Wastewater Systems to FIMC Hideaway, Inc.


To Whom It May Concern:

To the extent our August 16, 2008 letter constitutes a formal objection to the above transfer of facilities of Springside water and wastewater systems to FIMC Hideaway, Inc., we hereby withdraw our objections, if the transfer is approved by the Commission pursuant to the terms and conditions of the Settlement Agreement entered into by and between FIMC Hideaway, Inc., Par Utilities, Inc. and Fred Loughmiller. We agree with the Settlement Agreement and urge the Commission to approve the Settlement Agreement and make the transfer conditioned upon the terms of the Agreement, with the understanding that the water storage tank was inspected and cleaned during the week of February 10, 2009. Further, it is our understanding that the tank began leaking after it was cleaned, but that the tank was repaired on February 23, 2009. The repair was performed by Two-Fold Water Engineering in accordance with the attached repair procedures which we are told is in compliance with Florida Department of Environmental Protection standards.

Sincerely,


Betty Butler


(352) 493-7351


Claudette LaFortune

(352) 493-7755


Ken Dietrich

(352) 490-7848


Gary Benedict

(352) 493-2454

DOCUMENT NUMBER-DATE
01679 MAR-28
FPSC-COMMISSION CLERK

Two-Fold Water Engineering
P.O. Box 767 Melrose, FL 32666
Melrose 352-475-2248 Gainesville 352-332-9911

Water and Wastewater Treatment

Complete Backflow Service

February 24, 2009

Public Service Council
Attn: Steve Reilly

Re: Tank at Springside
Chiefland, Florida

The hydropneumatic potable water tank which serves both the Springside & Hideaway communities was repaired on Monday the 23rd of February.

The residents were notified of the interruption in service and placed on a precautionary boil-water notice when the water was restored on Monday afternoon.

The repair was made on the inside of the tank (thus the interruption of service). The welder placed a small patch, roughly 8" x 10" over the pinhole leak and welded it shut.

The engineer will be including this repair in his report form the inspection and cleaning that was done of February 10th, 2009.

If you have any questions about the cleaning or repair please call me at 352-745-1022.

Sincerely,

Rick Tisdale

RT:ls
