



John T. Butler
Managing Attorney
Florida Power & Light Company
700 Universe Boulevard
Juno Beach, FL 33408-0420
(561) 304-5639
(561) 691-7135 (Facsimile)
E-mail: john.butler@fpl.com

January 19, 2011

Ms. Ann Cole
 Commission Clerk
 Florida Public Service Commission
 2540 Shumard Oak Blvd.
 Tallahassee, FL 32399-0850

Re: Docket No. 110001-EI

Dear Ms. Cole:

As requested by the Commission Staff, Florida Power & Light Company hereby files the original and ten (10) copies of the GPIF Actual Unit Performance Data Schedules (Original Sheets 6.202.001 to 6.202.042) covering the month of December 2010. These schedules are being filed at the same time but separately from its monthly filing of the A Schedules.

Sincerely,

 John T. Butler

OM _____
 PA _____
 CR _____
 KCL _____
 LAD _____
 SC _____
 ADM _____
 DPC _____
 CLK _____

Copy to: All parties of record

DOCUMENT NUMBER-DATE
 00474 JAN 20 =
 FPSC-COMMISSION CLERK


CERTIFICATE OF SERVICE
Docket No. 110001-EI

I HEREBY CERTIFY that a true and correct copy of the foregoing has been furnished by overnight delivery (*) or United States mail this 19th day of January, 2011, to the following:

<p>Lisa Bennett, Esq.* Division of Legal Services Florida Public Service Commission 2540 Shumard Oak Blvd Tallahassee, Florida 32399-0850 <u>LBENNETT@PSC.STATE.FL.US</u></p>	<p>J. R. Kelly, Esq. Patricia Christensen, Esq. Charles Beck, Esq. Office of Public Counsel c/o The Florida Legislature 111 West Madison Street, Room 812 Tallahassee, Florida 32399 <u>Kelly.jr@leg.state.fl.us</u> <u>Christensen.patty@leg.state.fl.us</u> <u>beck.charles@leg.state.fl.us</u></p>
<p>James D. Beasley, Esq J. Jeffrey Wahlen, Esq. Ausley & McMullen Attorneys for Tampa Electric P.O. Box 391 Tallahassee, Florida 32302 <u>jbeasley@ausley.com</u> <u>jwahlen@ausley.com</u></p>	<p>John T. Burnett, Esq. Progress Energy Service Company, LLC P.O. Box 14042 St. Petersburg, Florida 33733-4042 <u>john.burnett@pgnmail.com</u></p>
<p>John W. McWhirter, Jr., Esq McWhirter & Davidson, P.A. Attorneys for FIPUG P.O. Box 3350 Tampa, Florida 33602 <u>jmcwhirter@mac-law.com</u></p>	<p>Beth Keating, Esq. Gunster Firm Attorneys for FPUC 215 So. Monroe St., Suite 618 Tallahassee, Florida 32301- 1804 <u>bkeating@gunster.com</u></p>
<p>Jeffrey A. Stone, Esq. Russell A. Badders, Esq. Beggs & Lane Attorneys for Gulf Power 501 Commendancia Street Pensacola, FL 32502 <u>jas@beggslane.com</u> <u>rab@beggslane.com</u></p>	<p>James W. Brew, Esq Attorney for White Springs Brickfield, Burchette, Ritts & Stone, The P.C 1025 Thomas Jefferson Street, NW Eighth Floor, West Tower Washington, DC 2007-5201 <u>jbrew@bbrslaw.com</u></p>

<p>Robert Scheffel Wright, Esq Jay T. LaVia, III, Esq Young van Assenderp, P.A Attorneys for Florida Retail Federation and City of Marianna 225 South Adams Street, Suite 200 Tallahassee, FL 32301 swright@yvlaw.net jlavia@yvlaw.net</p>	<p>Jon C. Moyle, Esq. and Vicki Kaufman, Esq. Keefe, Anchors Gordon & Moyle, P.A. 118 N. Gadsden St. Tallahassee, FL 32301 Co-Counsel for FIPUG vkaufman@kagmlaw.com jmoyle@kagmlaw.com</p>
<p>Cecilia Bradley, Esq. Senior Assistant Attorney General Office of the Attorney General The Capitol - PL01 Tallahassee, FL 32399-1050 cecilia.bradley@myfloridalegal.com</p>	<p>Michael Barrett Division of Legal Services Florida Public Service Commission 2540 Shumard Oak Blvd Tallahassee, Florida 32399-0850 MBARRETT@PSC.STATE.FL.US</p>
<p>Karen S. White, Civ USAF Allan Jungels, Capt, USAF Utility Litigation & Negotiation Team Staff Attorney AFLOA/JACL-ULT/FLOA/JACL-ULT 139 Barnes Drive, Suite 1 Tyndall AFB, FL 32403-5317 Attorneys for the Federal Executive Agencies Karen.White@tyndall.af.mil Allan.Jungels@tyndall.af.mil</p>	<p>Patrick K. Wiggins, Esq. Attorneys for AFFIRM P.O. Drawer 1657 Tallahassee, FL 32302 wigglaw@gmail.com</p>

By:



John T. Butler
Fla. Bar No. 283479

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

FROM: Jan-2010 TO: Dec-2010

DOCKET NO. 15147000
= 02 MW 4/400
00474 JAN 20

PLANT / UNIT: FORT MYERS 02 PFM 02

	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1. EAF (%)	99.3	91.6	80.4	94.4	71.3	96.9	96.2	96.4	88.3	94.1	98.6	97.1	92
2. PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3. SH	744	672	601.87	696.68	744	720	744	744	720	744	721	744	8595.55
4. RSH	0	0	0	0	0	0	0	0	0	0	0	0	0
5. UH	0	0	141.13	23.32	0	0	0	0	0	0	0	0	164.45
6. POH	0	0	0	0	0	0	0	0	0	0	0	0	0
7. FOH	0	0	0	0	0	0	0	0	0	0	0	0	0
8. MOH	0	0	141.13	23.32	0	0	0	0	0	0	0	0	164.45
9. PPOH	0	0	0	0	0	0	0	0	453.2	65.27	0	0	518.47
10. LR PP (MW)	0	0	0	0	0	0	0	0	245.75	221.84	0	0	242.74
11. PFOH	8.88	9.32	11.5	7.17	180.73	91.63	9.1	8.13	1.8	0	17.53	42.28	388.08
12. LR PF (MW)	58	209.7	221.84	555.63	152.61	221.84	191.01	221.84	221.84	0	221.84	417.32	212.3
13. PMOH	27.93	328.08	4.85	37.03	623.8	42.13	158.72	151.27	0	195.5	41.52	48.98	1659.82
14. LR PM (MW)	221.83	221.84	746.97	511.81	411.53	221.84	228.91	221.83	0	225.86	221.84	221.84	302.28
15. NSC	1330	1330	1330	1330	1330	1330	1330	1330	1330	1330	1330	1330	1330
16. OPER BTU (MBTU)	5080670	4564056	4535819	5357377	4437386	5855209	6001692	5872806	5367050	5736645	5413480	5249726	63471916
17. NET GEN	690034	627378	621208	732167	527442	811302	830753	811955	745230	795326	740946	703651	8637392
18. ANOHR (BTU/KWH)	7363	7275	7302	7317	8413	7217	7224	7233	7202	7213	7306	7461	7349
19. NOF (%)	69.7	70.2	77.6	79	53.3	84.7	84	82.1	77.8	80.4	77.3	71.1	75.6
20. NPC (MW)	1440	1440	1440	1440	1440	1440	1440	1440	1440	1440	1570	1570	1462

21. ANOHR EQUATION	ANOHR = A + B (N.O.F.) A = 0 B = 0												
--------------------	--	--	--	--	--	--	--	--	--	--	--	--	--

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

ACTUAL PERFORMANCE DATA
COMPANY: FLORIDA POWER AND LIGHT
FROM: Jan-2010 TO: Dec-2010

		PLANT / UNIT: MANATEE UNIT 3 CC 03											PM3 03	
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1.	EAF (%)	99	89.3	98.3	43.9	97.8	100	84.9	99.9	96.6	97.3	74.4	76.6	88.3
2.	PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3.	SH	744	672	743	315.45	744	720	744	744	720	744	664.37	744	8298.82
4.	RSH	0	0	0	250.32	0	0	0	0	0	0	0	0	250.32
5.	UH	0	0	0	154.23	0	0	0	0	0	0	56.63	0	210.86
6.	POH	0	0	0	0	0	0	0	0	0	0	0	0	0
7.	FOH	0	0	0	0	0	0	0	0	0	0	0	0	0
8.	MOH	0	0	0	0	0	0	0	0	0	0	0	0	0
9.	PPOH	27.33	287.25	50.07	518.22	66.27	0	0	0	0	0	547	134.9	1631.03
10.	LR PP (MW)	260.25	260.25	260.25	675.58	260.25	0	0	0	0	0	246.66	260.25	387.65
11.	PFOH	4.98	0	0	247.03	0	0	32.27	1.65	1.22	0	0	0.9	288.05
12.	LR PF (MW)	191.26	0	0	283.51	0	0	297.03	457	56	0	0	116	282.94
13.	PMOH	0	0	0	0	0	0	408	0	97.77	79.52	69.62	520.2	1175.1
14.	LR PM (MW)	0	0	0	0	0	0	263.63	0	260.25	260.25	821.34	280.55	303.65
15.	NSC	1041	1041	1041	1041	1041	1041	1041	1041	1041	1041	1041	1041	1041
16.	OPER BTU (MBTU)	3801517	3564952	4280626	1266628	4516144	4346119	3792438	4361285	3899095	3696890	2825201	3203650	43554545
17.	NET GEN	546428	518854	619957	182394	643269	615748	530409	613080	544201	518279	407960	461598	6202177
18.	ANOHR (BTU/KWH)	6957	6871	6905	6944	7021	7058	7150	7114	7165	7133	6925	6940	7022
19.	NOF (%)	70.6	74.2	80.2	55.5	83.1	82.2	68.5	79.2	72.6	66.9	59	59.6	71.8
20.	NPC (MW)	1109	1109	1109	1111	1111	1111	1111	1111	1111	1111	1187	1187	1123

21. ANOHR EQUATION

ANOHR = A + B (N.O.F.)

A = 0 B = 0

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 FROM: Jan-2010 TO: Dec-2010

		PLANT / UNIT: MARTIN-UNIT 8 08											PM8 08	
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1.	EAFF (%)	94.2	53.4	51.6	91.5	95.1	96.3	85.8	95.9	98	95.6	89.9	98.7	87.4
2.	PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3.	SH	739	455.72	559.43	720	744	720	720.75	715.02	720	744	721	744	8302.92
4.	RSH	5	0	20.48	0	0	0	23.25	28.98	0	0	0	0	77.72
5.	UH	0	216.28	163.09	0	0	0	0	0	0	0	0	0	379.36
6.	POH	0	216.28	163.08	0	0	0	0	0	0	0	0	0	379.37
7.	FOH	0	0	0	0	0	0	0	0	0	0	0	0	0
8.	MOH	0	0	0	0	0	0	0	0	0	0	0	0	0
9.	PPOH	0	344.1	579.92	42.77	0	0	216.68	120.32	0	105.2	84.22	0	1493.2
10.	LR PP (MW)	0	259.99	344.34	257.75	0	0	256.86	257.75	0	257.75	257.75	0	291.77
11.	PFOH	52.4	9.27	3.98	7.65	6.12	62.88	205.02	1.48	0	24.53	1.03	38.87	413.23
12.	LR PF (MW)	263.14	257.75	257.75	247.58	472.97	259.16	260.8	463	0	259.66	257.75	253.33	263.59
13.	PMOH	117.8	30.05	7.13	186.15	129	42.37	0	0	57.17	0	206.7	0	776.37
14.	LR PM (MW)	257.75	257.75	257.75	268.39	269.71	257.75	0	0	257.75	0	257.75	0	262.29
15.	NSC	1031	1031	1031	1031	1031	1031	1031	1031	1031	1031	1031	1031	1031
16.	OPER BTU (MBTU)	3344089	2092903	2177858	3672914	4313680	4232002	3737549	4059491	4013512	3481571	3543725	3931650	42600944
17.	NET GEN	454872	281033	301872	513820	602219	592520	519104	559252	553965	471906	495854	553006	5899423
18.	ANOHR (BTU/KWH)	7352	7447	7215	7148	7163	7142	7200	7259	7245	7378	7147	7110	7221
19.	NOF (%)	59.7	59.8	52.3	69.2	78.5	79.8	69.9	75.9	74.6	61.5	66.7	72.1	68.9
20.	NPC (MW)	1099	1099	1099	1105	1105	1105	1105	1105	1105	1105	1180	1180	1116

Solar
+ 75

21. ANOHR EQUATION

ANOHR = A + B (N.O.F.)

A = 0 B = 0

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

ACTUAL PERFORMANCE DATA
COMPANY: FLORIDA POWER AND LIGHT
FROM: Jan-2010 TO: Dec-2010

		PLANT / UNIT: SCHERER						PSG 04						
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1.	EAF (%)	48.3	0	8.5	94.4	94.2	100	95.1	100	99.9	95.3	100	100	78.4
2.	PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3.	SH	359.62	0	63	680.28	700.6	720	707.25	744	720	711.5	721	744	6871.25
4.	RSH	0	0	0	0	0	0	0	0	0	0	0	0	0
5.	UH	384.38	672	680	39.72	43.4	0	36.75	0	0	32.5	0	0	1888.75
6.	POH	384.38	672	680	39.72	0	0	0	0	0	0	0	0	1776.1
7.	FOH	0	0	0	0	0	0	36.75	0	0	0	0	0	36.75
8.	MOH	0	0	0	0	43.4	0	0	0	0	32.5	0	0	75.9
9.	PPOH	0	0	0	0	0	0	0	0	0	0	0	0	0
10.	LR PP (MW)	0	0	0	0	0	0	0	0	0	0	0	0	0
11.	PFOH	0	0	0	2.35	0	0	0	0.52	0	1.73	2.38	0	6.98
12.	LR PF (MW)	0	0	0	111	0	0	0	284.17	0	146.28	96.13	0	127.58
13.	PMOH	0	0	0	0	0	0	0	0	6	10.47	0	0	16.47
14.	LR PM (MW)	0	0	0	0	0	0	0	0	91	145.95	0	0	125.93
15.	NSC	846	846	846	846	846	846	846	846	846	846	846	846	846
16.	OPER BTU (MBTU)	3000132	0	559105	5161034	5626184	5778769	5700341	6091571	5816803	5541225	4288625	5699587	53263374
17.	NET GEN	293920	0	36558	525872	565256	590382	577767	609354	582853	554040	420558	555783	5312343
18.	ANOHR (BTU/KWH)	10207	0	15294	9814	9953	9788	9866	9997	9980	10001	10197	10255	10026
19.	NOF (%)	96.6	0	68.6	91.4	95.4	96.9	96.6	96.8	95.7	92	68.9	88.3	91.4
20.	NPC (MW)	882	882	882	869	869	869	869	869	869	869	882	882	874

21.	ANOHR EQUATION	ANOHR = A + B (N.O.F.)											
		A = 0 B = 0											

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
COMPANY: FLORIDA POWER AND LIGHT
FROM: Jan-2010 TO: Dec-2010

		PLANT / UNIT: ST LUCIE 01 PSL 01												
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1.	EAF (%)	100	100	100	11.5	0	9.4	79.8	77.1	93.8	100	100	100	72.6
2.	PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3.	SH	744	672	743	87.07	0	150.88	744	744	720	744	721	744	6813.95
4.	RSH	0	0	0	0	0	0	0	0	0	0	0	0	0
5.	UH	0	0	0	632.93	744	569.12	0	0	0	0	0	0	1946.05
6.	POH	0	0	0	632.93	744	312.45	0	0	0	0	0	0	1689.38
7.	FOH	0	0	0	0	0	256.67	0	0	0	0	0	0	256.67
8.	MOH	0	0	0	0	0	0	0	0	0	0	0	0	0
9.	PPOH	0	0	0	9.82	0	80.93	21.87	0	4.58	0	0	0	117.2
10.	LR PP (MW)	0	0	0	338.19	0	530.82	76.37	0	64.17	0	0	0	411.64
11.	PFOH	0	0	0	0	0	69.95	469.85	743.98	270.25	0	0	0	1554.03
12.	LR PF (MW)	0	0	0	0	0	386.18	264.26	192.01	137.47	0	0	0	213.11
13.	PMOH	0	0	0	0	0	0	0	0	0	0	0	0	0
14.	LR PM (MW)	0	0	0	0	0	0	0	0	0	0	0	0	0
15.	NSC	839	839	839	839	839	839	839	839	839	839	839	839	839
16.	OPER BTU (MBTU)	6849731	6186775	6397789	556268	0	616313	5469346	5298985	6216344	6850262	6638307	6850527	57930647
17.	NET GEN	641872	580455	588670	47211	0	49184	488429	468004	563301	633068	618747	642108	5321049
18.	ANOHR (BTU/KWH)	10671	10658	10868	11783	0	12531	11198	11323	11036	10821	10729	10669	10887
19.	NOF (%)	102.8	103	94.4	64.6	0	38.9	78.2	75	93.2	101.4	102.3	102.9	93.1
20.	NPC (MW)	853	853	853	839	839	839	839	839	839	839	839	839	843

21.	ANOHR EQUATION	ANOHR = A + B (N.O.F.) A = 0 B = 0											
-----	----------------	---------------------------------------	--	--	--	--	--	--	--	--	--	--	--

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
COMPANY: FLORIDA POWER AND LIGHT
FROM: Jan-2010 TO: Dec-2010

		PLANT / UNIT: ST LUCIE						02		PSL 02				
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1.	EAF (%)	97.4	100	100	75.5	100	100	99.1	100	98.2	100	99.8	100	97.5
2.	PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3.	SH	744	672	743	549.27	744	720	744	744	720	744	721	744	8589.27
4.	RSH	0	0	0	0	0	0	0	0	0	0	0	0	0
5.	UH	0	0	0	170.73	0	0	0	0	0	0	0	0	170.73
6.	POH	0	0	0	0	0	0	0	0	0	0	0	0	0
7.	FOH	0	0	0	170.73	0	0	0	0	0	0	0	0	170.73
8.	MOH	0	0	0	0	0	0	0	0	0	0	0	0	0
9.	PPOH	0	0	5.42	0	0	0	0	0	0	0	11.12	4.48	21.02
10.	LR PP (MW)	0	0	46.41	0	0	0	0	0	0	0	41.41	13.33	36.72
11.	PFOH	0	0	0	41.3	0	0	109.83	0	92.75	0	13.53	0	257.42
12.	LR PF (MW)	0	0	0	114.53	0	0	51.26	0	114.52	0	49.62	0	84.12
13.	PMOH	38.63	0	0	0	0	0	0	0	0	0	0	0	38.63
14.	LR PM (MW)	420.73	0	0	0	0	0	0	0	0	0	0	0	420.73
15.	NSC	839	839	839	839	839	839	839	839	839	839	839	839	839
16.	OPER BTU (MBTU)	6665812	6184342	6837780	5004286	6848050	6627286	6787142	6848559	6510180	6847343	6624438	6847918	78633136
17.	NET GEN	628140	582673	644228	467437	639917	615448	627039	639517	599656	635783	618645	643271	7339754
18.	ANOHR (BTU/KWH)	10646	10614	10614	10706	10701	10768	10824	10709	10857	10770	10708	10645	10713
19.	NOF (%)	100.3	103.3	103.3	101.4	102.5	101.9	100.5	102.5	99.3	101.9	102.3	103.1	101.9
20.	NPC (MW)	726	726	726	714	714	714	714	714	714	714	839	839	738

21. ANOHR EQUATION

ANOHR = A + B (N.O.F.)

A = 0 B = 0

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
COMPANY: FLORIDA POWER AND LIGHT
FROM: Jan-2010 TO: Dec-2010

		PLANT / UNIT: TURKEY POINT 03											PTN 03	
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1.	EAF (%)	100	97.1	100	100	100	99.5	100	100	75.3	0	58.9	100	85.8
2.	PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3.	SH	744	672	743	720	744	720	744	744	545.23	0	474.68	744	7594.92
4.	RSH	0	0	0	0	0	0	0	0	0	0	0	0	0
5.	UH	0	0	0	0	0	0	0	0	174.77	744	246.32	0	1165.08
6.	POH	0	0	0	0	0	0	0	0	96	744	96	0	936
7.	FOH	0	0	0	0	0	0	0	0	78.77	0	150.32	0	229.08
8.	MOH	0	0	0	0	0	0	0	0	0	0	0	0	0
9.	PPOH	0	37.95	0	0	0	0	0	0	12.95	0	101.27	0	152.17
10.	LR PP (MW)	0	350	0	0	0	0	0	0	5	0	224.99	0	237.45
11.	PFOH	0	0	0	0	0	65.58	0	0	11.92	0	50.3	0	127.8
12.	LR PF (MW)	0	0	0	0	0	35.88	0	0	192.95	0	239	0	130.47
13.	PMOH	0	0	0	0	0	0	0	0	0	0	0	0	0
14.	LR PM (MW)	0	0	0	0	0	0	0	0	0	0	0	0	0
15.	NSC	693	693	693	693	693	693	693	693	693	693	693	693	693
16.	OPER BTU (MBTU)	5830378	5121381	5820860	5644976	5833637	5625967	5833807	5833939	4250118	0	3333790	5833619	58962472
17.	NET GEN	543517	476181	541931	518824	525067	496013	518556	516200	378013	0	303829	546607	5364739
18.	ANOHR (BTU/KWH)	10727	10755	10741	10880	11110	11342	11250	11302	11243	0	10973	10672	10991
19.	NOF (%)	105.4	102.3	105.2	104	101.8	99.4	100.6	100.1	100	0	92.4	106	101.9
20.	NPC (MW)	717	717	717	693	693	693	693	693	693	693	693	693	699

21. ANOHR EQUATION

ANOHR = A + B (N.O.F.)
 A = 0 B = 0

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

ACTUAL PERFORMANCE DATA
COMPANY: FLORIDA POWER AND LIGHT
FROM: Jan-2010 TO: Dec-2010

		PLANT / UNIT: TURKEY POINT 04							PTN 04					
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1.	EAF (%)	87.8	100	100	99	100	100	100	98.3	84	100	97.1	74.8	95
2.	PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3.	SH	664.48	672	743	720	744	720	744	744	618.5	744	721	563.52	8398.5
4.	RSH	0	0	0	0	0	0	0	0	0	0	0	0	0
5.	UH	79.52	0	0	0	0	0	0	0	101.5	0	0	180.48	361.5
6.	POH	0	0	0	0	0	0	0	0	0	0	0	0	0
7.	FOH	79.52	0	0	0	0	0	0	0	101.5	0	0	180.48	361.5
8.	MOH	0	0	0	0	0	0	0	0	0	0	0	0	0
9.	PPOH	0	0	0	59.9	0	0	0	34	0	0	43.58	0	137.48
10.	LR PP (MW)	0	0	0	83	0	0	0	255	0	0	329.03	0	203.53
11.	PFOH	29.13	0	0	0	0	0	0	0	36.43	0	0	15.48	81.05
12.	LR PF (MW)	275.28	0	0	0	0	0	0	0	256.42	0	0	322.2	275.73
13.	PMOH	0	0	0	0	0	0	0	0	0	0	0	0	0
14.	LR PM (MW)	0	0	0	0	0	0	0	0	0	0	0	0	0
15.	NSC	693	693	693	693	693	693	693	693	693	693	693	693	693
16.	OPER BTU (MBTU)	5118442	5267352	5823633	5593619	5831546	5645051	5833958	5743678	4749673	5833129	5497900	4362120	65300101
17.	NET GEN	476427	491195	541466	511745	525981	502200	522313	510191	425706	534689	508414	407727	5958055
18.	ANOHR (BTU/KWH)	10743	10724	10755	10930	11087	11241	11169	11258	11157	10909	10814	10699	10960
19.	NOF (%)	103.5	105.5	105.2	102.6	102	100.6	101.3	99	99.3	103.7	101.8	104.4	102.4
20.	NPC (MW)	717	717	717	693	693	693	693	693	693	693	693	693	699

21. ANOHR EQUATION

ANOHR = A + B (N.O.F.)

A = 0 B = 0

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

ACTUAL PERFORMANCE DATA
COMPANY: FLORIDA POWER AND LIGHT
FROM: Jan-2010 TO: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 04

PSR 04

	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1. EAF (%)	99.3	98.9	38.5	73.4	96.4	100	98	97.3	97.9	96.4	98.6	98.7	91
2. PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3. SH	722.27	606.67	281.22	517.88	672.5	720	744	744	720	744	721	744	7937.53
4. RSH	21.73	65.33	6.57	39.65	71.5	0	0	0	0	0	0	0	204.78
5. UH	0	0	455.21	162.47	0	0	0	0	0	0	0	0	617.69
6. POH	0	0	455.22	147.63	0	0	0	0	0	0	0	0	602.85
7. FOH	0	0	0	14.83	0	0	0	0	0	0	0	0	14.83
8. MOH	0	0	0	0	0	0	0	0	0	0	0	0	0
9. PPOH	0	0	3.4	17.1	0	0	0	0	0	0	0	0	20.5
10. LR PP (MW)	0	0	383.59	321.98	0	0	0	0	0	0	0	0	332.2
11. PFOH	0.13	28.42	0	43.13	0.45	0	0	5.5	0	0.05	7.23	0	84.92
12. LR PF (MW)	154.12	221.25	0	304.41	221.25	0	0	221.25	0	118	219.29	0	263.16
13. PMOH	20.37	0	0	32.3	75.42	0	59.35	52.62	61.85	106.58	34.17	39.78	482.43
14. LR PM (MW)	221.25	0	0	221.25	317	0	221.25	315.37	221.25	221.25	221.25	221.25	246.48
15. NSC	885	885	885	885	885	885	885	885	885	885	885	885	885
16. OPER BTU (MBTU)	2928173	2582937	1390499	2554857	3622607	4076214	4079712	3764612	3850276	3981239	3588133	3697251	40116510
17. NET GEN	382673	341964	185582	342108	493548	558605	554841	505269	524089	543976	482847	491765	5407267
18. ANOHR (BTU/KWH)	7652	7553	7493	7468	7340	7297	7353	7451	7347	7319	7431	7518	7419
19. NOF (%)	59.9	63.7	74.6	74.6	82.9	87.7	84.3	76.7	82.2	82.6	75.7	74.7	77
20. NPC (MW)	955	955	955	958	958	958	958	958	958	958	1040	1040	971

21. ANOHR EQUATION

ANOHR = A + B (N.O.F.)

A = 0 B = 0

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

ACTUAL PERFORMANCE DATA
COMPANY: FLORIDA POWER AND LIGHT
FROM: Jan-2010 TO: Dec-2010

		PLANT / UNIT: SANFORD 4 & 5 CC 05										PSR 05		
		Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Ytd
1.	EAF (%)	94.6	95.3	98.2	78.4	87.7	94.9	86.3	87.9	94.8	94.5	96.9	93.3	91.9
2.	PH	744	672	743	720	744	720	744	744	720	744	721	744	8760
3.	SH	638.77	630.45	743	664.65	744	720	744	744	720	744	623.03	640.33	8356.23
4.	RSH	105.23	41.55	0	55.35	0	0	0	0	0	0	97.97	103.67	403.77
5.	UH	0	0	0	0	0	0	0	0	0	0	0	0	0
6.	POH	0	0	0	0	0	0	0	0	0	0	0	0	0
7.	FOH	0	0	0	0	0	0	0	0	0	0	0	0	0
8.	MOH	0	0	0	0	0	0	0	0	0	0	0	0	0
9.	PPOH	0	0	0	337.25	265.58	0	313	303.13	0	0	0	0	1218.97
10.	LR PP (MW)	0	0	0	332.01	256.7	0	220.75	220.75	0	0	0	0	259.37
11.	PFOH	51.72	16.53	0.23	0	7.68	6.67	15.52	5.03	4.3	2.02	2.37	0	112.07
12.	LR PF (MW)	227.13	222.79	220.75	0	220.75	220.75	220.75	220.75	220.75	220.75	315	0	225.99
13.	PMOH	104.67	57.33	53.42	66.63	48.58	141.15	79.43	52.85	146.22	160.23	87.02	199.37	1196.7
14.	LR PM (MW)	226.66	422.33	220.75	384.19	220.75	220.75	220.75	220.75	220.75	220.75	220.75	220.75	240.02
15.	NSC	883	883	883	883	883	883	883	883	883	883	883	883	883
16.	OPER BTU (MBTU)	2588921	2983417	3782460	2951132	3511125	3674905	3168968	3392668	3543262	3632449	2795882	2910877	38936066
17.	NET GEN	340022	399229	512875	395700	481128	505468	433418	463711	486084	497143	370303	391026	5276107
18.	ANOHR (BTU/KWH)	7614	7473	7375	7458	7298	7270	7312	7316	7289	7307	7550	7444	7380
19.	NOF (%)	60.3	71.7	78.2	67.4	73.2	79.5	66	70.6	76.5	75.7	67.3	69.2	71.5
20.	NPC (MW)	952	952	952	954	954	954	954	954	954	954	1037	1037	987
21.	ANOHR EQUATION	ANOHR = A + B (N.O.F.) A = 0 B = 0												

NOTE: LINE 17 IS DATA WHEN THE UNIT IS SYNCHRONIZED TO THE SYSTEM

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: FORT MYERS 02

PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/23/2010	FFO	8.9	58	steamer 1 trip (inlet pressure sensor)
01/30/2010	FMO	27.9	141	2B R0/R1 inspection, replace expansion joint, off line wash.
01/30/2010	PMO	27.9	71.14	Impact loss due to curtailment on 2B
01/30/2010	PMO	27.9	9.69	Impact loss due to curtailment on 2B
02/01/2010	FMO	45.0	141	2B R0/R1 inspection, replace expansion joint, off line wash.
02/01/2010	PMO	45.0	9.69	Impact loss due to curtailment on 2B
02/01/2010	PMO	45.0	71.14	Impact loss due to curtailment on 2B
02/02/2010	PFO	0.5	3	2D Runback
02/08/2010	FMO	95.0	141	2F CT OUTAGE
02/08/2010	PMO	95.0	9.69	Impact loss due to curtailment on 2F
02/08/2010	PMO	95.0	71.15	Impact loss due to curtailment on 2F
02/14/2010	FMO	77.2	141	2a RO & R1 BLADE INSPECTIONS
02/14/2010	PMO	77.2	9.69	Impact loss due to curtailment on 2A
02/14/2010	PMO	77.2	71.15	Impact loss due to curtailment on 2A
02/18/2010	FMO	8.5	141	2F CT BFP REPAIR
02/18/2010	PMO	8.5	9.69	Impact loss due to curtailment on 2F
02/18/2010	PMO	8.5	71.15	Impact loss due to curtailment on 2F
02/22/2010	FMO	102.4	141	2C RO & R1 BLADE INSPECTION
02/22/2010	PMO	102.4	9.69	Impact loss due to curtailment on 2C
02/22/2010	PMO	102.4	71.15	Impact loss due to curtailment on 2C
02/27/2010	FFO	3.9	141	2C Gas monitor HI HI alarms
02/27/2010	PFO	3.9	71.15	Impact loss due to curtailment on 2C
02/27/2010	PFO	3.9	9.69	Impact loss due to curtailment on 2C
02/27/2010	FFO	4.9	141	2C CT Duplex Strainer Gas Leak HI HI Haz Gas Alarm

- (1) FFO - FULL FORCED OUTAGE
- PPO - PARTIAL PLANNED OUTAGE
- PMO - PARTIAL MAINTENANCE OUTAGE
- PO - PLANNED OUTAGE
- PFO - PARTIAL FORCED OUTAGE
- FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: FORT MYERS

02

PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
02/27/2010	PFO	4.9	71.15	Impact loss due to curtailment on 2C
02/27/2010	PFO	4.9	9.69	Impact loss due to curtailment on 2C
03/10/2010	FFO	3.7	141	2B Gas Monitor HI-HI
03/10/2010	PFO	3.7	71.15	Impact loss due to curtailment on 2B
03/10/2010	PFO	3.7	9.69	Impact loss due to curtailment on 2B
03/23/2010	FFO	7.8	141	2 bravo (gas monitor)
03/23/2010	PFO	7.8	9.69	Impact loss due to curtailment on 2B
03/23/2010	PFO	7.8	71.15	Impact loss due to curtailment on 2B
03/25/2010	PMO	1.9	9.69	Impact loss due to curtailment on 2D
03/25/2010	PMO	2.7	71.15	Impact loss due to curtailment on 2D
03/25/2010	FMO	146.0	141	2D CT/HRSG Site Outage
03/25/2010	PMO	1.3	9.69	Impact loss due to curtailment on 2C
03/25/2010	PMO	2.2	71.15	Impact loss due to curtailment on 2C
03/25/2010	FMO	145.4	141	2C CT/HRSG Site Outage
03/25/2010	PMO	0.4	9.69	Impact loss due to curtailment on 2F
03/25/2010	PMO	1.2	71.15	Impact loss due to curtailment on 2F
03/25/2010	FMO	144.5	141	2F CT/HRSG Site Outage
03/25/2010	FMO	144.1	58	Steam Turbine 1 - CT/HRSG Site Outage
03/26/2010	FMO	143.3	426	Steam Turbine 2 - CT/HRSG Site Outage
03/26/2010	FMO	142.4	141	2B CT/HRSG Site Outage
03/26/2010	FMO	142.2	141	2A CT/HRSG Site Outage
03/26/2010	FMO	141.1	141	2E CT/HRSG Site Outage
04/01/2010	FMO	23.3	141	2F CT/HRSG Site Outage
04/01/2010	FMO	23.3	141	2A CT/HRSG Site Outage

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: FORT MYERS

02

PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
04/01/2010	FMO	25.7	141	2B CT/HRSG
04/01/2010	FMO	25.8	141	2D CT/HRSG Site Outage
04/01/2010	FMO	28.6	426	ST2 Site Outage
04/01/2010	FMO	31.8	141	2C CT /HRSG Site Outage
04/01/2010	FMO	31.9	141	2E CT/HRSG Site Outage
04/01/2010	FMO	33.8	58	ST1 Site Outage
04/02/2010	PMO	3.2	71.15	Impact loss due to curtailment on 2C
04/02/2010	PMO	3.3	71.15	Impact loss due to curtailment on 2E
04/05/2010	FFO	6.8	141	2C CT - 2A 230 volt string bus protection relay failure.
04/05/2010	PFO	6.8	9.69	Impact loss due to curtailment on 2C
04/05/2010	PFO	6.8	71.15	Impact loss due to curtailment on 2C
04/05/2010	FFO	5.9	141	2B CT - 2A 230 volt string bus protection relay failure.
04/05/2010	PFO	5.9	9.69	Impact loss due to curtailment on 2B
04/05/2010	PFO	5.9	71.15	Impact loss due to curtailment on 2B
04/05/2010	FFO	4.9	141	2A CT - 2A 230 volt string bus protection relay failure.
04/05/2010	PFO	4.9	9.69	Impact loss due to curtailment on 2A
04/05/2010	PFO	4.9	71.15	Impact loss due to curtailment on 2A
04/22/2010	FFO	0.3	141	2BCT HMI
04/22/2010	PFO	0.3	71.15	Impact loss due to curtailment on 2B
04/22/2010	PFO	0.3	9.69	Impact loss due to curtailment on 2B
04/29/2010	FMO	41.1	58	STM 1 Offline for STM 2 EHC Leak Repairs
04/29/2010	FMO	38.8	426	Steam Turbine # 2 LP Admission Stop Valve EHC Leak
05/01/2010	PFO	43.1	201	Steam Turbine # 2 Reduced Load(50%) Reheat Stop Valve Fa
05/02/2010	FMO	70.8	141	2B CT Change Over to Simple Cycle Unit

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: FORT MYERS

02

PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
05/02/2010	PMO	70.8	9.69	Impact loss due to curtailment on 2B
05/02/2010	PMO	70.8	71.15	Impact loss due to curtailment on 2B
05/03/2010	FMO	82.6	141	2F CT Change Over to Simple Cycle
05/03/2010	PMO	82.6	71.15	Impact loss due to curtailment on 2F
05/03/2010	PMO	82.6	9.69	Impact loss due to curtailment on 2F
05/03/2010	PFO	114.3	126	Steam Turbine # 2 Reduced Load(66%) Reheat Stop Valve Fa
05/05/2010	PMO	72.5	9.69	Impact loss due to curtailment on 2E
05/05/2010	PMO	74.6	71.15	Impact loss due to curtailment on 2E
05/05/2010	FMO	78.3	141	2E CT Change over to Simple Cycle Unit
05/08/2010	FMO	283.5	58	ST1 Maint Outage for ST2 Reheat Stop Valve Repairs
05/08/2010	FMO	276.8	426	ST2 Maintenance outage for #1 RSV
05/11/2010	PFO	0.5	109	2F CT Runback
05/13/2010	FFO	5.9	141	2F Direct Fired Heater Failure to Start
05/19/2010	PMO	78.2	216	Simple Cycle MW loss to ST2 output from 2E, 2F & 2B
05/19/2010	PFO	1.1	210	#2 steamer trip
05/20/2010	FMO	61.8	141	2E CT blanking plate (remove)
05/20/2010	PMO	61.8	71.15	Impact loss due to curtailment on 2E
05/20/2010	PMO	61.8	9.69	Impact loss due to curtailment on 2E
05/21/2010	PFO	0.5	38	ST1 FGT Gas Yard Regulator Station Failure
05/21/2010	PFO	0.5	19	ST2 FGT Gas Yard Regulator Station Failure
05/21/2010	PFO	0.5	15	2F CT FGT Gas Yard Regulator Station Failure
05/21/2010	PFO	0.5	15	2D CT FGT Gas Yard Regulator Station Failure
05/21/2010	PFO	0.5	15	2C CT FGT Gas Yard Regulator Station Failure
05/21/2010	PFO	0.5	15	2B CT FGT Gas Yard Regulator Station Failure

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:

SUSPENDED:

EFFECTIVE:

DOCKET NO.:

ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: FORT MYERS 02 PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
05/21/2010	PFO	0.5	15	2A CT FGT Gas Yard Regulator Station Failure
05/22/2010	PMO	46.7	141	Simple Cycle MW loss to ST2 output from 2F & 2B
05/22/2010	FMO	46.2	141	2F CT Blanking Plate Removal
05/22/2010	PMO	46.2	71.14	Impact loss due to curtailment on 2F
05/22/2010	PMO	46.2	9.69	Impact loss due to curtailment on 2F
05/24/2010	FMO	60.7	141	2B blanking plate removal
05/24/2010	PMO	60.7	71.15	Impact loss due to curtailment on 2B
05/24/2010	PMO	60.7	9.69	Impact loss due to curtailment on 2B
05/24/2010	PMO	59.7	68	Simple Cycle MW loss to ST2 output from 2B
05/30/2010	PFO	0.3	6	2C HP to CRH Bypass Valve SGG-ACV-3 Failed 100% open
05/31/2010	FFO	15.0	141	2E HP SPRAY HEADER CRACK
05/31/2010	PFO	15.0	71.15	Impact loss due to curtailment on 2E
05/31/2010	PFO	15.0	9.69	Impact loss due to curtailment on 2E
06/01/2010	FFO	41.5	141	2E HP SPRAY HEADER CRACK
06/01/2010	PFO	41.5	71.15	Impact loss due to curtailment on 2E
06/01/2010	PFO	41.5	9.69	Impact loss due to curtailment on 2E
06/08/2010	FFO	50.1	141	2C CT/HRSG Expansion Joint / Possible Tube leak.
06/08/2010	PFO	50.1	71.15	Impact loss due to curtailment on 2C
06/08/2010	PFO	50.1	9.69	Impact loss due to curtailment on 2C
06/25/2010	FMO	42.1	141	2B CT/HRSG Hot Reheat Header Spray Nozzles Repair
06/25/2010	PMO	42.1	71.15	Impact loss due to curtailment on 2B
06/25/2010	PMO	42.1	9.69	Impact loss due to curtailment on 2B
07/06/2010	FMO	17.2	141	Replace broken exhaust thermocouple
07/06/2010	PMO	17.2	71.15	Impact loss due to curtailment on 2C

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: FORT MYERS 02 PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
07/06/2010	PMO	17.2	9.69	Impact loss due to curtailment on 2C
07/09/2010	FFO	0.3	141	PFM 2D CT Exciter Failure
07/09/2010	PFO	0.3	71.15	Impact loss due to curtailment on 2D
07/09/2010	PFO	0.3	9.69	Impact loss due to curtailment on 2D
07/15/2010	FMO	14.6	58	#1 Control valve repair
07/16/2010	FMO	84.1	141	2D CT/HRSG HP SPRAY PIPING REPAIR
07/16/2010	PMO	84.1	9.69	Impact loss due to curtailment on 2D
07/16/2010	PMO	84.1	71.15	Impact loss due to curtailment on 2D
07/17/2010	FMO	15.9	141	2ACT Generator lift oil check valve replacement
07/17/2010	PMO	15.9	71.15	Impact loss due to curtailment on 2A
07/17/2010	PMO	15.9	9.69	Impact loss due to curtailment on 2A
07/19/2010	PFO	1.3	6	2 alpha hp fill reg sgg-acv-408
07/23/2010	FMO	42.8	141	repair 2C SGG-ACV-3
07/23/2010	PMO	42.8	71.15	Impact loss due to curtailment on 2C
07/23/2010	PMO	42.8	9.69	Impact loss due to curtailment on 2C
07/27/2010	FFO	7.6	141	2CCT PM3 Trip
07/27/2010	PFO	7.6	71.15	Impact loss due to curtailment on 2C
07/27/2010	PFO	7.6	9.69	Impact loss due to curtailment on 2C
08/06/2010	FMO	21.9	141	2A CT fuel gas coalescing filter replacement
08/06/2010	PMO	21.9	71.15	Impact loss due to curtailment on 2A
08/06/2010	PMO	21.9	9.69	Impact loss due to curtailment on 2A
08/10/2010	FMO	111.1	141	HP Attenuator Piping repair
08/10/2010	PMO	111.1	71.14	Impact loss due to curtailment on 2C
08/10/2010	PMO	111.1	9.69	Impact loss due to curtailment on 2C

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: FORT MYERS 02 PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
08/23/2010	FFO	8.1	141	2D aux stop valve failure
08/23/2010	PFO	8.1	71.15	Impact loss due to curtailment on 2D
08/23/2010	PFO	8.1	9.69	Impact loss due to curtailment on 2D
08/25/2010	FMO	18.3	141	2A CT Replace PM3 centerline
08/25/2010	PMO	18.3	71.15	Impact loss due to curtailment on 2A
08/25/2010	PMO	18.3	9.69	Impact loss due to curtailment on 2A
09/09/2010	FPO	215.0	141	2F CT/HRSG Outage for Valve work
09/09/2010	PPO	215.0	71.15	Impact loss due to curtailment on 2F
09/09/2010	PPO	215.0	9.69	Impact loss due to curtailment on 2F
09/15/2010	FFO	1.8	141	2E CT Generator field ground
09/15/2010	PFO	1.8	71.15	Impact loss due to curtailment on 2E
09/15/2010	PFO	1.8	9.69	Impact loss due to curtailment on 2E
09/16/2010	FPO	170.9	141	2 delta
09/16/2010	PPO	170.9	71.15	Impact loss due to curtailment on 2D
09/16/2010	PPO	170.9	9.69	Impact loss due to curtailment on 2D
09/26/2010	FPO	116.2	141	2E CT HRSG Outage Reheat Expansion Joint
09/26/2010	PPO	116.2	71.15	Impact loss due to curtailment on 2E
09/26/2010	PPO	116.2	9.69	Impact loss due to curtailment on 2E
10/03/2010	FMO	60.6	141	2C CT/HRSG OUTAGE
10/03/2010	PMO	60.6	71.14	Impact loss due to curtailment on 2C
10/03/2010	PMO	60.6	9.69	Impact loss due to curtailment on 2C
10/07/2010	FPO	65.3	141	2B HRSG Planned Outage
10/07/2010	PPO	65.3	71.15	Impact loss due to curtailment on 2B
10/07/2010	PPO	65.3	9.69	Impact loss due to curtailment on 2B

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: FORT MYERS 02 PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
10/10/2010	FMO	134.9	141	2A CT GSU Bushing Outage
10/10/2010	PMO	134.9	71.15	Impact loss due to curtailment on 2A
10/10/2010	PMO	118.6	9.69	Impact loss due to curtailment on 2A
10/13/2010	FMO	16.3	58	steamer 1 #2 control valve repair
11/08/2010	FFO	9.9	141	2C HP Attenuator Block Valve Failure
11/08/2010	PFO	9.9	71.15	Impact loss due to curtailment on 2C
11/08/2010	PFO	9.9	9.69	Impact loss due to curtailment on 2C
11/18/2010	FMO	41.5	141	2F SGJ-ACV-10 Repair
11/18/2010	PMO	41.5	71.15	Impact loss due to curtailment on 2F
11/18/2010	PMO	41.5	9.69	Impact loss due to curtailment on 2F
11/21/2010	FFO	7.0	141	2F CT Hi-HI Hazardous Gas, Fuel Gas Duplex Strainer Leak
11/21/2010	PFO	7.0	71.15	Impact loss due to curtailment on 2F
11/21/2010	PFO	7.0	9.69	Impact loss due to curtailment on 2F
11/28/2010	FFO	0.7	141	2B CT/HRSG Gas Aux Stop Valve
11/28/2010	PFO	0.7	71.15	Impact loss due to curtailment on 2B
11/28/2010	PFO	0.7	9.69	Impact loss due to curtailment on 2B
12/02/2010	FMO	49.0	141	2D CT/HRSG Offline Water Wash
12/02/2010	PMO	49.0	71.15	Impact loss due to curtailment on 2D
12/02/2010	PMO	49.0	9.69	Impact loss due to curtailment on 2D
12/15/2010	FFO	27.1	426	Steam Turbine #2
12/15/2010	FFO	30.4	58	Steam Turbine 1 Trip because of Steam Turbine 2 Trip.
12/15/2010	FFO	6.1	141	2A CT/HRSG Trip from HP high pressure.
12/15/2010	FFO	6.1	141	2D CT/HRSG Tripped off because of Steam Turbine 2.
12/17/2010	FFO	5.5	141	2E CT/HRSG Trip on lube oil high temp

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: FORT MYERS 02

PFM 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
12/17/2010	PFO	5.5	71.15	Impact loss due to curtailment on 2E
12/17/2010	PFO	5.5	9.69	Impact loss due to curtailment on 2E
12/23/2010	FFO	6.3	141	2D HRSG HP to Cold Reheat Bypass Valve Failure
12/23/2010	PFO	6.3	71.15	Impact loss due to curtailment on 2D
12/23/2010	PFO	6.3	9.69	Impact loss due to curtailment on 2D

(1) FFO - FULL FORCED OUTAGE
PPO - PARTIAL PLANNED OUTAGE
PMO - PARTIAL MAINTENANCE OUTAGE
PO - PLANNED OUTAGE
PFO - PARTIAL FORCED OUTAGE
FMO - FULL MAINTENANCE OUTAGE

FILED:
SUSPENDED:
EFFECTIVE:
DOCKET NO.:
ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: SCHERER 04

PSG 04

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/15/2010	FPO	1723.6	846	Scherer Unit 4 Outage
03/31/2010	FPO	52.5	846	Scherer 4 Planned Outage
04/11/2010	PFO	2.4	111	ID fan Amp problem/Trip going low to high
05/28/2010	FMO	43.4	846	Boiler Leak Repair
07/10/2010	FFO	36.8	846	Boiler Tube Leak
08/08/2010	PFO	0.5	286	4B Boiler Feed Pump Trip
09/19/2010	PMO	6.0	91	Chemically Cleaning Generator Hydrogen Coolers
10/12/2010	PMO	10.5	146	4B ID Fan outboard bearing wiped
10/13/2010	PFO	1.7	146	4B ID Fan outlet damper linkage
10/23/2010	FMO	32.5	846	Lower water wall tube leak
11/06/2010	PFO	2.4	96	H and J Feeder Trip

- (1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: ST LUCIE

01

PSL 01

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
04/04/2010	PPO	6.0	269.33	U1 PEL MSSV Testing 040410
04/04/2010	PPO	3.9	444.43	U1 PEL SL1-23 Down Power 040410
04/04/2010	FPO	1080.0	839	U1 PEL SL1-23 Refueling Outage 040410
05/19/2010	FPO	609.4	839	SL1-23 Refueling Outage Extension 051910
06/14/2010	PPO	64.7	592.95	SL1-23 Refueling Outage Power Ascension part 1 061410
06/16/2010	FFO	256.7	839	U1 UEL CEA 38 & CEA 65 Drop SNO 061610
06/27/2010	PFO	22.9	525.84	U1 UEL CEA SNO Uppower 062710
06/28/2010	PFO	28.1	425.78	U1 UEL Chemistry Hold during Uppower 062810
06/29/2010	PPO	16.2	282.78	U1 PEL SL1-23 PWR Ascension part 2 062909
06/30/2010	PFO	33.7	159.49	U1 UEL Chemistry Hold during Uppower part 2 063010
07/01/2010	PPO	21.9	76.38	U1 PEL SL1-23 PWR Ascension part 3 070110
07/13/2010	PFO	215.3	76.03	U1 UEL 1A2 CW pump motor repair 071310
07/22/2010	PFO	419.3	439.66	U1 UEL 1B Main Feed Pump Repair 072210
08/08/2010	PFO	2.5	328.89	U1 UEL MG Set Instr. Up Power Delay 080810
08/08/2010	PFO	11.4	163.72	U1 UEL Main Feed Water Pump Up Power 080810
08/09/2010	PFO	550.6	111.24	U1 UEL 1A2 CW pump motor repair (part 2) 080910
09/01/2010	PFO	266.9	138.81	U1 UEL 1A2 CW pump motor repair part 3 090110
09/12/2010	PPO	4.6	64.12	U1 PEL Turbine Valve Test 091210
09/12/2010	PFO	3.3	30.23	U1 UEL 1A2 CW pump motor repair part 4 - final 091210

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: ST LUCIE 02 PSL 02

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/08/2010	PMO	38.6	420.69	U2 UEL Condensate Pump Seal Line 010810
03/10/2010	PPO	5.4	46.44	U2 PEL Turbine Valve Test 031010
04/03/2010	PFO	3.7	45.97	U2 UEL 2A HDP Actuator Feedback Arm Linkage Pin Repair C
04/15/2010	FFO	152.5	839	PSL 2 UEL 2B MSR Relief Valve Repair 041510
04/22/2010	FFO	11.5	839	U2 UEL MFIV repair 042210
04/22/2010	FFO	6.7	839	U2 UEL MSR Relief Valve Relief part 2
04/22/2010	PFO	11.0	305.51	U2 UEL MSR Relief Valve Repair Uppower 042210
04/27/2010	PFO	26.6	44.76	U2 UEL 2B MSR Drain Collector Steam Leak 042710
07/19/2010	PFO	109.8	51.26	U2 UEL 2B1 Debris Filtration System repair 071910
09/26/2010	PFO	92.8	114.52	U2 UEL 2B2 DFS Repair 092610
11/29/2010	PPO	3.7	50.29	U2 PEL Turbine Valve Test 112910
11/30/2010	PFO	13.5	49.61	U2 UEL Turbine Valve Repair 113010
11/30/2010	PPO	7.5	37.06	U2 PEL Turbine Valve Test (part 2)

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: TURKEY POINT 03

PTN 03

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
02/17/2010	PPO	38.0	350	Unit 3 planned downpower for Turbine Valve Testing
06/03/2010	PFO	9.6	41	Unit 3 Unplanned power reduction due to 3B Condensate Pmp
06/24/2010	PFO	56.0	35	Unit 3 unplanned downpower due to Heater Drain pump issues
09/07/2010	PPO	13.0	5	Unit 3 Mw loss for planned maintenance inspection of the 3B1
09/07/2010	PFO	11.9	193	Unit 3 unplanned power reduction due to Screen Wash system
09/23/2010	FFO	78.8	693	Unit 3 Reactor Trip
09/27/2010	FPO	936.0	693	Unit 3 Cycle 25 RFO
11/05/2010	FFO	113.7	693	Unit 3 Cycle 25 RFO extension
11/09/2010	PPO	101.3	225	Unit 3 Power ascension following Cycle 25 RFO
11/15/2010	FFO	36.6	693	Unit 3 Reactor trip due to loss of 3A2 CWP packing failure
11/16/2010	PFO	50.3	239	Unit 3 power ascension following unplanned reactor trip due to

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: TURKEY POINT

04

PTN 04

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/11/2010	PFO	5.6	26	Unit 4 unplanned downpower due to both Heater Drain pump t
01/11/2010	FFO	79.5	693	Unit 4 Reactor Trip due to loss of the 4A SGFP
01/14/2010	PFO	23.5	335	Unit 4 Reactor Trip due to loss of the 4A SGFP - Power ascen:
04/07/2010	PPO	59.9	83	Unit 3 planned downpower to replace positioner on CV-4-1510.
08/26/2010	PPO	34.0	255	Unit 4 planned sown power for turbine valve testing
09/08/2010	FFO	37.9	693	Unit 4 Reactor trip during replacement of a Reactor Protection
09/10/2010	PFO	23.3	251	Unit 4 power ascension due to unplanned Reactor Trip
09/21/2010	FFO	63.6	693	Unit 4 Reactor Trip due to RPS Comparator Module failure
09/24/2010	PFO	13.1	266	Unit 4 Power ascension following Reactor Trip
11/29/2010	PPO	43.6	329	Unit 4 planned downpower due to 4C 4KV Bus FME retrieval
12/09/2010	PFO	1.0	263	Unit 4 power reduction due to High sodium in Steam Generato
12/09/2010	FFO	180.5	693	Unit 4 Manual Reactor trip due to high sodium in Steam Gener
12/17/2010	PFO	14.5	326	Unit 4 power ascension following reactor trip due to high sodiu

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: MANATEE UNIT 3 CC 03

PM3 03

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/16/2010	FFO	3.2	146	3 CTB - GE network switch (missed RFC)
01/16/2010	PFO	3.2	114.25	Impact loss due to curtailment on 3B
01/28/2010	PFO	1.8	71	CT C IP Feedwater regulator valve- positioner replacement
01/30/2010	FPO	106.9	146	OFF LINE WATER WASH
01/30/2010	PPO	106.9	114.25	Impact loss due to curtailment on 3A
02/05/2010	FPO	125.2	146	OFF LINE WATER WASH
02/05/2010	PPO	125.2	114.25	Impact loss due to curtailment on 3B
02/11/2010	FPO	53.9	146	OFF LINE WATER WASH
02/11/2010	PPO	53.9	114.25	Impact loss due to curtailment on 3D
02/14/2010	FPO	28.5	146	OFF LINE WATER WASH
02/14/2010	PPO	28.5	114.25	Impact loss due to curtailment on 3A
03/01/2010	FPO	50.1	146	Off line water wash
03/01/2010	PPO	50.1	114.25	Impact loss due to curtailment on 3C
04/02/2010	FPO	305.7	146	full planned outage
04/02/2010	PPO	305.7	114.25	Impact loss due to curtailment on 3C
04/02/2010	FPO	304.8	146	full planned outage
04/02/2010	PPO	304.8	114.25	Impact loss due to curtailment on 3D
04/06/2010	FFO	3.4	146	Failed Mark VI card
04/06/2010	PFO	3.4	114.25	Impact loss due to curtailment on 3A
04/09/2010	FPO	351.6	146	Full Planned Outage
04/09/2010	PPO	351.6	114.25	Impact loss due to curtailment on 3B
04/09/2010	FPO	351.5	146	Full Planned Outage
04/09/2010	PPO	351.5	114.25	Impact loss due to curtailment on 3A
04/15/2010	FPO	16.4	146	full planned

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: MANATEE UNIT 3 CC 03

PM3 03

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
04/15/2010	PPO	16.4	114.25	Impact loss due to curtailment on 3D
04/15/2010	FPO	15.3	146	full planned
04/15/2010	PPO	15.3	114.25	Impact loss due to curtailment on 3C
04/16/2010	PFO	184.6	228.5	Toshiba Reheat Stop Valves Failed to Open
04/24/2010	FFO	59.0	457	Toshiba Reheat Stop Valves Failed to Open
05/19/2010	FPO	31.5	146	Offline Water Wash
05/19/2010	PPO	31.5	114.25	Impact loss due to curtailment on 3C
05/24/2010	FPO	34.8	146	Offline Water Wash
05/24/2010	PPO	34.8	114.25	Impact loss due to curtailment on 3B
07/07/2010	FMO	408.0	146	CT wheel space inspection
07/07/2010	PMO	403.7	114.25	Impact loss due to curtailment on 3D
07/09/2010	FFO	4.3	457	3ST Trip
07/09/2010	FFO	2.3	146	3B trip on loss of Steam Turbine see PM320102662
07/12/2010	FFO	28.0	146	PMT 3B Unavailable - BFP Motor Failed
07/12/2010	PFO	28.0	114.25	Impact loss due to curtailment on 3B
07/13/2010	FMO	7.2	146	thermocouple changeout
07/13/2010	PMO	7.2	114.25	Impact loss due to curtailment on 3B
08/13/2010	FFO	1.7	457	PMT 3 ST Trip
09/07/2010	FMO	55.7	146	WW & PT fuse change out
09/07/2010	PMO	55.7	114.25	Impact loss due to curtailment on 3A
09/13/2010	PFO	1.2	56	3B IP level positioner failure
09/24/2010	FMO	42.1	146	Off-Line Water Wash
09/24/2010	PMO	42.1	114.25	Impact loss due to curtailment on 3D
10/11/2010	FMO	79.5	146	Off-Line Water Wash

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: MANATEE UNIT 3 CC 03

PM3 03

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
10/11/2010	PMO	79.5	114.25	Impact loss due to curtailment on 3B
11/08/2010	FPO	681.9	146	outage
11/08/2010	PPO	616.9	114.25	Impact loss due to curtailment on 3C
11/11/2010	PMO	0.8	114.25	Impact loss due to curtailment on 3A
11/11/2010	FMO	59.1	146	condensate pump repairs
11/11/2010	FMO	65.1	457	condensate pp repairs
11/12/2010	FMO	58.2	146	condensate pump repairs
11/12/2010	FMO	67.2	146	condensate pump repair
11/14/2010	PMO	3.8	114.25	Impact loss due to curtailment on 3B
12/01/2010	FMO	520.2	146	circ water pump/motor
12/01/2010	PMO	520.2	114.25	Impact loss due to curtailment on 3A
12/06/2010	FMO	0.1	146	STARS testing
12/06/2010	PMO	0.1	114.25	Impact loss due to curtailment on 3C
12/06/2010	FMO	17.5	146	CIRC WATER PUMP/MOTOR
12/06/2010	PMO	17.5	114.25	Impact loss due to curtailment on 3D
12/08/2010	FMO	23.1	146	Balance shot
12/08/2010	PMO	23.1	114.25	Impact loss due to curtailment on 3C
12/30/2010	PFO	0.9	116	CT-C Emissions Compliance Malfunction

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: MARTIN-UNIT 8

08

PM8 08

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/02/2010	FFO	7.5	142	8C CTG SRV Not tracking failed to start
01/02/2010	PFO	7.5	115.75	Impact loss due to curtailment on 8C
01/10/2010	PFO	0.3	60	PMG 8A Missed 0400 RFC
01/10/2010	FFO	1.7	142	PMG 8B Missed RFC
01/10/2010	PFO	1.7	115.75	Impact loss due to curtailment on 8B
01/10/2010	FFO	3.9	142	8B Missed RFC Continuation
01/10/2010	PFO	3.9	115.75	Impact loss due to curtailment on 8B
01/14/2010	FMO	4.3	142	8C CT MEDIA CONVERTER(S) REPLACEMENT
01/14/2010	PMO	4.3	115.75	Impact loss due to curtailment on 8C
01/14/2010	FMO	33.3	142	8A SNOW
01/14/2010	PMO	33.3	115.75	Impact loss due to curtailment on 8A
01/21/2010	FFO	5.2	142	8B CT ATOMIZING AIR HIGH TEMP
01/21/2010	PFO	5.2	115.75	Impact loss due to curtailment on 8B
01/21/2010	FFO	23.1	142	8B CT ATOMIZING AIR HIGH TEMP
01/21/2010	PFO	23.1	115.75	Impact loss due to curtailment on 8B
01/22/2010	FFO	6.8	142	PMG 8C Missed RFC
01/22/2010	PFO	6.8	115.75	Impact loss due to curtailment on 8C
01/23/2010	FMO	32.0	142	8D CT Off-Line Waterwash
01/23/2010	PMO	32.0	115.75	Impact loss due to curtailment on 8D
01/25/2010	FFO	4.9	142	8C CT TRIP - fire suppression system
01/25/2010	PFO	4.9	115.75	Impact loss due to curtailment on 8C
01/29/2010	FFO	0.4	142	PMG 8D Missed RFC
01/29/2010	PFO	0.4	115.75	Impact loss due to curtailment on 8D
01/29/2010	FMO	78.3	142	8B CT MOF/AA COOLER OUTAGE

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: MARTIN-UNIT 8 08 PM8 08

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/29/2010	PMO	78.3	115.75	Impact loss due to curtailment on 8B
02/02/2010	FFO	9.3	142	8B CT IP Feedwater REGULATOR Failure
02/02/2010	PFO	9.3	115.75	Impact loss due to curtailment on 8B
02/03/2010	FPO	56.1	142	8C Liquid Fuel Reliability & Capability Repairs
02/03/2010	PPO	56.1	115.75	Impact loss due to curtailment on 8C
02/07/2010	FPO	834.0	142	8D CT Off For Outage 02/07/10
02/07/2010	PPO	424.2	115.75	Impact loss due to curtailment on 8D
02/19/2010	PPO	1.1	115.75	Impact loss due to curtailment on 8A
02/19/2010	FPO	384.5	142	8A CT Overhaul
02/19/2010	FPO	409.8	463	8X Planned Outage
02/19/2010	FPO	1002.2	142	8C CT/HRSG Planned Outage
02/19/2010	FPO	379.4	142	8B CT/HRSG Planned Outage
03/09/2010	PPO	593.1	115.75	Impact loss due to curtailment on 8C
03/09/2010	FMO	7.1	142	8B CT OUTAGE (EVENT MOF; GAS STRAINER PLUGGAGE
03/09/2010	PMO	7.1	115.75	Impact loss due to curtailment on 8B
03/15/2010	FFO	4.0	142	PMG 8D EFOR due to solar tie in valve
03/15/2010	PFO	4.0	115.75	Impact loss due to curtailment on 8D
04/01/2010	FFO	1.1	142	8D CT TRIP
04/01/2010	PFO	1.1	115.75	Impact loss due to curtailment on 8D
04/02/2010	FPO	0.1	142	8C CT Planned Outage
04/02/2010	PPO	0.1	115.75	Impact loss due to curtailment on 8C
04/05/2010	FFO	2.8	142	8C TRIP Due to BFP
04/05/2010	PFO	2.8	115.75	Impact loss due to curtailment on 8C
04/06/2010	PFO	0.7	141	8C CT Trip From Boiler Feed Pump Trip

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:

SUSPENDED:

EFFECTIVE:

DOCKET NO.:

ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: MARTIN-UNIT 8

08

PM8 08

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
04/16/2010	FMO	175.1	142	8D CT/HRSG Boiler Feed Pump replacement
04/16/2010	PMO	175.1	115.75	Impact loss due to curtailment on 8D
04/23/2010	FMO	18.7	142	8A CT Atomizing Air cooler repairs 04/23/2010
04/23/2010	PMO	18.7	115.75	Impact loss due to curtailment on 8A
04/30/2010	FFO	3.1	142	8D CT EFOR "R" Processor Comm Fault
04/30/2010	PFO	3.1	115.75	Impact loss due to curtailment on 8D
05/07/2010	FMO	55.4	142	8C RSD
05/07/2010	PMO	55.4	115.75	Impact loss due to curtailment on 8C
05/09/2010	FMO	55.0	142	8B SNOW
05/09/2010	PMO	55.0	115.75	Impact loss due to curtailment on 8B
05/17/2010	FFO	3.9	463	8X Main Steam Turbine Trip Due To NO Condensate Pump
05/17/2010	FFO	5.9	142	8B CT RUNBACK TO FSNL 910 Event
05/17/2010	PFO	2.2	115.75	Impact loss due to curtailment on 8B
05/26/2010	FMO	24.7	142	8B mof
05/26/2010	PMO	24.7	115.75	Impact loss due to curtailment on 8B
06/01/2010	FFO	21.8	142	8D CT Tripped off (I/O com failure) Missed RFC 06/02/10
06/01/2010	PFO	21.8	115.75	Impact loss due to curtailment on 8D
06/18/2010	FMO	42.4	142	8C CT 06/18/10 Compressor blade inspection
06/18/2010	PMO	42.4	115.75	Impact loss due to curtailment on 8C
06/21/2010	PFO	0.4	52	Impact loss due to curtailment on 8E
06/21/2010	PFO	0.4	52	Impact loss due to curtailment on 8E
06/21/2010	PFO	0.4	52	Impact loss due to curtailment on 8E
06/21/2010	PFO	0.4	52	Impact loss due to curtailment on 8E
06/21/2010	PFO	0.4	272	Circulating Water Pump 1B Trip

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: MARTIN-UNIT 8 08 PM8 08

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
06/23/2010	FFO	7.4	142	8D CT Trip
06/23/2010	PFO	7.4	115.75	Impact loss due to curtailment on 8D
06/24/2010	FFO	9.1	142	8D CT Trip
06/24/2010	PFO	9.1	115.75	Impact loss due to curtailment on 8D
06/25/2010	FFO	24.2	142	8D CT TRIP
06/25/2010	PFO	24.2	115.75	Impact loss due to curtailment on 8D
07/07/2010	FFO	3.9	142	8A CT MISSED RFC DUE TO CT TRIP
07/07/2010	PFO	3.9	115.75	Impact loss due to curtailment on 8A
07/16/2010	FFO	199.5	142	8D BFP TRIP MOTOR SHORT CIRCUIT
07/16/2010	PFO	199.5	115.75	Impact loss due to curtailment on 8D
07/21/2010	FFO	0.3	142	8C CT EFOR due to HP FW Reg Block Valve stuck closed.
07/21/2010	PFO	0.3	115.75	Impact loss due to curtailment on 8C
07/22/2010	FPO	337.0	142	8A CTG POF
07/22/2010	PPO	335.3	115.75	Impact loss due to curtailment on 8A
07/30/2010	FFO	1.7	463	PM8 STEAM TURBINE TRIP
07/30/2010	PFO	1.7	42	Impact loss due to curtailment on 8E
07/30/2010	PFO	1.7	42	Impact loss due to curtailment on 8E
07/30/2010	PFO	1.7	42	Impact loss due to curtailment on 8E
08/21/2010	FFO	1.5	463	8X STG TRIP
09/21/2010	FMO	57.2	142	8C CT Task MOF Boroscope Inspection
09/21/2010	PMO	57.2	115.75	Impact loss due to curtailment on 8C
10/02/2010	FFO	0.9	142	8D CT Trip Due to Solar CRH Valve Tuning
10/02/2010	PFO	0.9	115.75	Impact loss due to curtailment on 8D
10/13/2010	FPO	105.2	142	8A CT Snow

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: MARTIN-UNIT 8 08 PM8 08

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
10/13/2010	PPO	105.2	115.75	Impact loss due to curtailment on 8A
10/15/2010	PFO	0.7	231	Impact loss due to curtailment on 8D
10/15/2010	PFO	0.7	97	8D CT Missed RFC Due to Inability to Control HP Drum Level
10/26/2010	FFO	5.8	142	8B CTG
10/26/2010	PFO	5.8	115.75	Impact loss due to curtailment on 8B
10/28/2010	FFO	6.1	142	8D CTG MARK 6 ISSUE / MISSED RFC & EFOR EVENT
10/28/2010	PFO	6.1	115.75	Impact loss due to curtailment on 8D
10/28/2010	FFO	11.2	142	8D CT IBH Valve failure
10/28/2010	PFO	11.2	115.75	Impact loss due to curtailment on 8D
11/04/2010	FPO	84.2	142	8D SNOW OUTAGE
11/04/2010	PPO	84.2	115.75	Impact loss due to curtailment on 8D
11/14/2010	FMO	83.4	142	8B CTG RSD
11/14/2010	PMO	83.4	115.75	Impact loss due to curtailment on 8B
11/18/2010	FFO	1.0	142	8B CT HRH BY-PASS TRIP
11/18/2010	PFO	1.0	115.75	Impact loss due to curtailment on 8B
11/19/2010	FMO	15.3	142	8B CT SNOW
11/19/2010	PMO	15.3	115.75	Impact loss due to curtailment on 8B
11/22/2010	FMO	53.1	142	8C CT SNOW
11/22/2010	PMO	53.1	115.75	Impact loss due to curtailment on 8C
11/26/2010	FMO	54.9	142	8D Off Line Water/Wash
11/26/2010	PMO	54.9	115.75	Impact loss due to curtailment on 8D
12/01/2010	FFO	0.9	142	12-01-10 C CT Liquid Fuel test Fired Shutdown
12/01/2010	PFO	0.9	115.75	Impact loss due to curtailment on 8C
12/10/2010	PFO	1.0	86	8B CT Missed RFC

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: MARTIN-UNIT 8 08 PM8 08

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
12/21/2010	FFO	36.9	142	8B CT MISSED RFC/EFOR EVENT
12/21/2010	PFO	36.9	115.75	Impact loss due to curtailment on 8B

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 04

PSR 04

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/09/2010	PFO	0.1	48.12	Impact loss due to curtailment on 4A
01/09/2010	PFO	0.1	106	4A runback due to IP feedwater block valve failed closed
01/21/2010	FMO	20.4	142	4A OFF FOR BOROSCPE BLADE INSPECTION
01/21/2010	PMO	20.4	79.25	Impact loss due to curtailment on 4A
02/05/2010	FFO	28.4	142	PSR 4A Lockout Trip on start-up
02/05/2010	PFO	28.4	79.25	Impact loss due to curtailment on 4A
03/12/2010	PPO	3.1	79.25	Impact loss due to curtailment on 4A
03/12/2010	FPO	606.3	142	4A HRSG INSPECTION
03/12/2010	PPO	1.9	79.25	Impact loss due to curtailment on 4D
03/12/2010	FPO	605.7	142	4D HRSG INSPECTION
03/12/2010	FPO	620.3	317	4 STEAM TURBINE PIPING REPLACEMENT
03/12/2010	FPO	602.9	142	4C HRSG INSPECTION
03/12/2010	FPO	602.9	142	4B HRSG INSPECTION
04/07/2010	FFO	1.6	142	4D tripped during S/U due to 2 exhaust T/Cs failing
04/07/2010	FFO	14.9	142	4D CT OFF DUE TO ST FIRE
04/07/2010	FFO	14.9	142	4B CT OFF DUE TO FIRE IN STEAM TURBINE
04/07/2010	FFO	53.4	317	PSR 4 ST Trip/Fire
04/07/2010	FFO	14.8	142	4C OFF DUE TO FIRE IN STEAM TURBINE
04/07/2010	FFO	14.8	142	4A OFF DUE TO 4 STEAM TURBINE FIRE
04/23/2010	FFO	3.0	142	4C High Vibration
04/23/2010	PFO	3.0	79.25	Impact loss due to curtailment on 4C
04/23/2010	FMO	32.3	142	4C OFF TO MAKE REPAIRS TO VIBRATION PROBE
04/23/2010	PMO	32.3	79.25	Impact loss due to curtailment on 4C
05/02/2010	FFO	0.5	142	4B RFC delayed due to boiler feed pump breaker

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 04

PSR 04

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
05/02/2010	PFO	0.5	79.25	Impact loss due to curtailment on 4B
05/22/2010	FMO	75.4	317	PSR 5 STEAM TURBINE DOWN FOR INTERCEPT VALVE R
07/02/2010	FMO	37.3	142	PSR 4C OFF FOR COMPRESSOR WASH
07/02/2010	PMO	37.3	79.25	Impact loss due to curtailment on 4C
07/24/2010	FMO	22.1	142	PSR 4D OFF FOR COMPRESSOR WASH
07/24/2010	PMO	22.1	79.25	Impact loss due to curtailment on 4D
08/08/2010	FMO	21.2	142	UNIT 4B OFF FOR OFFLINE COMPRESSOR WASH
08/08/2010	PMO	21.2	79.25	Impact loss due to curtailment on 4B
08/22/2010	FFO	5.5	142	PSR 4A Missed RFC* Exciter Issue
08/22/2010	PFO	5.5	79.25	Impact loss due to curtailment on 4A
08/25/2010	FMO	31.5	142	4C OF FOR OFFLINE COMPRESSOR WASH.
08/25/2010	PMO	31.5	79.25	Impact loss due to curtailment on 4C
08/25/2010	FMO	22.4	142	4A OFF FOR MAIN TRANSFORMER WASH
08/25/2010	PMO	22.4	79.25	Impact loss due to curtailment on 4A
09/04/2010	FMO	23.6	142	PSR 4B OFF FOR OFFLINE COMPRESSOR WASH
09/04/2010	PMO	23.6	79.25	Impact loss due to curtailment on 4B
09/18/2010	FMO	38.3	142	PSR 4D OFF FOR BLADE INSPECTION
09/18/2010	PMO	38.3	79.25	Impact loss due to curtailment on 4D
10/06/2010	FMO	52.6	142	PSR 4A OFF TO REPAIR BFP RECIRC AND HRH EXP JOIN
10/06/2010	PMO	52.6	79.25	Impact loss due to curtailment on 4A
10/13/2010	FMO	54.0	142	PSR 4C OFF FOR BLADE INSPECTIONS
10/13/2010	PMO	54.0	79.25	Impact loss due to curtailment on 4C
10/19/2010	PFO	0.1	118	4C runback from 80 Mwatts due to drum level out of cascade
11/01/2010	FFO	3.0	142	PSR CT4D Taken Off-line

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 04

PSR 04

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
11/01/2010	PFO	3.0	79.25	Impact loss due to curtailment on 4D
11/08/2010	FMO	13.7	142	PSR 4B COMPRESSOR WASH
11/08/2010	PMO	13.7	79.25	Impact loss due to curtailment on 4B
11/19/2010	FMO	20.5	142	PSR 4D off to repair LP feedwater control valve
11/19/2010	PMO	20.5	79.25	Impact loss due to curtailment on 4D
11/21/2010	FFO	3.9	142	PSR 4D TAKEN OFF DUE TO DRUM LEVEL LOSS
11/21/2010	PFO	3.9	79.25	Impact loss due to curtailment on 4D
11/22/2010	FFO	0.1	142	4C tripped due to drum level control
11/22/2010	PFO	0.1	79.25	Impact loss due to curtailment on 4C
11/29/2010	PFO	0.3	64.4	Impact loss due to curtailment on 4B
11/29/2010	PFO	0.3	112	4B CT run back to 30 MWs
12/21/2010	FMO	16.0	142	PSR 4C OFF TO REPAIR BFP COUPLING
12/21/2010	PMO	16.0	79.25	Impact loss due to curtailment on 4C
12/22/2010	FMO	23.8	142	4D Off Line Water Wash
12/22/2010	PMO	23.8	79.25	Impact loss due to curtailment on 4D

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 05 PSR 05

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
01/03/2010	FFO	21.3	142	5D tripped , Low drum level ACV-408 sticking shut
01/03/2010	PFO	21.3	78.75	Impact loss due to curtailment on 5D
01/07/2010	FFO	14.1	142	5C CT Tripped due to PM1 position diff error when unit xfer mc
01/07/2010	PFO	14.1	78.75	Impact loss due to curtailment on 5C
01/09/2010	FFO	2.7	315	5ST tripped while performing Pushbutton Simulated Trip Test
01/17/2010	FFO	0.1	142	5A Generator breaker opened on loss of steam path
01/17/2010	PFO	0.1	78.75	Impact loss due to curtailment on 5A
01/18/2010	FFO	6.3	142	5A IBH not functioning during startup
01/18/2010	PFO	6.3	78.75	Impact loss due to curtailment on 5A
01/19/2010	FFO	0.6	142	5B tripped during S/U Permissive Issue
01/19/2010	PFO	0.6	78.75	Impact loss due to curtailment on 5B
01/19/2010	FFO	0.8	315	5ST late RFC, RSV1 stuck
01/22/2010	FMO	30.5	142	5B OFF FOR R0 BLADE INSPECITON
01/22/2010	PMO	30.5	78.75	Impact loss due to curtailment on 5B
01/24/2010	FFO	6.0	142	5B BFP breaker cause startup failure
01/24/2010	PFO	6.0	78.75	Impact loss due to curtailment on 5B
01/27/2010	FMO	51.3	142	5D OFF FOR COMPRESSOR WASH
01/27/2010	PMO	51.3	78.75	Impact loss due to curtailment on 5D
01/29/2010	FMO	25.7	142	5B OFF FOR COMPRESSOR WASH
01/29/2010	PMO	25.7	78.75	Impact loss due to curtailment on 5B
02/02/2010	FFO	0.6	315	PSR 5 Missed RFC Due to "DX" alarm on panelmate
02/09/2010	FFO	3.0	142	5B low flow BFP and loss of steam path on S/U
02/09/2010	PFO	3.0	78.75	Impact loss due to curtailment on 5B
02/10/2010	FFO	1.8	142	5D 41AC-1 to 41AC-2 Transfer Failure

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 05

PSR 05

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
02/10/2010	PFO	1.8	78.75	Impact loss due to curtailment on 5D
02/11/2010	FMO	23.6	142	5D off for troubleshooting 89SS
02/11/2010	PMO	23.6	78.75	Impact loss due to curtailment on 5D
02/12/2010	FFO	0.1	142	5C tripped. Fuse pulled on wrong unit
02/12/2010	PFO	0.1	78.75	Impact loss due to curtailment on 5C
02/17/2010	FFO	4.7	142	5C generator breaker opened on reverse power
02/17/2010	PFO	4.7	78.75	Impact loss due to curtailment on 5C
02/17/2010	FFO	0.9	142	5C tripped during startup on blocked steam path
02/17/2010	PFO	0.9	78.75	Impact loss due to curtailment on 5C
02/22/2010	FMO	33.8	315	5ST OFF FOR PROTECTION AND CONTROL WORK
02/22/2010	FMO	29.2	142	5A OFF FOR PROTECTION AND CONTROL WORK
02/22/2010	FMO	29.8	142	5B OFF TO WORK ON GAS ORIFICE
02/24/2010	FFO	0.9	142	5B CT HP Steam Path Blocked
02/24/2010	FFO	2.7	142	PSR 5D Compressor Bleed Valve CLOSED - Missed RFC
02/24/2010	PFO	2.7	78.75	Impact loss due to curtailment on 5D
02/24/2010	FFO	2.1	142	PSR 5C LCI Issues - Missed RFC
02/24/2010	PFO	2.1	78.75	Impact loss due to curtailment on 5C
03/08/2010	FMO	23.4	142	Unit 5C off for LCI troubleshooting
03/08/2010	PMO	23.4	78.75	Impact loss due to curtailment on 5C
03/10/2010	FFO	0.2	142	5C missed RFC on 3/10/10
03/10/2010	PFO	0.2	78.75	Impact loss due to curtailment on 5C
03/26/2010	FMO	30.0	142	5D TO REPAIR INLET BLEED VALVE
03/26/2010	PMO	30.0	78.75	Impact loss due to curtailment on 5D
04/15/2010	FMO	17.3	142	5A OFF TO REPAIR EXPANSION JOINT

(1) FFO - FULL FORCED OUTAGE
PPO - PARTIAL PLANNED OUTAGE
PMO - PARTIAL MAINTENANCE OUTAGE
PO - PLANNED OUTAGE
PFO - PARTIAL FORCED OUTAGE
FMO - FULL MAINTENANCE OUTAGE

FILED:
SUSPENDED:
EFFECTIVE:
DOCKET NO.:
ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 05

PSR 05

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
04/15/2010	PMO	17.3	78.75	Impact loss due to curtailment on 5A
04/16/2010	FPO	602.8	142	5B DOWN FOR MAJOR OVERHAUL
04/16/2010	PPO	602.8	78.75	Impact loss due to curtailment on 5B
04/23/2010	FPO	213.2	142	5A COMBUSTOR INSPECTION OUTAGE
04/23/2010	PPO	213.2	78.75	Impact loss due to curtailment on 5A
04/27/2010	FMO	49.3	142	PSR 5D OFF TO MAKE HRSG INTERNAL LINER REPAIRS
04/27/2010	FMO	49.3	142	PSR 5C OFF FOR OFFLINE COMPRESSOR WASH
04/27/2010	PMO	49.3	78.75	Impact loss due to curtailment on 5D
04/27/2010	PMO	49.3	78.75	Impact loss due to curtailment on 5C
05/02/2010	FPO	0.0	142	5A COMBUSTOR INSPECTION OUTAGE
05/02/2010	PPO	0.0	78.75	Impact loss due to curtailment on 5A
05/12/2010	FPO	0.0	142	5B MAJOR OVERHAUL
05/12/2010	PPO	0.0	78.75	Impact loss due to curtailment on 5B
05/22/2010	FMO	4.6	142	PSR 5B OFF TO INSPECT BFP
05/22/2010	PMO	4.6	78.75	Impact loss due to curtailment on 5B
05/22/2010	FFO	6.8	142	5B CT BFP Coupling repairs
05/22/2010	PFO	6.8	78.75	Impact loss due to curtailment on 5B
05/25/2010	FFO	0.9	142	5D Late for RFC due to BFP trip
05/25/2010	PFO	0.9	78.75	Impact loss due to curtailment on 5D
05/25/2010	FMO	44.0	142	PSR 5A OFF FOR BALANCE SHOT
05/25/2010	PMO	44.0	78.75	Impact loss due to curtailment on 5A
06/13/2010	FMO	69.6	142	5D OUTAGE FOR SUPERHEAT SPRAY BLOCK VALVE WO
06/13/2010	PMO	69.6	78.75	Impact loss due to curtailment on 5D
06/13/2010	FFO	6.7	142	5B BFP Inboard Motor Bearing/Coupling

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA
 COMPANY: FLORIDA POWER AND LIGHT
 From: Jan-2010 To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 05 PSR 05

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
06/13/2010	PFO	6.7	78.75	Impact loss due to curtailment on 5B
06/25/2010	FMO	48.9	142	PSR 5B OFF FOR HRH EXP JOINT REPAIR
06/25/2010	PMO	48.9	78.75	Impact loss due to curtailment on 5B
06/27/2010	FMO	21.6	142	5B OUTAGE EXTENSION
06/27/2010	PMO	21.6	78.75	Impact loss due to curtailment on 5B
06/30/2010	FMO	18.0	142	Unit 5D off for boroscope inspection
06/30/2010	PMO	18.0	78.75	Impact loss due to curtailment on 5D
07/05/2010	FMO	21.3	142	PSR 5D OFF FOR BOROSCOPE INSPECTION
07/05/2010	PMO	21.3	78.75	Impact loss due to curtailment on 5D
07/10/2010	FFO	12.4	142	5D missed RFC due to the inside G-switch not fully closing
07/10/2010	PFO	12.4	78.75	Impact loss due to curtailment on 5D
07/17/2010	FMO	17.0	142	5C OFF FOR OFFLINE COMPRESSOR WASH
07/17/2010	PMO	17.0	78.75	Impact loss due to curtailment on 5C
07/17/2010	FMO	24.2	142	UNIT OFF FOR REPAIR OF GENERATOR DISCONNECT
07/17/2010	PMO	24.2	78.75	Impact loss due to curtailment on 5D
07/18/2010	FPO	615.6	142	PSR 5D MAJOR OVERHAUL
07/18/2010	PPO	615.6	78.75	Impact loss due to curtailment on 5D
07/29/2010	FFO	3.1	142	4C late RFC partly due to the fuel gas aux stop valve solenoid
07/29/2010	PFO	3.1	78.75	Impact loss due to curtailment on 5C
08/03/2010	FFO	5.0	142	5C CT Cycled Off due to BFP Coupling Issues.
08/03/2010	PFO	5.0	78.75	Impact loss due to curtailment on 5C
08/13/2010	FPO	0.6	142	5D CYCLE FOR AFTER O/H TESTING
08/13/2010	PPO	0.6	78.75	Impact loss due to curtailment on 5D
08/29/2010	FMO	52.7	142	PSR 5D OFF FOR VIBRATION TESTING

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 05

PSR 05

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
08/29/2010	PMO	52.7	78.75	Impact loss due to curtailment on 5D
09/05/2010	FMO	18.5	142	PSR 5B OFF FOR OFFLINE COMPRESSOR WASH
09/05/2010	PMO	18.5	78.75	Impact loss due to curtailment on 5B
09/14/2010	FMO	48.1	142	PSR 5C OFF FOR BLAD INSPECTION
09/14/2010	PMO	48.1	78.75	Impact loss due to curtailment on 5C
09/16/2010	FMO	31.3	142	PSR 5C OFF FOR BLADE INSPECTION
09/16/2010	PMO	31.3	78.75	Impact loss due to curtailment on 5C
09/21/2010	FFO	3.8	142	5B missed RFC on 9/21/10 due to failed ignitors
09/21/2010	PFO	3.8	78.75	Impact loss due to curtailment on 5B
09/25/2010	FFO	0.5	142	5D CT Trip on high HP drum level
09/25/2010	PFO	0.5	78.75	Impact loss due to curtailment on 5D
09/28/2010	FMO	24.5	142	PSR 5A OFF FOR COMPRESSOR WASH
09/28/2010	PMO	24.5	78.75	Impact loss due to curtailment on 5A
09/29/2010	FMO	23.9	142	PSR 5D OFF FOR OFFLINE COMPRESSOR WASH
09/29/2010	PMO	23.9	78.75	Impact loss due to curtailment on 5D
10/01/2010	FFO	2.0	142	5D CT high HP drum level unindicated
10/01/2010	PFO	2.0	78.75	Impact loss due to curtailment on 5D
10/03/2010	FMO	58.8	142	PSR 5A OFF TO REPAIR EXHAUST FRAME SEAL
10/03/2010	PMO	58.8	78.75	Impact loss due to curtailment on 5A
10/09/2010	FMO	49.7	142	PSR 5B OFF FOR HRH EXP JOINT REPAIR
10/09/2010	PMO	49.7	78.75	Impact loss due to curtailment on 5B
10/29/2010	FMO	50.8	142	PSR 5C off to repair HP attemperator spray header
10/29/2010	PMO	50.8	78.75	Impact loss due to curtailment on 5C
10/31/2010	FMO	22.5	142	PSR 5c off to repair leaking HP attemperator spray header

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ACTUAL PERFORMANCE DATA

COMPANY: FLORIDA POWER AND LIGHT

From: Jan-2010

To: Dec-2010

PLANT / UNIT: SANFORD 4 & 5 CC 05

PSR 05

DATE	OUTAGE TYPE(1)	HOURS	(MW) AFFECTED	DESCRIPTION
10/31/2010	PMO	22.5	78.75	Impact loss due to curtailment on 5C
11/03/2010	FMO	21.3	142	PSR 5A OFF TO REPAIR DRAIN VALVE
11/03/2010	PMO	21.3	78.75	Impact loss due to curtailment on 5A
11/06/2010	FFO	0.7	315	5ST stuck Intercept valve
11/06/2010	FFO	1.6	315	5ST generator breaker relay failure
11/20/2010	FFO	0.1	315	5ST LATE FOR RFC, Field Breaker
11/25/2010	FMO	20.5	142	PSR 5B OFF FOR OFFLINE COMPRESSOR WASH
11/25/2010	PMO	20.5	78.75	Impact loss due to curtailment on 5B
11/26/2010	FMO	22.0	142	PSR 5D OFF FOR COMPRESSOR WASH
11/26/2010	PMO	22.0	78.75	Impact loss due to curtailment on 5D
11/30/2010	FMO	52.3	142	PSR 5A OFF FOR R0 INSPECTION
11/30/2010	PMO	52.3	78.75	Impact loss due to curtailment on 5A
12/16/2010	FMO	106.9	142	PSR 5C off to replace superheat attemperator header
12/16/2010	PMO	106.9	78.75	Impact loss due to curtailment on 5C
12/29/2010	FMO	42.0	142	5B LP Evap Tube Leak
12/29/2010	PMO	42.0	78.75	Impact loss due to curtailment on 5B

(1) FFO - FULL FORCED OUTAGE
 PPO - PARTIAL PLANNED OUTAGE
 PMO - PARTIAL MAINTENANCE OUTAGE
 PO - PLANNED OUTAGE
 PFO - PARTIAL FORCED OUTAGE
 FMO - FULL MAINTENANCE OUTAGE

FILED:
 SUSPENDED:
 EFFECTIVE:
 DOCKET NO.:
 ORDER NO.:

ISSUED BY: FLORIDA POWER & LIGHT CO.

GPIF Units
Actual Performance Data (ACRONYMS) for 2010

ACRONYMS	DESCRIPTION
"R"	Mark VI "R" Processor
1A2	Unit 1 Pump A2
1B	Unit 1 Pump B
2B1	Unit 2 Pump B1
2A	Unit 2 Combustion Turbine (sub unit A)
2A CT - 2A 230	Combustion Turbine (sub unit A) - 2A Collector Bus
2A HDP	2 Alpha High Differential Pressure
2B	Unit 2 Combustion Turbine (sub unit B)
2B CT - 2A 230	Combustion Turbine (sub unit B) - 2A Collector Bus
2B MSR	2 Bravo Moisture Separator Reheater
2C	Unit 2 Combustion Turbine (sub unit C)
2C CT - 2A 230	Combustion Turbine (sub unit C) - 2A Collector Bus
2D	Unit 2 Combustion Turbine (sub unit D)
2E	Unit 2 Combustion Turbine (sub unit E)
2F	Unit 2 Combustion Turbine (sub unit F)
3 CTB	Unit 3 Combustion Turbine (sub unit B)
3A	Unit 3 Combustion Turbine (sub unit A)
3B	Unit 3 Combustion Turbine (sub unit B)
3C	Unit 3 Combustion Turbine (sub unit C)
3D	Unit 3 Combustion Turbine (sub unit D)
3ST	Unit 3 Steam Turbine
41AC-1	Breaker 1 for Power Supply to Exciter
41AC-2	Breaker 2 for Power Supply to Exciter
4A	Unit 4 Combustion Turbine (sub unit A)
4A SGFP	4A Steam Generator Feedwater Pump
4B	Unit 4 Combustion Turbine (sub unit B)
4C	Unit 4 Combustion Turbine (sub unit C)
4D	Unit 4 Combustion Turbine (sub unit D)
4KV	4 Thousand Volts
5A	Unit 5 Combustion Turbine (sub unit A)
5B	Unit 5 Combustion Turbine (sub unit B)
5C	Unit 5 Combustion Turbine (sub unit C)
5D	Unit 5 Combustion Turbine (sub unit D)
5ST	Unit 5 Steam Turbine
89SS	Static Start Switch
8A	Unit 8 Combustion Turbine (sub unit A)
8B	Unit 8 Combustion Turbine (sub unit B)
8C	Unit 8 Combustion Turbine (sub unit C)
8D	Unit 8 Combustion Turbine (sub unit D)
8X	Unit 8 Steam Turbine
ACV-3	Automatic Control Valve # 3
ACV-408	Air Control Valve Tag 408
AUX	Auxiliary
BFP	Boiler Feed Pump
CEA	Control Element Assembly
CEA 38	Control Element Assembly Number 38
CEA 65	Control Element Assembly Number 65
com	Communication
comm	Communication
CRH	Cold Reheat
CT	Combustion Turbine
CT C	Combustion Turbine (sub unit C)
CTG SRV	Speed Ratio Valve on Combustion Turbine (gas system)
CV-4-1510	Control Valve Number 4-1510

GPIF Units
Actual Performance Data (ACRONYMS) for 2010

ACRONYMS	DESCRIPTION
CW	Circulating Water
CWP	Circulating Water Pump
DFS	Debris Filtration System
diff	Differential
DX	DeXcitation
EFOR	Equivalent Forced Outage Rate
EHC	Hydraulic
EXP	Expansion
Fa	Failed
FGT	Florida Gas Transmission
FME	Foreign Material Exclusion
FSNL	Full Speed No Load
GE	General Electric
GSU	Generator Step Up
Haz	Hazardous
HI	High
HMI	Human Machine Interface
HP	High Pressure
HRH	Hot Reheat
HRSG	Heat Recovery Steam Generator
I/O	Input / Output
IBH	Inlet Bleed Heat Valve
ID	Induced Draft
Instr.	Instrumentation
IP	Intermediate Pressure
LCI	Load Commutating Inverter
LP	Low Pressure
MFIV	Main Feed Isolation Valve
MG	Motor Generator
MOF	Maintenance Outage Factor
mof	maintenance outage factor
MOF/AA	Maintenance Outage Factor / Atomizing Air
MSR	Moisture Separator Reheater
MSSV	Main Steam Safety Valve
MW	Megawatt
NO	No
O/H	Overhaul
POF	Planned Outage Factor
PEL	Planned Energy Loss
PFM	Ft. Myers
PM1	Gas Valve Number 1
PM3	Gas Valve Number 3
PM320102662	Manatee Unit 3 GADS #20102662
PMG	Martin
PMT	Manatee
Pmp	Pump
PSL	St Lucie
PSR	Sanford
PT	Potential transformer
PWR	Power
R	Repair
R0	Row 0 blades on steam turbine
R1	Row 1 blades on steam turbine
RFC	Ready For Control

**GPIF Units
Actual Performance Data (ACRONYMS) for 2010**

ACRONYMS	DESCRIPTION
RFO	Refueling Outage
RPS	Reactor Protection System
RSD	Reserve Shutdown
RSV	Reheat Stop Valve
RSV1	Reheat Stop Valve Number 1
S/U	Startup
SGG	Main Steam - High Pressure
SGJ-ACV-10	System Designator Air Control Valve
SL1-23	St Lucie Unit 1 cycle 23 refueling outage
SNO	Short Notice Outage
SNOW	Short Notice Outage
STARS	Strategic Anti Rotation Stall Surge testing
ST	Steam Turbine
ST1	Steam Turbine Number 1
ST2	Steam Turbine Number 2
STG	Steam Generator
STM 1	Steam Turbine Number 1
STM 2	Steam Turbine Number 2
T/Cs	Thermal/Couples
U1	Unit 1
U2	Unit 2
UEL	Unplanned Energy Loss
Vi	Roman Numeral 6
WO	Work
WW	Water wash