

98

FPUC's Response to OPC's Fifth
Production of Documents No. 17

(No. 17 has an attachment)

DOCUMENT REQUESTS

17. On page 26 of the SPP in the last paragraph you state that “post-storm data for Hurricane Michael found that hardened structures performed significantly better than non-hardened structures.” Please provide copies of all documents that discuss, describe, or analyze this post- storm data and the associated findings described here.

Company Response:

Please see Exhibit “PMC-50” which is a summary document for the forensic inspections that took place during Hurricane Michael. This shows the results of a forensics inspection that included 88 poles that were broken during Hurricane Michael. The results indicated of the random sample of 88 broken poles, only 2 (2.27%) were considered storm hardened poles.