

Review of Electric Utility Hurricane Preparedness and Restoration Actions

Docket No : 20170215-EU

Name : James Spencer

Electric Utility Provider : FPL

Zip Code : 34239

Category : Power restoration time

Comments : One of the big problems regarding the storm was that FPL should have trimmed many trees before the storm. I previously called FPL to trim the trees and they said they had to be leaning on the lines. This should not happen. If more preventive measures were taken we wouldn't have had so much waste of time.