State of Florida



ł



Public Service Commission

CAPITAL CIRCLE OFFICE CENTER • 2540 SHUMARD OAK BOULEVARD TALLAHASSEE, FLORIDA 32399-0850

-M-E-M-O-R-A-N-D-U-M-

DATE:	March 09, 2007
то:	Ann Cole, Chief of Records, Division of the Commission Clerk & Administrative Services Cheryl Johnson, Regulatory Analyst IV, Division of Economic Regulation
FROM:	Cheryl Johnson, Regulatory Analyst IV, Division of Economic Regulation
RE:	Docket No. 050595-WS; Application for certificates to provide water and wastewater service in Polk County by Four Points Utility Corporation

Please include the attached documents in docket file 050595-WS.

RECEIVED-PPSC 07 MAR -9 PH 3: 40 09 MINISSION

DOCUMENT NUMBER-CATE 02164 MAR-95 FPSC-COMMISSION CLERK

March 9, 2007

James Brett Pres/Island Club West Homeowners Assoc 7320 Ober Lane Chagrin Falls, OH 44023

Re: Four Points Utility Corporation

Dear Mr. Brett:

I am providing you with additional information to address your questions concerning the integrity of the fire hydrant system at the Island Club West Development (the "Development") and as-built drawings for the utility system serving the Development.

FOUR POINTS UTILITY CORPORATI

With respect to the fire hydrant system, all of the fire hydrants at the Development were tested by a certified fire inspector on March 8, 2007 and are operating properly. A copy of the inspector's report is attached.

With respect to as-built drawings of the utility system, I understand that you would like to see diagrams of the utility system that are more detailed than that provided to you pursuant the Settlement Agreement. To address that issue, detailed blue print diagrams of the utility system have been given to Mike Flynn, and a copy of those drawings will be sent by over night mail to your present location. Our utility manager and other personnel are more than willing to meet with you to conduct a walk-through of the system using the blue print as a guide. Please let me know when you would be able to participate in that walk-through.

Finally, if you have any questions concerning any of the other information that was provided to you as part of the Settlement Agreement, including without limitation, my personal financial statement, please do not hesitate to give me a call.

I trust this information is helpful. Of course if you have any additional questions, please do not hesitate to contact me.

Sincerely,

David Meadows)

David Meadows President

Encl. cc: Pat

email david@assuredrecord.com

333 0917

Patti Daniel Cheryl Johnson

REV. 3/03 **Report of Inspection, Testing & Maintenance** of Water Based Fire Protection Systems

tere Intechou Inspecting Firm (Contractor) Inspector Inspection Contract# Date of This Inspection: Completed by: Island Club West Name of Property: 4000 andmine Street Address: Aven zor City: State Zip: Fax: 863-547-1729 Phone: C-1-407-947 Contact Person Name: eand Authority to Approve Work? N/A Position: Y N Ality Cop. / Island Club West Property Owner: MA-IA-Address: State: Zip: City: 863--0130 X1 Fax: 863-547-172 Phone: 66 er 7-947-9845 osition: Responsible Party Name: Name of Supervisory Alarm Compa Phone is bectiener Inspector's Name: Date of Last Inspection: **General Information Section** Cleaned - Greased - Flowed - EtERCISEd & Nomboard N/A Ν Prior inspection reports, logs and test data are available for review: Plans of systems on site for review? Modifications made to systems reviewed and documented? Reports of sprinkler activation reviewed and documented? Copy of NFPA #25 on file? 5. Weekly logs of inspections required by NFPA #25 on file? Owner/Owner's Representative verifies that the occupancy and hazard 7. are the same as reported on last inspection? All deficiencies reported at last inspection corrected? 8. 9. Material Safety Data Sheets reviewed and hazards to inspector removed? (Use separate sheet for additional information as may be needed. All "NO" answers to be explained.) AFSA Form 104A should be completed by the Inspecting Firm/Contractor and provided to the Owner. COMMENTS: # 6 Hydrant underground arts turned off Cleaned out pit and but Hydrant in service. The owner and/or designated representative acknowledges the responsibility of the operating condition of the component parts at the time of this inspection. It is agreed that the inspection service provided by the contractor as prescribed herein is limited to performing a visual inspection and/or routine testing, and any investigation or unscheduled testing, modification, maintenance, repair, etc., of the component parts is not included as part of the inspection work performed. It is further understood that all information contained herein is provided to the best of the knowledge of the party providing such information OWNER/DESIGNATED REPRESENTATIVE

INSPECTOR'S SIGNATURE:



ATTENTION: The American Fire Sprinkler Association (AFSA) is a non-profit trade association. AFSA does not guarantee, certify, underwrite, or pre-approve any services provided by those who use forms produced by AFSA. Our logo is only an advertisement. Warnings, disclaimers, and update information exist on the back of the form. It is your responsibility to read these statements.

(AFSA Form 103A) Page 1 of 1

DATE: 2

COMPANY NAME: FOUR Dirats Utility Cop. OF FIRE HYDRANTS 3-8-2007

COX FIRE PROTECTION, INC. 2001 N. 36TH STREET TAMPA, FL 33605 PHONE # 247-4777 FAX # 247-5100