## Page 1

From: Robert Derryberry < robert@kwru.com>

To: Chris@kwru.com

Date: 12/8/2017 12:09:32 PM
Subject: Fwd: TRUCK INSPECTION
Attachments: INSPECTION 2011 F-450.pdf

----- Original Message -----

From: Tim Heinze <tim.heinze@helfmanford.com>

To: robert@kwru.com

Date: December 7, 2017 at 1:54 PM Subject: TRUCK INSPECTION

2011 F-450 INSPECTION ATTACHED

THANK YOU

Tim Heinze

Helfman Ford

Tim.heinze@helfmanford.com

W- 281 274 7223

Cell- 713 240 4325

FAX-281 274 7248

## Used Vehicle Inspection Checklist(UVIC)

Back To Weba Menu	
ESP UVIC inspection must be done no more than 90 days and 1,000 miles or kilometers prior to vehicle sale	
P&A Code:* RO Number: 174548 Vehicle identification Number(VIN):	* 1FD0X4GT9BEB16026
STARS ID: Technician Name: BEN WARD	5.4 Min 1
I. INITIAL INSPECTION	IV. UNDER VEHICLE
ENGINE TYPE ® Diesel Engine Gas Engine HOUR METER READING	Pass Fail
ODOMETER READING (Road Test must be a minimum of 3 miles)	TRANSMISSION OR TRANSFER CASE - no leaks,damage, or wear.
Before road test:* 170894 After road test:* 170900 miles	HALF SHAFT AND CV JOINTS OR DRIVE SHAFT AND U-JOINTS - no leaks, damage, or wear.
Optional Images(Max size 2 MB)	
VIN Decal Image: Browse Odometer Image: Browse	O BRAKE SYSTEM - no leaks, damage, or wear.
Underside of the engine:  Top side of engine:  Browse  Browse	
Yes O No Does this vehicle meet the eligibility requirements per the pricebook?  USA Pricebook Canadian Pricebook	STEERING SYSTEM AND LINKAGE - no leaks, damage, or wear.
Yes No	SUSPENSION SYSTEM - no leaks, damage, or wear.
Has your dealership performed the scheduled maintenance interval based on the current mileage?	AXLES - no leaks, damage, or wear.
Are there any noticeable(non-factory) modifications on this vehicle?*  Comments*	Convertors.  EXHAUST SYSTEM - no leaks,damage. All components in place including convertors.  EXHAUST SYSTEM - no leaks,damage. All components in place including convertors.
○ Chain ○ Belt Does the vehicle have an engine timing chain or timing belt?	FRAME/UNDERCARRIAGE - examine for damage or wear.
II. EXTERIOR OF VEHICLE	V. VEHICLE INTERIOR CHECKS & ROAD TEST
Yes No	Pass Fail
Are all exterior lights operational?	Scan Tool - PCM Quick Test & Network Test - scan all electronic modules for © fault codes Print the IDS Log Viewer and maintain with the UVIC RO documentation.
○ ③ Is there any exterior vehicle damage?	SmGINE PERFORMANCE - no problems (e.g., starting, poor performance, smoking, etc.).
○ ○ Is the vehicle equipped with a snowplow or snowplow mounting frame?	TRANSMISSION PERFORMANCE - shifts smoothly with no unusual noises.
III. UNDER HOOD	BRAKE SYSTEM - vehicle brakes without any issues (e.g., drift, pull, noise, vibration, etc.). Parking brake functions properly.
Pass Fail N/A	STEERING - steering is tight and responsive with no unusual characteristics or noises.
ENGINE **- examine for leaks, damage, and abnormal noises. Oil condition and oil level are correct with no signs of sludge.	SUSPENSION - vehicle exhibits no sign of harshness or loose suspension.
AIR INLET SYSTEM - air filter, filter box, and inlet tube are clean.	O A/C AND HEATER - operating properly with no unusual noises.
EMISSION SYSTEM - visually inspect to ensure all components are intact with no modifications.	O O VIBRATION/NOISE - No unusual vibration or noise.
RADIATOR/COOLING SYSTEM - no leaks,damage, or wear to the water pump, overflow bottle, hoses, fan. Coolant is in good condition and full.	INSTRUMENT WARNING LIGHTS - no warning lights illuminated while operating the vehicle.
O O Condition and correct level.	INTERIOR EQUIPMENT - Items are working:
POWER STEERING - pump, gear, and hoses have no leaks or damage.	Pass Fail N/A Pass Fail N/A
ELECTRICAL - cables are corrosion-free, starter and alternator are operational, and wiring harnesses are intact and without corrosion or modifications.	⑥    ⑥
AIR CONDITIONING - compressor, clutch, and hoses have no leaks, damage, or unusual noises.	○ Clights ⊕ O Horn ⊕ O Windows/Locks ○ ○ ⑥ Navigation/Video System
BRAKE SYSTEM - no leaks or damage. Fluid is at proper level and clean.	● ○ Mirrors ○ ○ ● Moonroof  ● ○ Clock/Audio System ○ ○ Other Switches/Controls
○ ○ ELECTRIC OR HYBRID VEHICLE COMPONENTS - no damage or corrosion.	○ ○ ● Heated Backglass
Maintain a copy of the interim repair order, indicating repairs performed on the vehicle prior to the sale.  Verified through OASIS that NVLW or specified component parts are not voided, in whole or in part, or is not a branded vehicle (Ford, Lincoln, Mercury vehicles) as vehicle would be ineligible for ESP.	*Future failures related to a modification are subject to denial.  ** Engine, transmission, and drive axle must be the same original equipment specified for the vehicle and meet all applicable Federal Regulations to be eligible for ESP coverage.
Comments LEFT REAR TAIL LIGHT OUT	^ ···
Customer Name	
Customer Name Submit	Reset